

**Landmark Implement Inc.**

P.O. Box 11  
73049 L Road  
Holdrege, NE 68949  
Phone: 308-995-6511  
Fax: 308-995-5475  
www.landmarkimp.com  
Holdrege@landmarkimp.com

**JOHN DEERE**

Invoice To Account No: 1004

Deliver To:

**SERVICE INVOICE**

Bus Phone: Prv Phone:	Invoice Number: 10545501 Invoice Date: 9/13/2018 Location: 01 Work Order Number: 277058 Payment Type: Account	Page: 1 of 2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	1574	1H0S680SPD0765105		

**PIP17HX527A Warranty****COMPLAINT:**

01 17HX527A - DF3 CHAFFER FRAME IMPROVEMENT - MANDATORY

**CAUSE:**

17HX527A - DF3 CHAFFER FRAME IMPROVEMENT - MANDATORY

**CORRECTION:**

17HX527A - DF3 CHAFFER FRAME IMPROVEMENT - MANDATORY

**COMPLETED:**

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
MPH20178	ENGINE KIT	1.00	121.20	121.20	\$121.20	N
Labor: \$838.25		Parts: \$121.20	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$959.45	

**PIP17HX527B Warranty****COMPLAINT:**

02 17HX527B - DF3 CHAFFER FRAME IMPROVEMENT - FIX AS FAIL

DTAC CASE 255680

**CAUSE:**

FOUND CRACKS OUTSIDE OF THE DESIGNATED AREA.

**CORRECTION:**


PERFORMED PIP 17HX527B PER INSTRUCTIONS.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
MPH20140	CHAFFER SIDE RAIL KIT	1.00	1,356.51	1,356.51	\$1,356.51	N
Labor: \$1,197.50		Parts: \$1,356.51	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2,554.01	

**PIP17HX527D Warranty****COMPLAINT:**

04 17HX527D - DF3 CHAFFER FRAME IMPROVEMENT - FIX AS FAIL

CONTINUED ON NEXT PAGE-&gt;



Landmark Implement Inc.  
P.O. Box 11  
73049 L Road  
Holdrege, NE 68949  
Phone: 308-995-6511  
Fax: 308-995-5475  
www.landmarkimp.com  
Holdrege@landmarkimp.com



JOHN DEERE

Invoice To Account No: 1004

Deliver To:

## SERVICE INVOICE

Bus Phone:		Invoice Number:	10545501
Prv Phone:		Invoice Date:	9/13/2018
		Location:	01
		Work Order Number:	277058
		Payment Type:	Account
		Page:	2 of 2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S680	1574	1H0S680SPD0765105		

PIP17HX527D Warranty

CAUSE:

WHILE DISASSEMBLING CHAFFER FOUND THE FRONT DEFLECTOR AND THE CROSS SUPPORT WERE CRACKED.

CORRECTION:

REPLACED CHANNEL AND DEFLECTOR.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH164851	CHANNEL	1.00	368.17	368.17	\$368.17	N
AXE17210	DEFLECTOR	1.00	846.69	846.69	\$846.69	N

Labor: \$59.88	Parts: \$1,214.86	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,274.74
----------------	-------------------	--------------	--------------	-----------------------

Customer PO No:	
Tax Exempt No:	ON FILE
Advisor:	JOEL KONZACK

Labor:	\$2,095.63
Parts:	\$2,692.57
OL&M:	\$0.00
Misc:	\$0.00
Sales Tax:	\$0.00
Grand Total:	\$4,788.20

\*\*\* DOCUMENT COPY \*\*\*

### TERMS AND CONDITIONS

Approved charges are due by the 10th of the month following purchase, I agree to pay a monthly periodic FINANCE CHARGE at the rate of 1.33% which is an ANNUAL PERCENTAGE CHARGE OF 16% on the unpaid balance. The purchaser agrees to pay reasonable attorney fees if collection efforts are required.

Received by: ..... Date: .....