DATE	Driver	OIL CHANGE	OPERATED			2016 Western Star Truck Tractor (5KJJAXDV7GLHL8831) OPERATION COST													REPAIR COST				OPERATING COST											
						FUEL			Exhaust Fluid			OIL		ANTIFREEZE																				
			ACTUAL MILES	NEWODE	MILES	GAL	MILE PER GAL	Cost	GAL	MILE PER GAL	Cost $2.95 Gal	Total Cost	QTS	COST	GAL	COST	GREASE	TIRES, TUBES	SPECIAL SERVICE	LABOR	PARTS	TOTAL REPAIR COST	DEPREC	TOTAL COST ALL ITEMS	COST PER MILE									
12/18/2018			**354329.0**		**0.0**														**$68,000.00**							**Purchased Truck**								
		25000.0		**diferenc**	**89.3**																													
12/18/2018		24970.0	354359.0		30.0	82.844		$254.25	10.0		$21.90	$219.00					$2.00																	
12/20/2018		24692.0	354637.0		278.0	58.978	4.714	$181.00																										
1/2/2019		24692.0	354637.0		0.0	0.000	0.000	$0.00													$197.68	$197.68				Floor Mats								
1/7/2019		24390.1	354938.9		301.9	56.047	5.387	$172.01																										
1/9/2019		24354.0	354975.0		36.1	0.000	0.000	$0.00													$179.52	$179.52				Air Filter								
1/23/2019		24015.0	355314.0		339.0	67.480	5.024	$207.10																										
2/13/2019		23790.0	355539.0		225.0	49.614	4.535	$146.81																										
3/18/2019		23511.0	355818.0		279.0	50.256	5.552	$152.23	1.0		$2.19	$2.19																						
3/20/2019		23319.4	356009.6		191.6	38.259	5.008	$115.89																										
3/26/2019		22915.3	356413.7		404.1	85.467	4.728	$258.88																										
3/27/2019		22670.1	356658.9		245.2	41.462	5.914	$125.59	6.5		$14.24	$92.53	8.00	$30.16																				
4/1/2019		22396.0	356933.0		274.1	71.812	3.817	$217.52					4	$11.00												Added gallon of antifreeze and gallon of water.								
4/3/2019		21921.0	357408.0		475.0	78.307	6.066	$237.19																		Windshield cracked								
4/4/2019		21596.0	357733.0		325.0	67.939	4.784	$205.79																										
4/8/2019		21166.0	358163.0		430.0	85.256	5.044	$258.24	10.0		$21.90	$219.00																						
4/9/2019		20948.0	358381.0		218.0	42.242	5.161	$127.95																										
4/16/2019		20616.0	358713.0		332.0	71.354	4.653	$216.13																										
4/17/2019		20236.0	359093.0		380.0	90.553	4.196	$274.29																										
4/18/2019		19874.0	359455.0		362.0	76.691	4.720	$232.30	5.0		$10.95	$54.75																						
4/19/2019		19458.0	359871.0		416.0	76.672	5.426	$232.24																										
4/26/2019		19120.0	360209.0		338.0	82.414	4.101	$249.63												$966.50	$614.55	$1,581.05												
4/29/2019		18964.0	360365.0		156.0	24.771	6.298	$75.03	5.0		$10.95	$54.75									$35.72	$35.72				5th Wheel Lube Disk								
5/6/2019		18647.2	360681.8		316.8	67.122	4.720	$206.00																		Back Glass broken at rock pit.								
5/8/2019		18383.5	360945.5		263.7	56.697	4.651	$174.00	7.0		$15.33	$107.31																						
5/9/2019		18031.5	361297.5		352.0	79.953	4.403	$245.38																										
5/10/2019		17654.0	361675.0		377.5	81.122	4.653	$248.96																										
5/20/2019		17229.0	362100.0		425.0	89.497	4.749	$271.98																										
5/22/2019		16898.2	362430.8		330.8	68.772	4.810	$209.00	10.0		$21.90	$219.00																						
6/4/2019		16459.0	362870.0		439.2	88.334	4.972	$263.15																										
6/17/2019		16156.0	363173.0		303.0	61.587	4.920	$175.46																										
6/19/2019		15848.0	363481.0		308.0	64.129	4.803	$182.70																										
6/21/2019		15417.0	363912.0		431.0	77.175	5.585	$216.01																										
6/25/2019		15061.0	364268.0		356.0	70.969	5.016	$198.64	7.5		$16.43	$123.19																						
6/26/2019		14785.0	364544.0		276.0	58.384	4.727	$163.42																										
6/27/2019		14414.0	364915.0		371.0	80.178	4.627	$224.42																										
7/2/2019		13987.0	365342.0		427.0	85.469	4.996	$239.23	6.0		$13.14	$78.84																						
7/3/2019		13601.0	365728.0		386.0	71.812	5.375	$201.00																										
7/8/2019		13218.0	366111.0		383.0	75.835	5.050	$212.26																										
7/9/2019		12810.0	366519.0		408.0	72.389	5.636	$202.00	3.5		$7.67	$26.83																						
7/10/2019		12547.0	366782.0		263.0	47.114	5.582	$131.87																										
7/12/2019		12098.0	367231.0		449.0	81.866	5.485	$229.14																										
7/15/2019		12012.0	367317.0		86.0	17.489	4.917	$49.30																										
7/16/2019		11650.0	367679.0		362.0	66.326	5.458	$186.97	6.0		$13.14	$78.84																						
7/17/2019		11268.0	368061.0		382.0	71.644	5.332	$201.96													$380.00	$380.00				purchased 2 tarps after the tarp was destroyed by a bucket full of rock								
7/19/2019		10831.0	368498.0		437.0	72.189	6.054	$203.50																										
7/22/2019		10513.0	368816.0		318.0	58.185	5.465	$162.86	6.0		$13.14	$78.84																						
7/23/2019		10276.0	369053.0		237.0	46.440	5.103	$129.99																										
7/24/2019		9925.0	369404.0		351.0	60.739	5.779	$170.01										$410.04								right rear inside tandum had 1.5 inch slit in bottom, un repairable								
7/31/2019		9790.0	369539.0		135.0	27.309	4.943	$76.44									$5.47									Nebraska Truck replaced electronic module								
8/1/2019		9299.0	370030.0		491.0	85.105	5.769	$238.21																										
8/2/2019		9086.0	370243.0		213.0	39.756	5.358	$111.28	6.0		$13.14	$78.84																						
8/5/2019		8629.0	370700.0		457.0	74.669	6.120	$209.00																										
8/6/2019		8177.0	371152.0		452.0	86.815	5.206	$243.00	7.5		$16.43	$123.19																						
8/7/2019		7726.3	371602.7		450.7	75.383	5.979	$211.00																										
8/8/2019		7363.2	371965.8		363.1	69.812	5.201	$195.41										$15.00								Tire disposal Fee								
8/13/2019		6945.9	372383.1		417.3	70.381	5.929	$197.00																										
8/14/2019		6533.8	372795.2		412.1	78.241	5.267	$219.00																										
8/20/2019		6127.0	373202.0		406.8	70.555	5.766	$193.96	5.0		$10.95	$54.75																						
8/21/2019		5717.0	373612.0		410.0	76.461	5.362	$191.61																										
8/22/2019		5280.0	374049.0		437.0	75.464	5.791	$189.11	10.0		$21.90	$219.00																						
8/26/2019		4875.0	374454.0		405.0	81.113	4.993	$222.98																										
8/27/2019		4699.0	374630.0		176.0	35.700	4.930	$89.46																										
8/28/2019		4308.0	375021.0		391.0	75.798	5.158	$189.95																										
8/29/2019		3862.0	375467.0		446.0	77.761	5.736	$194.86	5.0		$10.95	$54.75																						
8/30/2019		3483.0	375846.0		379.0	63.881	5.933	$160.09																										
9/3/2019		3259.0	376070.0		224.0	50.601	4.427	$126.80																										
9/4/2019		2890.0	376439.0		369.0	78.546	4.698	$196.83																										
9/10/2019		25000.0	376865.0		426.0	0.000	0.000	$0.00												$220.50	$497.60	$718.10				NE TRUCK CENTER SERVICED								
9/11/2019		24970.0	376895.0		30.0	80.378	0.373	$201.43																										
9/12/2019		24671.0	377194.0		299.0	57.499	5.200	$158.06																										
9/13/2019		24231.0	377634.0		440.0	87.868	5.008	$224.59																										
9/13/2019		24140.3	377814.0		90.7	28.714	3.159	$73.39																										
9/16/2019		24003.3	377951.0		137.0	31.702	4.321	$81.04	5.0		$10.95	$54.75																						
9/17/2019		23651.3	378303.0		352.0	67.714	5.198	$191.56																										
9/17/2019		23245.3	378709.0		406.0	71.821	5.653	$194.35																										
9/19/2019		22855.3	379099.0		390.0	61.503	6.341	$160.89	5.0		$10.95	$54.75					$2.00																	
9/24/2019		22528.3	379426.0		327.0	61.278	5.336	$160.30																										
9/26/2019		22095.3	379859.0		433.0	76.444	5.664	$199.97																										
10/1/2019		21674.3	380280.0		421.0	74.253	5.670	$194.25	5.0		$10.95	$54.75																						
10/2/2019		21274.3	380680.0		400.0	76.919	5.200	$201.22																										
10/3/2019		20958.3	380996.0		316.0	57.679	5.479	$150.88	5.0		$10.95	$54.75																						
10/7/2019		20546.3	381408.0		412.0	80.288	5.132	$227.94																										
10/9/2019		20243.5	381710.8		302.8	60.584	4.998	$157.28																										
10/16/2019		19807.3	382147.0		436.2	87.465	4.987	$227.06													$10.53	$10.53												
10/21/2019		19459.3	382495.0		348.0	69.712	4.992	$200.00																										
10/22/2019		19090.3	382864.0		369.0	73.893	4.994	$212.00																										
10/23/2019		18845.6	383108.7		244.7	48.939	5.000	$140.41																										
10/23/2019		18618.2	383336.1		227.4	45.480	5.000	$130.48																										

10/25/2019		18428.9	383525.4		189.3	37.854	5.001	$99.40																												
10/25/2019		18137.8	383816.5		291.1	58.214	5.001	$152.87																												
10/28/2019		17855.5	384098.8		282.3	56.466	4.999	$162.00						1.0	$10.75											1 quart of diesel additive									
10/30/2019		17657.8	384296.5		197.7	39.536	5.001	$106.59						1.0	$12.39											1 quart of Air brake Anti-Freeze									
10/31/2019		17347.9	384606.4	309.9	309.9	53.069	5.840	$143.07																												
11/5/2019		17015.7	384938.6	642.1	332.2	70.448	4.716	$189.93											$121.00	$8.47	$129.47					Repaired two shorts in gate wiring									
11/6/2019		16803.6	385150.7	854.2	212.1	38.668	5.485	$104.25																												
11/7/2019		16532.5	385421.8	1125.3	271.1	52.776	5.137	$15.11						1.0	$12.39											1 quart of air brake antifreeze									
11/8/2019		16276.0	385678.3	1381.8	256.5	0.000	0.000	$0.00	10.0		$21.90	$219.00																								
11/13/2019		16000.0	385954.3	1657.8	276.0	49.335	5.594	$133.01											$218.75	$260.20	$478.95					Broken fan Belt, Inland came out to Cody Park and replaced									
11/18/2019		15731.6	386222.7	1926.2	268.4	41.169	6.519	$111.00	2.5		$5.48	$13.69																								
11/20/2019		15404.3	386550.0	2253.5	327.3	59.025	5.545	$159.13											$180.00	$104.00	$284.00					Shredded Fan Belt, took to Troyers in BB, Replaced fan belt alinged pullies, repair turn signal problem									
11/22/2019		15073.8	386880.5	2584.0	330.5	64.309	5.139	$173.37																												
11/25/2019		14741.5	387212.8	2916.3	332.3	55.461	5.992	$149.52									$1,434.42		$72.70	$110.00	$182.70					4 new driver tires on front axle, new drivers side windshield									
12/9/2019		14342.9	387611.4	3314.9	398.6	75.925	5.250	$205.00	7.5		$16.43	$123.19																								
12/10/2019		13971.0	387983.3	3686.8	371.9	73.693	5.047	$198.97																												
12/12/2019		13571.8	388382.5	4086.0	399.2	70.259	5.682	$189.70																												
1/14/2020		13279.1	388675.2	4378.7	292.7	55.236	5.299	$150.58	2.5		$5.48	$13.69				$2.00																				
2/7/2020		12954.1	389000.2	4703.7	325.0	66.920	4.857	$169.04												$7.45	$7.45															
2/10/2020		12545.7	389408.6	5112.1	408.4	77.290	5.284	$195.24	5.0		$10.95	$54.75																								
2/14/2020		12165.2	389789.1	380.5	380.5	69.398	5.483	$209.02																												
2/28/2020		11878.2	390076.1	287.0	287.0	63.998	4.485	$161.66																												
3/2/2020		11629.7	390324.6	535.5	248.5	50.175	4.953	$126.74	7.5		$16.43	$123.19																								
3/3/2020		11351.4	390602.9	813.8	278.3	59.231	4.699	$149.62																												
3/9/2020		10971.7	390982.6	1193.5	379.7	80.589	4.712	$193.90																												
3/16/2020		10894.2	391060.1	1271.0	77.5		0.000							1.0	$12.00				$687.50	$811.80	$1,499.30					Replaced broken tensioner pulley and two belts. Replaced speedometer. Added 1 gallon of antifreeze									
3/17/2020		10666.5	391287.8	227.7	227.7	69.208	3.290	$152.67																												
3/25/2020		10315.4	391638.9	578.8	351.1	85.095	4.126	$174.95	5.0		$10.95	$54.75																								
3/27/2020		9997.8	391956.5	896.4	317.6	64.901	4.894	$133.44																												
4/1/2020		9688.7	392265.6	1205.5	309.1	70.510	4.384	$162.10	5.0		$10.95	$54.75																								
4/3/2020		9322.1	392632.2	1572.1	366.6	75.856	4.833	$149.80																												
4/6/2020		8999.0	392955.3	1895.2	323.1	56.860	5.682	$130.72	1.0		$2.19	$2.19																								
4/7/2020		8632.2	393322.1	2262.0	366.8	80.700	4.545	$184.49	10.0		$21.90	$219.00																								
4/13/2020		8158.9	393795.4	2735.3	473.3	65.681	7.206	$125.19																												
4/14/2020		7902.2	394052.1	2992.0	256.7	76.146	3.371	$163.64																												
4/15/2020		7568.2	394386.1	3326.0	334.0	59.137	5.648	$127.68																												
4/17/2020		7351.2	394603.1	3543.0	217.0	39.046	5.558	$74.42																												
4/20/2020		7035.5	394918.8	3858.7	315.7	66.730	4.731	$127.18																												
4/21/2020		7035.5	394918.8	3858.7	0.0																															
4/28/2020		6579.6	395374.7	4314.6	455.9	75.008	6.078	$147.64	2.5		$5.48	$13.69							$187.50	$18.48	$205.98															
4/28/2020		6579.6	395374.7	4314.6	0.0												$863.38		$448.00	$62.36	$510.36					Two new front tires from Garrett's, Nebraska Truck aligned front end.									
4/30/2020		6185.7	395768.6	4708.5	393.9	88.183	4.467	$171.44	2.5		$5.48	$13.69								$38.46	$38.46															
5/1/2020		5898.6	396055.7	4995.6	287.1	60.375	4.755	$118.20	2.5		$5.48	$13.69																								
5/6/2020		5603.8	396350.5	5290.4	294.8	71.409	4.128	$125.40																												
5/6/2020		5336.5	396617.8	5557.7	267.3	53.753	4.973	$94.39																												
5/7/2020		4975.1	396979.2	5919.1	361.4	72.804	4.964	$127.85	5.0		$10.95	$54.75																								
5/8/2020		4655.7	397298.6	6238.5	319.4	66.400	4.810	$116.59					4	$10.68																						
5/11/2020		4349.6	397604.7	6544.6	306.1	59.470	5.147	$105.03	2.5		$5.48	$13.69		$0.00																						
5/12/2020		4030.5	397923.8	6863.7	319.1	67.224	4.747	$118.04						$0.00																						
5/18/2020		3747.2	398207.1	7147.0	283.3	55.254	5.127	$97.02						$0.00																						
5/20/2020		3508.6	398445.7	7385.6	238.6	49.186	4.851	$86.37	5.0		$10.95	$54.75	3	$8.01																						
6/1/2020		3111.1	398843.2	7783.1	397.5	75.023	5.298	$131.74						$0.00																						
6/2/2020		2654.9	399299.4	8239.3	456.2	79.086	5.768	$138.87	5.0		$10.95	$54.75		$0.00																						
6/3/2020		2210.4	399743.9	8683.8	444.5	76.463	5.813	$134.27	3.5		$7.67	$26.83		$0.00																						
6/4/2020		1827.5	400126.8	9066.7	382.9	68.288	5.607	$119.92						$0.00																						
6/8/2020		1421.3	400533.0	9472.9	406.2	81.654	4.975	$143.39	4.0		$8.76	$35.04		$0.00																						
6/12/2020		973.6	400980.7	9920.6	447.7	77.152	5.803	$135.48						$0.00																						
6/15/2020		629.7	401324.6	10264.5	343.9	71.224	4.828	$125.07						$0.00																						
6/16/2020		292.6	401661.7	10601.6	337.1	65.042	5.183	$114.21	5.0		$10.95	$54.75		$0.00						$19.50	$19.50					Windshield washer fluid									
6/17/2020		-41.5	401995.8	10935.7	334.1	66.163	5.050	$116.18						$0.00																						
6/22/2020		-432.8	402387.1	11327.0	391.3	73.607	5.316	$139.56						$0.00																						
6/23/2020		-844.4	402798.7	11738.6	411.6	74.026	5.560	$140.35						$0.00																						
6/23/2020		-1106.0	403060.3	12000.2	261.6	46.424	5.635	$88.02						$0.00																						
6/24/2020		-1466.5	403420.8	12360.7	360.5	63.811	5.649	$120.98	7.0		$15.33	$107.31		$0.00																						
6/25/2020		-1880.5	403834.8	12774.7	414.0	75.555	5.479	$143.25						$0.00																						
6/30/2020		25000.0	403966.1	12906.0	131.3	75.555	1.738							$0.00					$595.50	$600.76	$1,196.26					Nebr Truck Center serviced truck and replaced wiring harness. Harness was under warranty									
7/1/2020		24726.0	404240.1	13180.0	274.0	75.555	3.626	$138.42	5.0		$10.95	$54.75		$0.00																						
7/2/2020		24546.0	404420.1	13360.0	180.0	28.192	6.385	$60.40						$0.00																						
7/6/2020		24071.7	404894.4	13834.3	474.3	85.624	5.539	$162.34	4.0		$8.76	$35.04		$0.00																						
7/6/2020		23843.0	405123.1	14063.0	228.7	36.192	6.319	$68.62						$0.00																						
7/7/2020		23521.0	405445.1	14385.0	322.0	63.262	5.090	$135.32						$0.00																						
7/8/2020		23099.0	405867.1	14807.0	422.0	76.612	5.508	$145.25						$0.00																						
7/9/2020		22652.0	406314.1	15254.0	447.0	78.987	5.659	$149.76						$0.00																						
7/10/2020		22251.3	406714.8	15654.7	400.7	72.489	5.528	$137.44	8.3		$18.09	$149.42		$0.00																						
7/13/2020		21872.4	407093.7	16033.6	378.9	71.491	5.300	$135.55						$0.00																						
7/15/2020		21563.0	407403.1	16343.0	309.4	56.914	5.436	$121.80						$0.00					$570.00	$213.35	$783.35					Repaired AC and replaced wiring harness									
7/16/2020		21096.0	407870.1	16810.0	467.0	81.018	5.764	$153.61						$0.00																						
7/17/2020		20733.0	408233.1	17173.0	363.0	64.029	5.669	$121.40	2.5		$5.48	$13.69		$0.00																						
7/17/2020		20558.0	408408.1	17348.0	175.0	29.140	6.005	$57.00						$0.00																						
7/20/2020		20221.0	408745.1	17685.0	337.0	64.842	5.197	$122.94						$0.00																						
7/21/2020		19828.0	409138.1	18078.0	393.0	70.664	5.562	$168.32	7.5		$16.43	$123.19		$0.00																						
7/23/2020		19547.0	409419.1	18359.0	281.0	42.723	6.577	$81.00						$0.00			$1,521.54									4 new driver tires on the rear tandum									
7/27/2020		19140.0	409826.1	18766.0	407.0	71.972	5.655	$136.46						$0.00																						
7/28/2020		18728.0	410238.1	19178.0	412.0	72.605	5.675	$137.66	5.0		$10.95	$54.75	2	$5.34																						
7/31/2020		17869.0	411097.1	20037.0	859.0	75.780	11.335	$143.68						$0.00																						
8/3/2020		17506.0	411460.1	20400.0	363.0	65.500	5.542	$124.18						$0.00																						
8/4/2020		17197.0	411769.1	20709.0	309.0	57.664	5.359	$109.33	7.5		$16.43	$123.19		$0.00																						
8/4/2020		16737.0	412229.1	21169.0	460.0	79.672	5.774	$170.42						$0.00																						
8/6/2020		16388.0	412578.1	21518.0	349.0	60.286	5.789	$143.60	7.5		$16.43	$123.19		$0.00																						
8/7/2020		15992.8	412973.3	21913.2	395.2	74.643	5.295	$141.52						$0.00																						
8/10/2020		15634.0	413332.1	22272.0	358.8	74.643	4.807	$126.27	7.5		$16.43	$123.19		$0.00																						
8/11/2020		15234.0	413732.1	22672.0	400.0	74.471	5.371	$141.19						$0.00												Replaced right side front driver air bag									
8/12/2020		14782.0	414184.1	23124.0	452.0	78.839	5.733	$168.64						$0.00																						
8/13/2020		14426.0	414540.1	23480.0	356.0	65.170	5.463	$123.56	7.5		$16.43	$123.19		$0.00																						
8/14/2020		14107.0	414859.1	23799.0	319.0	58.188	5.482	$124.46					1	$2.67																						

8/17/2020		13827.0	415139.1	24079.0	280.0	50.467	5.548	$135.69					$0.00																						
8/18/2020		13467.0	415499.1	24439.0	360.0	67.683	5.319	$128.32					$0.00																						
8/19/2020		13107.0	415859.1	24799.0	360.0	65.281	5.515	$74.36	7.5	$16.43	$123.19		$0.00																						
8/20/2020		12649.0	416317.1	25257.0	458.0	84.173	5.441	$159.60				3	$8.01																						
8/21/2020		12157.0	416809.1	25749.0	492.0	77.629	6.338	$147.19					$0.00																						
8/21/2020		11958.0	417008.1	25948.0	199.0	42.137	4.723	$90.13					$0.00																						
8/24/2020		11647.0	417319.1	26259.0	311.0	58.151	5.348	$110.25				3	$8.01																						
8/25/2020		11285.0	417681.1	26621.0	362.0	64.261	5.633	$121.83	6.5	$14.24	$92.53	5	$54.36												1 gallon of oil stableizer and 1 qt Oil										
8/26/2020		10918.0	418048.1	26988.0	367.0	69.521	5.279	$131.82					$0.00																						
8/27/2020		10554.0	418412.1	27352.0	364.0	66.039	5.512	$141.26	7.0	$15.33	$107.31		$0.00																						
8/27/2020		10091.0	418875.1	27815.0	463.0	83.888	5.519	$179.44					$0.00																						
8/28/2020		9817.0	419149.1	28089.0	274.0	48.836	5.611	$92.59					$0.00																						
8/31/2020		9371.5	419594.6	28534.5	445.5	82.647	5.390	$179.44	2.5	$5.48	$13.69		$0.00				$40.00								Tire repair										
9/1/2020		9193.0	419773.1	28713.0	178.5	33.679	5.300	$63.86					$0.00																						
9/2/2020		8819.0	420147.1	29087.0	374.0	66.369	5.635	$125.83					$0.00																						
9/3/2020		8369.0	420597.1	29537.0	450.0	74.859	6.011	$141.93	7.5	$16.43	$123.19		$0.00																						
9/3/2020		8059.0	420907.1	29847.0	310.0	59.987	5.168	$113.73					$0.00																						
9/8/2020		7711.2	421254.9	30194.8	347.8	69.399	5.012	$131.58					$0.00						$11.99	$11.99					Drivers side wiper blade										
9/9/2020		7283.2	421682.9	30622.8	428.0	84.046	5.092	$179.77					$0.00						$11.99	$11.99					Passenger side wiper blade										
9/10/2020		6961.0	422005.1	30945.0	322.2	58.036	5.552	$124.14	7.5	$16.43	$123.19		$0.00																						
9/11/2020		6616.0	422350.1	31290.0	345.0	64.498	5.349	$122.29					$0.00																						
10/5/2020		6271.0	422695.1	31635.0	345.0	63.408	5.441	$120.22					$0.00					$2,068.75	$3,725.33	$5,794.08					Replaced fuel pump										
10/6/2020		5846.0	423120.1	32060.0	425.0	73.436	5.787	$139.24	5.0	$10.95	$54.75		$0.00																						
10/7/2020		5421.0	423545.1	32485.0	425.0	72.038	5.900	$136.58					$0.00																						
10/8/2020		5095.7	423870.4	32810.3	325.3	70.471	4.616	$133.62	2.5	$5.48	$13.69		$0.00																						
10/9/2020		4900.8	424065.3	33005.2	194.9	36.773	5.300	$73.80	2.0	$4.38	$8.76		$0.00																						
10/12/2020		4690.8	424275.3	33215.2	210.0	48.607	4.320	$97.99					$0.00																						
10/13/2020		4312.0	424654.1	33594.0	378.8	58.979	6.423	$118.90					$0.00																						
10/14/2020		3995.0	424971.1	33911.0	317.0	59.443	5.333	$119.84	5.0	$10.95	$54.75		$0.00																						
10/14/2020		3835.0	425131.1	34071.0	160.0	30.862	5.184	$69.72					$0.00																						
10/19/2020		3076.0	425890.1	34830.0	759.0	61.303	12.381	$138.48					$0.00																						
10/20/2020		2676.9	426289.2	35229.1	399.1	77.136	5.174	$155.51	7.0	$15.33	$107.31		$0.00																						
10/21/2020		2295.2	426670.9	35610.8	381.7	75.353	5.065	$151.91					$0.00																						
10/22/2020		1939.0	427027.1	35967.0	356.2	67.782	5.255	$136.65	5.0	$10.95	$54.75		$0.00																						
10/30/2020		1682.0	427284.1	36224.0	257.0	73.950	3.475	$142.43					$0.00					$250.00	$139.29	$389.29					Repaired leaking wheel seal on drivers side front tandum										
11/2/2020		1227.0	427739.1	36679.0	455.0	59.291	7.674	$114.19					$0.00																						
11/3/2020		1036.0	427930.1	36870.0	191.0	37.678	5.069	$72.56	3.0	$6.57	$19.71		$0.00																						
11/4/2020		718.0	428248.1	37188.0	318.0	56.454	5.633	$108.73					$0.00																						
11/5/2020		448.0	428518.1	37458.0	270.0	46.391	5.820	$89.35					$0.00						$24.20	$24.20					Back Up Alarm										
11/12/2020		167.4	428798.7	37738.6	280.6	48.365	5.802	$92.19	4.5	$9.86	$44.35		$0.00						$24.78	$24.78					Air Brake Anti Freeze										
11/13/2020		-76.6	429042.7	37982.6	244.0	55.931	4.363	$106.61					$0.00																						
11/20/2020		25000.0	429254.1	38194.0	211.4								$0.00					$158.00	$406.67	$564.67	Nebr truck Center serviced truck & we purchased 5th wheel lube disk												
12/1/2020		24750.0	429504.1	38444.0	250.0	84.124	2.972	$183.06					$0.00																						
12/4/2020		24572.8	429681.3	38621.2	177.2	55.135	3.214	$123.25	3.5	$7.67	$26.83		$0.00																						
12/8/2020		24433.9	429820.2	38760.1	138.9	37.412	3.713	$90.50					$0.00																						
12/9/2020		24263.8	429990.3	38930.2	170.1	53.838	3.159	$130.23					$0.00																						
12/10/2020		24119.6	430134.5	39074.4	144.2	45.983	3.136	$111.23					$0.00																						
12/11/2020		23943.6	430310.5	39250.4	176.0	50.066	3.515	$121.11	6.0	$13.14	$78.84		$0.00																						
1/19/2021		23702.2	430551.9	39491.8	241.4	53.537	4.509	$127.20					$0.00																						
2/23/2021		23356.3	430897.8	39837.7	345.9	73.686	4.694	$198.65					$0.00				$40.00								Tire repair										
2/25/2021		22995.1	431259.0	40198.9	361.2	72.993	4.948	$196.79	2.5	$5.48	$13.69		$0.00																						
3/2/2021		22767.3	431486.8	40426.7	227.8	45.568	4.999	$125.59					$0.00																						
3/15/2021		22515.0	431739.1	40679.0	252.3		0.000											$437.50	$869.97	$1,307.47															
3/17/2021		22486.9	431767.2	40707.1	28.1	60.371	0.465	$171.21																											
3/18/2021		22170.3	432083.8	41023.7	316.6	65.724	4.817	$202.36	5.0	$10.95	$54.75																								
3/25/2021		21808.2	432445.9	41385.8	362.1	72.438	4.999	$244.98	2.5	$5.48	$13.69																								
3/30/2021		21461.5	432792.6	41732.5	346.7	82.822	4.186	$239.85																											
4/1/2021		21114.8	433139.3	42079.2	346.7	56.245	6.164	$162.88																											
4/2/2021		20768.1	433486.0	42425.9	346.7	56.661	6.119	$191.63																											
4/6/2021		20421.6	433832.5	42772.4	346.5	73.952	4.685	$250.11	9.0	$19.71	$177.39																								
4/7/2021		20026.4	434227.7	43167.6	395.2	90.123	4.385	$261.00																											
4/8/2021		19604.7	434649.4	43589.3	421.7	81.712	5.161	$236.63	2.5	$5.48	$13.69																								
4/12/2021		19296.0	434958.1	43898.0	308.7	60.386	5.112	$164.01	2.5	$5.48	$13.69																								
4/13/2021		18977.0	435277.1	44217.0	319.0	60.210	5.298	$163.53	2.5	$5.48	$13.69																								
5/7/2021		18540.0	435714.1	44654.0	437.0	84.488	5.172	$229.47																											
5/11/2021		18154.0	436100.1	45040.0	386.0	80.188	4.814	$217.79	10.0	$21.90	$219.00																								
5/12/2021		17716.0	436538.1	45478.0	438.0	86.671	5.054	$235.40									$424.99								Replaced drivers side front tire										
5/13/2021		17282.0	436972.1	45912.0	434.0	94.361	4.599	$258.98																											
6/4/2021		16894.0	437360.1	46300.0	388.0	63.563	6.104	$172.63																											
6/7/2021		16583.0	437671.1	46611.0	311.0	46.379	6.706	$147.27	7.8	$17.13	$133.92																								
6/8/2021		16261.0	437993.1	46933.0	322.0	72.893	4.417	$204.54					1.0	$10.00																					
6/9/2021		15894.0	438360.1	47300.0	367.0	36.769	9.981	$103.18																											
6/9/2021		15594.0	438660.1	47600.0	300.0	64.441	4.655	$180.82																											
6/10/2021		15394.0	438860.1	47800.0	200.0	48.770	4.101	$155.53																											
6/10/2021		15194.0	439060.1	48000.0	200.0	60.724	3.294	$170.39																											
6/14/2021		14845.0	439409.1	48349.0	349.0	69.669	5.009	$195.49																											
6/15/2021		14388.0	439866.1	48806.0	457.0	65.565	6.970	$199.91	7.5	$16.43	$123.19																								
6/24/2021		14086.0	440168.1	49108.0	302.0	59.918	5.040	$171.13																											
6/29/2021		13769.0	440485.1	49425.0	317.0	73.747	4.298	$210.62																											
6/29/2021		13369.0	440885.1	49825.0	400.0	62.492	6.401	$178.47																											
7/2/2021		13023.0	441231.1	50171.0	346.0	67.229	5.147	$192.00																											
7/7/2021		12672.0	441582.1	50522.0	351.0	68.163	5.149	$194.68																											
7/8/2021		12355.0	441899.1	50839.0	317.0	61.820	5.128	$176.56	7.5	$16.43	$123.19																								
7/8/2021		12183.0	442071.1	51011.0	172.0	34.676	4.960	$99.03																											
7/13/2021		11901.8	442352.3	51292.2	281.2	51.564	5.453	$147.27	3.0	$6.57	$19.71																								
7/14/2021		11560.0	442694.1	51634.0	341.8	60.454	5.654	$172.66																											
7/15/2021		11220.0	443034.1	51974.0	340.0	58.244	5.838	$166.35																											
7/27/2021		10905.0	443349.1	52289.0	315.0	63.520	4.959	$196.85																											
7/27/2021		10633.0	443621.1	52561.0	272.0	44.884	6.060	$128.19																											
7/28/2021		10249.0	444005.1	52945.0	384.0	67.021	5.730	$191.41	7.2	$15.77	$113.53																								
7/29/2021		9941.0	444313.1	53253.0	308.0	53.242	5.785	$152.06																											
7/30/2021		9694.0	444560.1	53500.0	247.0	62.698	3.940	$179.06					1.5	$15.00																					
8/2/2021		9332.0	444922.1	53862.0	362.0	56.180	6.444	$160.45	5.0	$10.95	$54.75		1.0	$10.00																					
8/2/2021		9086.0	445168.1	54108.0	246.0	40.232	6.115	$117.72																											
8/3/2021		8819.0	445435.1	54375.0	267.0	46.214	5.777	$135.22																											

8/5/2021		8511.0	445743.1	54683.0	308.0	51.531	5.977	$150.78	3.5		$7.67	$26.83			0.5	$5.00																				
8/10/2021		8107.0	446147.1	55087.0	404.0	67.686	5.969	$198.05																												
8/11/2021		7693.0	446561.1	55501.0	414.0	71.004	5.831	$207.76																												
8/12/2021		7288.0	446966.1	55906.0	405.0	68.539	5.909	$200.55																												
8/13/2021		6894.0	447360.1	56300.0	394.0	91.317	4.315	$272.15																												
8/18/2021		6458.0	447796.1	56736.0	436.0	65.243	6.683	$185.03	7.0		$15.33	$107.31			1.0	$10.00																				
8/19/2021		6286.9	447967.2	56907.1	171.1	30.147	5.676	$85.49							2.0	$20.00																				
8/30/2021		6254.0	448000.1	56940.0	32.9															$1,187.50	$2,682.62	$3,870.12				Ne Truck Center Replaced Radiator, checked out air conditioner										
9/1/2021		5973.0	448281.1	57221.0	281.0	63.104	4.453	$178.97																												
9/16/2021		5494.0	448760.1	57700.0	479.0	120.446	3.977	$365.64											$551.25	$312.50	$211.83	$524.33				Herbst towed to Ne Truck who replaced fuel pump										
9/20/2021		5013.0	449241.1	58181.0	481.0	55.581	8.654	$164.29	6.0		$13.14	$78.84																								
9/21/2021		4647.0	449607.1	58547.0	366.0	68.990	5.305	$203.94																												
9/22/2021		4372.0	449882.1	58822.0	275.0	50.673	5.427	$149.79													$88.25	$88.25				Replaced radiator hose										
9/23/2021		4015.0	450239.1	59179.0	357.0	61.503	5.805	$181.80	2.5		$5.48	$13.69						$358.55								repaired one driver tire and replaced another because of cut in sidewall										
9/27/2021		3603.1	450651.0	59590.9	411.9	79.007	5.213	$233.54																												
9/27/2021		3318.9	450935.2	59875.1	284.2	48.122	5.906	$142.25	6.5		$14.24	$92.53																								
9/28/2021		2968.9	451285.2	60225.1	350.0	65.121	5.375	$192.50																												
9/29/2021		2618.9	451635.2	60575.1	350.0	64.782	5.403	$222.98																												
10/4/2021		2393.9	451860.2	60800.1	225.0	43.828	5.134	$133.50									$329.42								Replaced passenter side rear inside driver tire										
10/5/2021		2072.9	452181.2	61121.1	321.0	74.044	4.335	$225.54	7.5		$16.43	$123.19																								
10/5/2021		1763.9	452490.2	61430.1	309.0	55.891	5.529	$170.25																												
10/6/2021		1413.7	452840.4	61780.3	350.2	76.367	4.586	$232.61																												
10/8/2021		1063.7	453190.4	62130.3	350.0	75.267	4.650	$229.26																												
10/12/2021		671.2	453582.9	62522.8	392.5	64.408	6.094	$200.09	7.5		$16.43	$123.19									$36.74	$36.74				Air Tank Mounting Cable										
10/12/2021		372.0	453882.1	62822.0	299.2	66.151	4.523	$201.50																												
10/13/2021		52.0	454202.1	63142.0	320.0	64.661	4.949	$196.96																												
10/14/2021		-248.0	454502.1	63442.0	300.0	56.782	5.283	$181.47																												
10/14/2021		-568.0	454822.1	63762.0	320.0	74.414	4.300	$255.91																												
10/19/2021		-877.5	455131.6	64071.5	309.5	77.464	3.995	$247.58	7.0		$15.33	$107.31																								
10/20/2021		-1185.0	455439.1	64379.0	307.5	70.413	4.367	$225.04									$40.00								CPI repaired passenger side inside rear duel, bolt in tire										
10/21/2021		-1505.0	455759.1	64699.0	320.0	58.640	5.458	$188.67	2.5		$5.48	$13.69																								
10/27/2021		-1805.0	456059.1	64999.0	300.0	63.968	4.690	$205.73																												
10/28/2021		-2105.0	456359.1	65257.0	300.0	63.986	4.689	$205.78																												
11/2/2021		25000.0	456657.1	65555.0	298.0	61.511	4.845	$212.77	7.5		$16.43	$123.19								$317.00	$364.01	$681.01				Serviced by Nebraska Truck										
11/5/2021		24634.0	457023.1	65921.0	366.0	77.331	4.733	$267.49																												
11/5/2021		24269.0	457388.1	66286.0	365.0	68.129	5.357	$224.55																												
11/23/2021		23871.0	457786.1	66684.0	398.0	75.006	5.306	$257.95									$40.00								T.O. Haas repared the Drivers side front driver inside duel tire										
11/24/2021		23534.0	458123.1	67021.0	337.0	68.802	4.898	$219.89	5.0		$10.95	$54.75																								
11/29/2021		23136.0	458521.1	67419.0	398.0	71.661	5.554	$246.44																												
11/30/2021		22747.0	458910.1	67808.0	389.0	72.115	5.394	$230.48																												
12/9/2021		22387.0	459270.1	68168.0	360.0	65.040	5.535	$217.17	7.5		$16.43	$123.19																								
12/13/2021		22072.0	459585.1	68483.0	315.0	35.970	8.757	$116.11																												
12/13/2021		21878.0	459779.1	68677.0	194.0	59.113	3.282	$197.38																												
12/17/2021		21648.0	460009.1	68907.0	230.0	48.676	4.725	$150.71																												
12/21/2021		21264.0	460393.1	69291.0	384.0	74.991	5.121	$232.17																												
12/23/2021		20852.0	460805.1	69703.0	412.0	76.361	5.395	$251.15	5.0		$10.95	$54.75																								
12/28/2021		20555.0	461102.1	70000.0	297.0																$21.55					Howes diesel treatment and starting fluid										
1/17/2022		20447.0	461210.1	70108.0	108.0	73.742	1.465	$240.10																												
1/29/2022		20382.0	461275.1	70173.0	65.0												$2.00			$1,264.90	$432.45	$1,697.35				Repaired air leak in fuel system that was allowing loss of prime over night										
3/16/2022		20182.0	461475.1	70373.0	200.0	48.978	4.083	$208.45									$2.00																			
3/17/2022		19929.0	461728.1	70626.0	253.0	62.420	4.053	$265.66											$40.00							Repaired Driver Side inside tire on rear axel at TO Haas										
3/21/2022		19626.0	462031.1	70929.0	303.0	61.150	4.955	$254.14																		Took back to TO Haas because same tire is low again.										
3/25/2022		19370.0	462287.1	71185.0	256.0	59.623	4.294	$280.58													$31.00					Headlight and fuses										
3/28/2022		19002.0	462655.1	71553.0	368.0	74.251	4.956	$349.43					2	$10.00																						
3/30/2022		18727.0	462930.1	71828.0	275.0	61.536	4.469	$289.59										$900.88								Replaced two passenger side drivers, Rebar damage										
3/31/2022		18526.0	463131.1	72029.0	201.0	46.122	4.358	$217.05																												
4/4/2022		18215.0	463442.1	72340.0	311.0	58.104	5.352	$273.03	7.0		$15.33	$107.31																								
4/4/2022		17820.0	463837.1	72735.0	395.0	73.787	5.353	$328.80																												
4/14/2022		17495.0	464162.1	73060.0	325.0	75.285	4.317	$327.95													$162.08	$162.08														
4/18/2022		17181.0	464476.1	73374.0	314.0	67.406	4.658	$326.85	6.0		$13.14	$78.84																								
4/27/2022		16782.0	464875.1	73773.0	399.0	69.961	5.703	$329.24													$76.36	$76.36				Replaced broken Mirror										
4/28/2022		16371.0	465286.1	74184.0	411.0	76.760	5.354	$388.10										$1,097.70			$78.52	$78.52				Two rubber hood latchs, two tires drivers side rear drivers.										
5/4/2022		16152.0	465505.1	74403.0	219.0	40.381	5.423	$206.19														$168.46				Air hose repair										
5/5/2022		15792.0	465865.1	74763.0	360.0	67.684	5.319	$346.51	6.5		$14.24	$92.53			2.0	$5.00																				
5/6/2022		15445.0	466212.1	75110.0	347.0	70.141	4.947	$358.14							2.0	$5.00																				
5/10/2022		15107.0	466550.1	75448.0	338.0	63.751	5.302	$325.51																												
5/12/2022		14795.0	466862.1	75760.0	312.0	55.091	5.663	$286.42																												
5/12/2022		14489.0	467168.1	76066.0	306.0	63.397	4.827	$329.60																												
5/17/2022		14129.0	467528.1	76426.0	360.0	68.529	5.253	$329.35	5.0		$10.95	$54.75			4.0	$10.00																				
5/18/2022		13841.0	467816.1	76714.0	288.0	53.476	5.386	$257.01							4.0	$10.00																				
5/19/2022		13426.0	468231.1	77129.0	415.0	80.567	5.151	$381.00																												
5/20/2022		13047.0	468610.1	77508.0	379.0	79.070	4.793	$354.71	6.0		$13.14	$78.84																								
5/25/2022		12716.0	468941.1	77839.0	331.0	66.874	4.950	$308.50																		New drivers side windshield replaced, repaired air conditioner, Brakes,										
6/15/2022		12371.0	469286.1	78184.0	345.0	68.315	5.050	$345.40																												
6/16/2022		12102.0	469555.1	78453.0	269.0	62.006	4.338	$328.57																												
6/16/2022		11856.0	469801.1	78699.0	246.0	53.923	4.562	$287.89																												
6/17/2022		11497.0	470160.1	79058.0	359.0	77.717	4.619	$425.03																												
6/21/2022		11148.0	470509.1	79407.0	349.0	67.301	5.186	$368.07	6.0		$13.14	$78.84																								
6/22/2022		10759.0	470898.1	79796.0	389.0	73.325	5.305	$383.19																												
6/23/2022		10568.0	471089.1	79987.0	191.0	37.955	5.032	$193.80																												
6/23/2022		10215.0	471442.1	80340.0	353.0	63.937	5.521	$342.00																												
6/27/2022		9841.0	471816.1	80714.0	374.0	71.602	5.223	$383.00	7.5		$16.43	$123.19																								
6/27/2022		9599.0	472058.1	80956.0	242.0	44.683	5.416	$228.15																												
6/28/2022		9259.0	472398.1	81296.0	340.0	66.978	5.076	$341.99																												
6/29/2022		8929.0	472728.1	81626.0	330.0	64.124	5.146	$327.42																												
6/30/2022		8488.0	473169.1	82067.0	441.0	83.941	5.254	$428.60	7.5		$16.43	$123.19																								
7/1/2022	Sean	8150.0	473507.1	82405.0	338.0	66.354	5.094	$351.54													$16.00	$16.00				2 wiper blades										
7/5/2022	Sean	7820.0	473837.1	82735.0	330.0	61.591	5.358	$314.48																												
7/6/2022	Kevin	7422.0	474235.1	83133.0	398.0	76.640	5.193	$410.00	5.0		$10.95	$54.75																								
7/7/2022	Kevin	7064.0	474593.1	83491.0	358.0	65.163	5.494	$332.73																												
7/8/2022	Kevin	6596.0	475061.1	83959.0	468.0	88.173	5.308	$432.57																												
7/11/2022	Kevin	6144.0	475513.1	84411.0	452.0	84.870	5.326	$416.38	6.0		$13.14	$78.84																								
7/12/2022	Kevin	5729.0	475928.1	84826.0	415.0	73.800	5.623	$362.07																												
7/13/2022	Kevin	5300.0	476357.1	85255.0	429.0	78.267	5.481	$383.98																												
7/14/2022	Kevin	4881.0	476776.1	85674.0	419.0	76.911	5.448	$377.32	6.0	62.9	$13.14	$78.84																								

7/15/2022	Kevin	4555.0	477102.1	86000.0	326.0	61.618	5.291	$302.30																													
7/18/2022	Kevin	4155.0	477502.1	86400.0	400.0	83.513	4.790	$409.72																													
7/19/2022	Sean	3777.0	477880.1	86778.0	378.0	68.290	5.535	$341.38	5.0	68.3	$10.95	$54.75																									
7/20/2022	Sean	3322.0	478335.1	87233.0	455.0	84.232	5.402	$421.00																													
7/22/2022	Kevin	3047.0	478610.1	87508.0	275.0	57.412	4.790	$287.00																													
7/25/2022	Mike	2711.3	478945.8	87843.7	335.7	61.532	5.456	$307.60									$45.00								Repair inside duel												
7/26/2022	Mike	2336.8	479320.3	88218.2	374.5	70.531	5.310	$352.58	7.0	50.4	$15.33	$107.31																									
7/27/2022	Mike	1865.0	479792.1	88690.0	471.8	83.300	5.664	$416.45																													
7/27/2022	Larry	1864.7	479792.4	88690.3	0.3	83.307	0.004	$396.21																													
7/29/2022	Sean	1534.0	480123.1	89021.0	330.7	62.785	5.267	$280.39	7.5	37.4	$16.43	$123.19																									
8/2/2022	Mike	1416.6	480240.5	89138.4	117.4	25.189	4.661	$118.62																													
8/3/2022	Kevin	1237.9	480419.2	89317.1	178.7	59.672	2.995	$266.50																													
8/3/2022	Kevin	870.0	480787.1	89685.0	367.9	57.762	6.369	$257.96																													
8/4/2022	Kevin	414.0	481243.1	90141.0	456.0	89.697	5.084	$417.00																													
8/8/2022	Kevin	-17.0	481674.1	90572.0	431.0	84.104	5.125	$370.56	5.0	74.1	$10.95	$54.75																									
8/9/2022	Kevin	-431.0	482088.1	90986.0	414.0	81.307	5.092	$358.24																													
8/10/2022	Kevin	-745.0	482402.1	91300.0	314.0	58.293	5.387	$356.83						1.0	$10.00																						
8/11/2022	Kevin	-1200.0	482857.1	91755.0	455.0	86.042	5.288	$379.10	2.5	151.6	$5.48	$13.69																									
8/12/2022	Sean	-1409.0	483066.1	91964.0	209.0	39.958	5.230	$176.05																													
8/15/2022	Kevin	25000.0	483464.1	92362.0	398.0	79.587	5.001	$350.66	7.5		$16.43	$123.19					$674.34			$340.39	$340.39				Kenny & Kevin serviced, Dawson tire replaced left front tire.												
8/17/2022	Kevin	24665.0	483799.1	92697.0	335.0	64.533	5.191	$284.33																													
8/18/2022	Sean	24400.0	484064.1	92962.0	265.0	48.687	5.443	$214.56																													
8/19/2022	Kevin	23931.0	484533.1	93431.0	469.0	89.053	5.267	$392.37									$1,695.40								Dawson Tire replaced all four rear driver tires												
8/22/2022	Sean	23469.0	484995.1	93893.0	462.0	50.642	9.123	$223.12																													
8/23/2022	Kevin	23108.0	485356.1	94254.0	361.0	70.337	5.132	$309.91																													
8/25/2022	Kevin	22774.0	485690.1	94588.0	334.0	64.529	5.176	$284.32																													
8/25/2022	Kevin	22537.0	485927.1	94825.0	237.0	44.431	5.334	$204.20																													
8/26/2022	Sean	22268.0	486196.1	95094.0	269.0	52.627	5.111	$241.87	6.0	40.3	$13.14	$78.84																									
8/29/2022	Kevin	21858.0	486606.1	95504.0	410.0	74.379	5.512	$341.93						0.5	$5.00																						
8/30/2022	Kevin	21618.0	486846.1	95744.0	240.0	45.465	5.279	$208.96	3.0	69.7	$6.57	$19.71								$64.58	$64.58				Passenger side mud flap hanger												
8/31/2022	Kevin	21294.0	487170.1	96068.0	324.0	60.715	5.336	$302.30																													
9/7/2022	Kevin	20964.0	487500.1	96398.0	330.0	63.595	5.189	$286.56																													
9/8/2022	Kevin	96856.0	487958.1	96856.0	458.0	86.336	5.305	$389.03																													
10/3/2022	Scott	96612.0	488202.1	97100.0	244.0	60.829	4.011	$257.06												$11.21	$11.21				Replaced tail light												
10/4/2022	Mike	96235.0	488579.1	97477.0	377.0	56.045	6.727	$257.75	5.0		$10.95	$54.75																									
10/7/2022	Sean	95874.0	488940.1	97838.0	361.0	79.097	4.564	$376.42																													
10/20/2022	Kevin	95491.0	489323.1	98221.0	383.0	78.251	4.895	$397.99																													
10/24/2022	Kevin	95059.0	489755.1	98653.0	432.0	88.385	4.888	$449.52	7.0		$15.33	$107.31		1.0	$10.00																						
10/25/2022	Kevin	94656.0	490158.1	99056.0	403.0	79.053	5.098	$391.79					4	$20.00																							
10/26/2022	Kevin	94194.0	490620.1	99518.0	462.0	86.556	5.338	$428.97																													
10/27/2022	Kevin	93806.0	491008.1	99906.0	388.0	73.285	5.294	$363.20																													
10/28/2022	Kevin	93454.0	491360.1	100258.0	352.0	65.397	5.383	$324.11	7.0		$15.33	$107.31		1.0	$10.00																						
10/31/2022	Kevin	93037.0	491777.1	100675.0	417.0	80.785	5.162	$400.37																													
11/2/2022	Kevin	92653.0	492161.1	101059.0	384.0	70.772	5.426	$331.38						1.0	$10.00					$13.44	$13.44				Kevin replaced the passenger side headlight												
11/3/2022	Kevin	92241.0	492573.1	101471.0	412.0	80.385	5.125	$373.47												$26.88	$26.88				Kevin replaced the drivers side headlight and bought a spare to put in inventory.												
11/7/2022	Kevin	91834.0	492980.1	101878.0	407.0	84.270	4.830	$391.52	10.0		$21.90	$219.00																									
11/8/2022	Kevin	91502.0	493312.1	102210.0	332.0	72.611	4.572	$337.36						0.5	$5.00																						
11/9/2022	Kevin	91177.0	493637.1	102535.0	325.0	66.681	4.874	$309.80																													
11/10/2022	Kevin	90789.0	494025.1	102923.0	388.0	66.066	5.873	$323.00																													
11/10/2022	Kevin	90505.0	494309.1	103207.0	284.0	74.043	3.836	$344.01																													
11/14/2022	Kevin	90248.0	494566.1	103464.0	257.0	56.461	4.552	$253.28	8.0		$17.52	$140.16																									
11/16/2022	Kevin	89881.0	494933.1	103831.0	367.0	79.934	4.591	$358.59																													
11/18/2022	Kevin	89525.0	495289.1	104187.0	356.0	79.721	4.466	$377.00																													
11/22/2022	Kevin	89190.0	495624.1	104522.0	335.0	72.743	4.605	$326.32	5.0		$10.95	$54.75								$107.02	$107.02				Air Line Antifreeze and two hood latchs												
11/23/2022	Kevin	88753.0	496061.1	104959.0	437.0	79.721	5.482	$357.63																													
11/28/2022	Mike	88636.0	496178.1	105076.0	117.0														$225.00	$29.08	$254.08	repaired Def heater wires and reset codes													
12/2/2022	Sean	88409.0	496405.1	105303.0	227.0	69.333	3.274	$295.08																													
12/5/2022	Kevin	88186.0	494532.1	105526.0	223.0	50.233	4.439	$213.79						0.5	$5.00		$503.89																				
12/7/2022	Kevin	87875.0	494843.1	105837.0	311.0	69.349	4.485	$295.15	7.5		$16.43	$123.19																									
3/2/2023	Kevin	87562.0	495156.1	106150.0	313.0	73.188	4.277	$282.22					4	$20.00																							
3/6/2023	Kevin	87192.0	495526.1	106520.0	370.0	79.287	4.667	$305.73																													
3/7/2023	Kevin	86821.0	495897.1	106891.0	371.0	76.269	4.864	$286.47	5.0		$10.95																										
3/8/2023	Kevin	86487.0	496231.1	107225.0	334.0	67.518	4.947	$253.59	4.0		$8.76																										
3/14/2023	Kevin	86097.0	496621.1	107615.0	390.0	86.772	4.495	$325.91																	Replaced tire												
3/15/2023	Kevin	85789.0	496929.1	107923.0	308.0	65.017	4.737	$244.20																													
3/21/2023	Kevin	85507.0	497211.1	108205.0	282.0	61.188	4.609	$230.01	7.0		$15.33																										
3/21/2023	Kevin	85306.0	497412.1	108406.0	201.0	47.086	4.269	$165.56																													
3/22/2023	Kevin	85080.0	497638.1	108632.0	226.0	54.269	4.164	$190.81																													
3/24/2023	Kevin	84768.0	497950.1	108944.0	312.0	73.423	4.249	$258.16																													
3/27/2023	Kevin	84376.0	498342.1	109336.0	392.0	79.811	4.912	$280.62																													
3/28/2023	Kevin	84044.0	498674.1	109668.0	332.0	68.634	4.837	$241.32																													
3/29/2023	Kevin	83711.0	499007.1	110001.0	333.0	70.498	4.724	$247.87	7.5		$16.43																										
3/30/2023	Kevin	87537.0	495181.1	110339.0	338.0	69.167	4.887	$243.19																													
4/20/2023	Kevin	87208.0	495510.1	110693.0	354.0	77.291	4.580	$287.22	6.0		$13.14								$1,272.00	$1,011.13	$2,283.13				Repaired air leak, greased, adjusted brakes												
4/24/2023	Kevin	86859.0	495859.1	111026.0	333.0	78.282	4.254	$306.00						4.0	$20.00																						
4/25/2023	Kevin	86530.0	496188.1	111317.0	291.0	62.676	4.643	$229.77																													
4/26/2023	Kevin	86117.0	496601.1	111687.0	370.0	72.512	5.103	$264.38																													
5/2/2023	Kevin	85681.0	497037.1	112103.0	416.0	82.910	5.017	$289.85	7.0		$15.33						$354.91			$517.11					Replaced all three batteries and returned old onesw for $90.00 core charge											Replaced drive tire	
5/3/2023	Kevin	85422.0	497296.1	112470.0	367.0	73.550	4.990	$257.13																													
5/4/2023	Kevin	85134.0	497584.1	112843.0	373.0	74.306	5.020	$241.94																													
5/8/2023	Kevin	84948.0	497770.1	113201.0	358.0	70.021	5.113	$227.98	5.0		$10.95																										
5/9/2023	Kevin	84724.0	497994.1	113557.0	356.0	76.307	4.665	$248.46												$27.26					2 convex mirrors												
5/11/2023	Kevin	84413.0	498305.1	113912.0	355.0	75.024	4.732	$251.78	3.5		$7.67			4.0	$20.00																						
5/15/2023	Kevin	84096.0	495461.1	114192.0	280.0	64.533	4.339	$224.32																													
5/17/2023	Kevin	84096.0	495461.1	114192.0	0.0				2.5		$5.48														Flashing Amber Light												
5/17/2023	Kevin	83748.0	495809.1	114540.0	348.0	70.987	4.902	$264.00																													
5/18/2023	Kevin	83352.0	496205.1	114936.0	396.0	73.171	5.412	$249.22																													
5/22/2023	Kevin	82909.0	496648.1	115379.0	443.0	84.954	5.215	$289.36	6.0		$13.14			4.0	$10.00																						
5/23/2023	Kevin	82528.0	497029.1	115760.0	381.0	72.622	5.246	$247.35																													
6/2/2023	Kevin	82285.0	497272.1	116003.0	243.0	51.523	4.716	$188.01	4.0		$8.76																										
6/5/2023	Kevin	81897.0	497660.1	116391.0	388.0	75.088	5.167	$255.75						4.0	$10.00																						
6/6/2023	Kevin	81565.0	497992.1	116723.0	332.0	65.771	5.048	$224.02																													
6/6/2023	Kevin	81246.0	498311.1	117042.0	319.0	57.762	5.523	$190.96																													
6/8/2023	Kevin	80824.0	498733.1	117464.0	422.0	77.204	5.466	$255.24																													
6/12/2023	Kevin	80454.0	499103.1	117834.0	370.0	65.370	5.660	$216.12	7.0		$15.33																										

6/13/2023	Kevin	80031.0	499526.1	118257.0	423.0	84.531	5.004	$279.46																										
6/14/2023	Kevin	79708.0	499849.1	118580.0	323.0	63.398	5.095	$209.59										$500.79			$45.42	$45.42				Purchased 2 fifth wheel lubrication disks								
6/21/2023	Kevin	79358.0	500199.1	118930.0	350.0	82.937	4.220	$275.85																										
6/21/2023	Kevin	79037.0	500520.1	119251.0	321.0	49.032	6.547	$163.09																										
6/26/2023	Kevin	78620.0	500937.1	119668.0	417.0	77.053	5.412	$275.00	7.0		$15.33																							
7/6/2023	Kevin	78270.0	501287.1	120018.0	350.0	59.680	5.865	$213.00												$1,128.00	$2,350.98	$3,478.98				Repaired heater switch & sensors that were setting codes								
7/10/2023	Kevin	77905.0	501652.1	120383.0	365.0	85.737	4.257	$285.17	5.0		$10.95		4	$10.00																				
7/11/2023	Kevin	77504.0	502053.1	120784.0	401.0	74.530	5.380	$247.89																										
7/17/2023	Kevin	77108.0	502449.1	121180.0	396.0	73.409	5.394	$244.16																										
7/18/2023	Kevin	76799.0	502758.1	121489.0	309.0	57.441	5.379	$205.01	6.5		$14.24																							
7/19/2023	Kevin	76489.0	503068.1	121799.0	310.0	56.037	5.532	$200.00																										
7/19/2023	Kevin	76083.0	503474.1	122205.0	406.0	73.410	5.531	$262.00																										
7/20/2023	Kevin	75729.0	503828.1	122559.0	354.0	64.430	5.494	$214.34																										
11/5/2023		75729.0	503828.1	122559.0	0.0															$186.41		$186.41				Mat Roll 30X150 to lay on the shoip floor while working on the new engine								
11/27/2023		75729.0	503828.1	122559.0	0.0															$630.00		$630.00				Herbst towed Western Star back to the Stapleton Shop								
12/28/2023		75729.0	503828.1	122559.0	0.0															$6,000.00	$7,081.25	$13,081.25				Rebuilding engine, replaced with used engine								
1/30/2024	Kevin	75729.0	503828.1	122559.0	0.0													$399.58			$3.91	$65.43				Replaced one of the driver tires and glad hand airchucki fixture								
1/31/2024	Kevin	75317.0	504240.1	122971.0	412.0	78.673	5.237	$260.88																										
2/1/2024	Kevin	74884.0	504673.1	123404.0	433.0	80.084	5.407	$265.56	7.5		$16.43										$80.55	$80.55				Kevin picked up replacement glad hand cable								
2/6/2024	Kevin	74473.0	505084.1	123815.0	411.0	72.493	5.670	$240.38													$30.31	$30.31				air chuck for Semi								
2/8/2024	Kevin	74075.0	505482.1	124213.0	398.0	62.095	6.410	$205.91																										
2/10/2024	Kevin	73594.0	505963.1	124694.0	481.0	80.225	5.996	$292.51																										
2/12/2024	Kevin	73268.0	506289.1	125020.0	326.0	79.458	4.103	$289.70																										
2/14/2024	Kevin	75294.0	504263.1	125455.0	435.0				5.0		$10.95							$805.27								TO Haas replaced the divers side front inside driver and the passenger side steer tires								
2/20/2024	Kevin	74949.0	504608.1	125800.0	345.0	78.762	4.380	$280.86	5.0		$10.95		2	$5.00	0.5	$5.00																		
3/18/2024	Mike	74702.0	504855.1	126047.0	247.0	61.023	4.048	$230.00	4.0		$8.76																							
3/19/2024	Mike	74220.0	505337.1	126529.0	482.0	57.310	8.410	$216.00																		Truck broke down again								
4/24/2024	Kevin	74168.0	505389.1	126581.0	52.0															$159.00	$112.72	$271.72												
5/6/2024	Kevin	73968.0	505589.1	126781.0	200.0	66.687	2.999	$242.01																										
5/16/2024	Kevin	73738.0	505819.1	127011.0	230.0	74.577	3.084	$233.88												$318.00	$300.87	$618.87				Nebraska Truck Replaced DPF out let sensor & Right Headlight								
5/20/2024	Kevin	73398.0	506159.1	127351.0	340.0	63.339	5.368	$198.83													$304.76					Kenny Replaced the alternator								
5/23/2024	Kevin	73038.0	506519.1	127711.0	360.0	67.476	5.335	$211.60																										
5/28/2024	Kevin	72714.0	506843.1	128035.0	324.0	65.403	4.954	$205.11	1.0		$2.19																							
6/11/2024	Clinton	72514.0	507043.1	128235.0	200.0																					took truck back to Inland to get the air pump repaired								
6/25/2024	Clinton	72360.0	507197.1	128389.0	154.0	64.625	2.383	$207.84																										
6/26/2024	Clinton	72094.0	507463.1	128655.0	266.0	53.288	5.000	$184.32																										
6/27/2024	Clinton	71758.0	507799.1	128991.0	336.0	51.473	6.528	$178.05														$14,765.22				Multiple repairs at inland truck repair and then they got angry when we did not pay them, we were not invoiced.								
7/2/2024	Clinton	71430.0	508127.1	129319.0	328.0	61.401	5.342	$214.84																										
7/3/2024	Clinton	71105.0	508452.1	129644.0	325.0	30.106	10.795	$107.45																										
7/23/2024	Clinton	71012.0	508545.1	129737.0	93.0	44.150	2.106	$153.16																										
7/24/2024	Clinton	70759.0	508798.1	129990.0	253.0	41.900	6.038	$145.27																										
7/25/2024	Clinton	70483.0	509074.1	130266.0	276.0	47.000	5.872	$163.24																										
8/5/2024	Clinton	70232.0	509325.1	130517.0	251.0	46.500	5.398	$159.00																										
8/8/2024	Clinton	69835.0	509722.1	130914.0	397.0	70.000	5.671	$239.35																										
8/13/2024	Clinton	69584.0	509973.1	131165.0	251.0	44.619	5.625	$152.55																										
8/28/2024	Clinton	69440.0	510117.1	131309.0	144.0	37.932	3.796	$125.90													$52.75	$52.75				Water hose and Hose clamps for water hose, Clinton repaired in house.								
8/29/2024	Clinton	69240.0	510317.1	131509.0	200.0	28.504	7.017	$94.60																										
9/3/2024	Kevin	68865.0	510692.1	131884.0	375.0	78.939	4.751	$242.82	7.5		$16.43		1	$5.00																				
9/5/2024	Kevin	68414.0	511143.1	132335.0	451.0	87.978	5.126	$270.62													$64.96	$64.96				2 mud flaps								
9/10/2024	Kevin	67978.0	511579.1	132771.0	436.0	76.781	5.678	$232.34							1.0	$10.00					$38.46	$38.46				2 fifth wheel grease pads								
10/9/2024	Kevin	67560.0	511997.1	133189.0	418.0	77.349	5.404	$247.20																										
11/27/2024	Kevin	67212.0	512345.1	133537.0	348.0	70.300	4.950	$209.92																										
12/3/2024	Kevin	66884.0	512673.1	133865.0	328.0	61.939	5.296	$184.95																										
12/4/2024	Kevin	66554.0	513003.1	134195.0	330.0	68.132	4.844	$203.44																										
12/10/2024	Kevin	66227.0	513330.1	134522.0	327.0	70.922	4.611	$229.01	5.0		$10.95																							
12/11/2024	Kevin	65859.0	513698.1	134890.0	368.0	74.326	4.951	$221.94																										
12/18/2024	Kevin	65445.0	514112.1	135304.0	414.0	81.787	5.062	$240.13																										
12/23/2024	Kevin	65056.0	514501.1	135693.0	389.0	78.045	4.984	$233.05																										
12/30/2024	Kevin	64673.0	514884.1	136076.0	383.0	74.325	5.153	$221.94	7.0		$15.33																							
1/16/2025	Kevin	64414.0	515143.1	136335.0	259.0	60.624	4.272	$185.27																										
1/28/2025	Kevin	63959.0	515598.1	136790.0	455.0	86.983	5.231	$278.86																										
1/29/2025	Kevin	63573.0	515984.1	137176.0	386.0	71.034	5.434	$245.00																										
5/19/2025	Clinton	63313.0	516244.1	137436.0	260.0	51.603	5.038	$174.88												$924.00	$236.35	$1,160.35				Repaired regin system								
7/1/2025	Kevin	62939.0	516618.1	137810.0	374.0	75.300	4.967	$237.70																										
7/2/2025	Kevin	62486.0	517071.1	138263.0	453.0	86.040	5.265	$294.00																										
Current			76222.0		175036.1	33792.6	5.2	$107,198.13	817.8	214.0		$9,858.22	50.0	$208.24	46.0	$277.53	$15.47	$12,535.10	$68,551.25	$21,106.51	$26,437.45	$47,543.96	$13,600.00	$259,787.90	$1.48										