

Landmark Implement Inc.

75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



CEDVICE INVOICE

Invoice To Account No: 81524	Deliver To:		SER	(AICE INACICE
			Invoice Number: Invoice Date: Location: Work Order Number: Payment Type:	11186452 10/19/2021 05 399039 Check
			Page:	1 of 3
Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8235R	3339	1RW8235RVCP06836	09 MM068309	

EXPERT-1000000026624 Retail

COMPLAINT:

01 HYDRAULIC LEAK ONLY UNDER LOAD/WHILE MOVING. OIL GETTING ON TURBO CAUSING SMOKE, TAKE SET OF FUEL FILTERS

CORRECTION:

Drove to the customer and diagnosed the leak. Found that the oil was leaking out of the input shaft and fling it up on the engine. This is generally caused by internal pressure in the transmission. Advised customer to have hauled to the shop. Once the tractor was at the shop, drained oil from the transmission and found that it was 3-4 gallons to full, and that the sump screen was completely plugged with metal and debris. Called customer and let him know that we were going to have to split it to determine what all was needed to repair.

		The state of the s		•
Labor: \$418.75	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$418.75
		Mark.	A STATE OF THE STA	-
PIP16RW688 Retail	3		July 1	
COMPLAINT:	MA EARLY AND	16 SPEED PST - RECONDITION	William Comment	
02 8R/8RT MODEL YEAR 20	112-EARLY 2014	MOSEED PSI -RECONDITION	and Control of Francis Control	Payron .
CORRECTION:	7. E	er INVIII en la company	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The state of the s
Remove transmission and dis	sassemble.			* -
Replace parts as necessary.				;

Replace parts as necessary.
Assemble transmission.
Reassemble in reverse order.
Fill oil to specifications.
Run and test machine.

Once we had the transmission disassembled, we found that the scavage pump had failed and ruined the manifold, and that a few other gears, and a drum were ruined from the spring material going through them.

<u>Part Number</u> 40M7115	<u>Description</u> SNAP RING	Quantity 1.00	List Price 11.30	<u>Net Price</u> 11.30	Extended Price \$11.30	<u>Taxed ind</u> N
AH89023	SEAL	1.00	31.71	31.71	\$31.71	N
A-RE151144	Seal	1.00	21.71	21.71	\$21.71	N
B3690R	O-RING	1.00	4.67	4.67	\$4.67	N



Invoice To Account No: 81524

Landmark Implement Inc.

75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com

Deliver To:



SERVICE INVOICE

invoice to Account No. 518			W	Invoice Num Invoice [Loca /ork Order Nun Payment l	Date: ation: aber:	10/1	9/2021 05 399039 Check
				Р	age:		2 of 3
Make/Model:	Met	ter: Serial Number:		Eq ID:		Fleet No:	
JOHN DEERE 8235R	333	9 1RW8235RVCP	068309	MM068309			
				•			
PIP16RW688 Retail F3171R	O-RING		2.00	2.65	2.65	\$5.30	N
JD10116	NEEDLE BEARING		2.00	12.77	12.77	\$25.54	N
JD8568	BALL BEARING		1.00	41.41	41.41	\$41.41	N
MPR13030	PRODUCT IM		1.00	1,292.04	1,292.04	\$1,292.04	И
MPR13032	PRODUCT IM		1.00	1,022.86	1,022.86	\$1,022.86	N
R105833	DISK SPRING		2.00	99.98	99.98	\$199.96	N
R115233	SHAFT		1.00	113.45	113.45	\$113.45	N
R125379	BOLT M10 X 45.5 SHLDR		4.00	5.86	5.86	\$23.44	N
R163055	Gear		1.00	2,207.33	2,207.33	\$2,207.33	N
R174698	Housing	Service Committee of the Committee of th	1.00	469.45	469.45	\$469.45	N
R185975	CLUTCH PLATE	The state of the s	2.00	232.94	232.94	\$465.88	N
R200571	Gear			1,946.60	1,946.60	\$1,946.60	N
R204520	RING 2	January (2004) January (2004) Santa (2004) S	6.00	11,05	11.05	\$66.30	N
R28640	Snap Ring	VAMEDIAN	, 1,00-	Jy 10/50	10.50	\$10.50	N
R304387	Drum	production of Specimens of Street Street Street	-1.00	1,050.88	1,050.88	\$1,050.88	N
R341564	Gasket	The state of the s	1.00	64.82	64.82	\$64.82	N
R44302	TIE BAND 1/4 X 7.5		20:00	0.18	0.18	\$3.60	N
R529510	GASKET		1.00	26.56	26.56	\$26.56	N
R529640	GASKET		1.00	32.57	32.57	\$32.57	N
R538465	GEAR		1.00	306.46	306.46	\$306.46	N
R570993	Gear		1.00	113.39	113.39	\$113.39	N
RE225759	PISTON		2.00	150.41	150.41	\$300.82	N
RE243742	Screen		1.00	60.05	60.05	\$60.05	N
RE336947	Relay		1.00	119.05	119.05	\$119.05	N
RE573265	Manifold Kit		. 1.00	2,813.76	2,813.76	\$2,813.76	N
RE576867	SEAL		1.00	38.91	38.91	\$38.91	N



Landmark Implement Inc.

75482 Road 435 Lexington, NE 68850 Phone: 308-324-4639 Fax: 308-324-6600 www.landmarkimp.com Lexington@landmarkimp.com



Invoice To Account No: 81524	Deliver	To:				SERV	ICE INV	OICE
		***************************************	**************************************		Invoice Nu	mber:		186452
					Invoice	Date:	10	/19/2021
						cation:		05
					Work Order Nu			399039
					Payment	Туре:		Check
						Page:		3 of 3
Make/Model:		Meter:	Serial Num	iber: .	Eq ID:		Fleet No:	
JOHN DEERE 8235R	A TOTAL CONTROL OF THE STATE OF	3339	1RW8235F	RVCP068309	MM068309			
PIP16RW688 Retail						•		
RE67949	BALL BEARING			2.0	90.56	90.56	\$181.12	N
T121280	SEAL			, 1.0	00 17.95	17.95	\$17.95	N
TY22028	HY-GARD BULK			30.0	00 16.75	16.75	\$502.50	N
Miscellaneous PT3750	Description FREIGHT JD - PARTS	S LEX		Quant 1.0	lty <u>List Price</u> 00 173.40	Net Price 173.40	Extended Price \$173.40	<u>Taxed Ind</u> N
Labor: \$9,912.50	Parts: \$13,591.89	OL&M	: \$0.00	Mis	sc: \$173.40	Sub-To	otal: \$23,677.	.79
An act region and add soft refer to be deviced the execution and the activation activation and the activation activation and the activation and the activation activation and the activation activat	nerez a l'este de construit de la construit de	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	V-4	4
			Personal Control of the Control of t	· ?************************************	*** **********************************	La	bor: \$10),331.25
		The state of the s	na.					3,591.89
				Oh∆			.&M:	\$0.00
·					oranic September 1. 11. 11. 11. 11. 11. 11. 11. 11. 11.	·	lisc:	\$173.40
		(A. Calai, Joseph		in the	and all all a	ුක් Sales	Tax:	\$0.00
*** DOCUMENT CO	OPY***	72 Y N				Grand T	otal:\$2	4,096.54
				ang di ankani Si ang di ankani				
			man district des					
		N.		L. Carlotte				
		Ç		A Charles		•		
				and the second				
			Way (S)	T.				
			V ST					

TERMS AND CONDITIONS

Approved charges are due by the 10th of the month following purchase, I agree to pay a monthly periodic FINANCE CHARGE at the rate of 1.33% which is an ANNUAL PERCENTAGE CHARGE OF 16% on the unpaid balance. The purchaser agrees to pay reasonable attorney fees if collection efforts are required.

Received by:	***************************************
--------------	---