



SAHLING KENWORTH

A CSM Company

Columbus | Kearney | York

Kearney

2206 East 25th St.
P.O. Box 2076
Kearney, NE 68848
(308) 234-2511

**** Reprint ****

Invoice: **041S234724.02**
Date / Hour: 7/22/2024 9:06:22AM
Repair Order: 234724
Customer: 204996
Branch: KRY
Total Invoice: \$ 2,052.58
Credit Card

Page 1 of 3

Bill To: Steve Bunger

Ship To: Steve Bunger

Customer P/O:

Add User: M Hill

Open Date: 07/15/2024

Completion Date: 07/18/2024

Salesperson: House

Unit Number: 5J088881

Model Year: 2005

Make/Model: Kenworth T600

Type: TRUCK

VIN: 1XKAD49X45J088881

Meter: 568813 Miles

In-Service Date: 02/24/2005

Task: 1 042 Cummins Cooling System - Service/Repair

Department: SERVICE

Complaint: Customer states truck is overheating

Correction: 7/15/2024 2:01:51 PM 13044 Pre-inspected tractor for overheating issues, I didn't feel any air being sucked in through the radiator I put a flashlight through the fins and saw that there was major debris in the radiator and pre cooler. First I removed the hood spring mounts and lowered the hood further. I removed the condenser, pre cooler bolts, brackets, and radiator hoses. I power washed the condenser, pre cooler, and radiator fins until I could see through the fins with a flashlight. Without vacuuming the A/C system I was able to flip the condenser laying on top of the engine. I did have to grind off the bottom passenger side pre cooler/condenser bolt and nut due to the nut being rounded off and I replaced that as well. Next I installed the pre cooler and condenser in order and tightened the bolts and brackets. Installed the hood spring mounts, and connected the radiator hoses back on.
7/18/2024 9:04:58 AM 10806 Took unit for a test drive the coolant gauge was not getting above 150 degrees. Replaced the thermostat in the unit removed the charge air piping and intake system piping and removed the a/c compressor belt. Moved the a/c compressor out of the way and drained the coolant then removed the upper radiator hose out of the way. Removed the thermostat housing found it was pitted removed the seal and took to sand blaster cleaned up all sealing surfaces looked good installed new seal and thermostat then installed. Took the unit for test drive now the ecm temp was reading 189 degrees but the coolant temp was showing 150 degrees with temp gun. Checked over wires found the ends were showing bear wire repaired the ends then touched together the gauge went to high temp then disconnected the gauge was not reading. Found all wiring to gauge was good. Took another temp gun and checked it was reading with the ecm temp on thermostat outlet the coolant temp sender had failed. Removed the sender the sensor was stuck in the adapter. Got sensor removed from the adaptor new sender adapter could not find new adapter. Installed sender and filled with coolant then test drove gauge was now working correctly.

Supp. Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
144455	Sender-Temperature	EA	1.0	\$92.19	\$92.19
186780CUM	Seal,Thermostat	EA	1.0	\$21.32	\$21.32
3081695CUM	SEAL,O RING	EA	1.0	\$6.03	\$6.03
3682673CUM	GASKET,THM HOUSING COVER	EA	1.0	\$29.00	\$29.00
4318947CUM	THERMOSTAT	EA	1.0	\$83.87	\$83.87
4954905CUM	SENSOR,TEMPERATURE	EA	1.0	\$27.13	\$27.13
516134C	GRADE 8 BOLT	EA	1.0	\$0.74	\$0.74
516BW	BODY WASHER	EA	5.0	\$3.68	\$18.40
516CSLN	SELF LOCKING N	EA	1.0	\$0.70	\$0.70
516FW	WASHER-EXTRA THICK	EA	4.0	\$0.83	\$3.32
7335337	2 1/2 EXHAUST CLAMP	EA	1.0	\$11.70	\$11.70
CT300LTRP	Clamp-Const Torque Hd Ss #48	EA	1.0	\$6.90	\$6.90
PREAF3300	ANTIFREEZE/COOLANT GREEN 50/50	EA	6.0	\$16.48	\$98.88

Task 1 Subtotals

Parts: \$400.18

Labor: \$1,530.00

Task 1 Subtotals \$1,930.18

** See Last Page for Invoice Total **



SAHLING KENWORTH

A CSM Company

Columbus | Kearney | York

Kearney

2206 East 25th St.
P.O. Box 2076
Kearney, NE 68848
(308) 234-2511

**** Reprint ****

Invoice: **041S234724.02**
Date / Hour: 7/22/2024 9:06:22AM
Repair Order: 234724
Customer: 204996
Branch: KRY
Total Invoice: \$ 2,052.58
Credit Card

Page 2 of 3

Bill To: Steve Bunger

Ship To: Steve Bunger

Customer P/O:

Add User: MHill

Open Date: 07/15/2024

Completion Date: 07/18/2024

Salesperson: House

Task: 2 001

Climate Control - Service/Repair

Department: SERVICE

Complaint: A/C INOP

Correction: Ran A/C on test drive and it was working correctly. Was probably due to cooling package being plugged. No issue found.

Task 2 Subtotals

Parts: \$0.00

Labor: \$0.00

Task 2 Subtotals \$0.00

TRANSACTION TYPE: SALE
TRANSACTION RESULT: APPROVED
TIMESTAMP: 7/22/2024 9:06:18 AM
MERCHANT ORDER NUMBER: 041S234724.02
AMOUNT: \$2,052.58
ENTRY METHOD: Contactlcc
NAME: BUNGER/STEVEN
ACCOUNT TYPE: Mastercard
ACCOUNT: XXXXXXXXXXXX4696
TRANSACTION ID: 1647803957
AUTHORIZATION CODE: 58292Z
RESPONSE CODE: 00
APPLICATION ID: A0000000041010
APPLICATION LABEL: Mastercard
CRYPTOGRAM VALUE: ARQC 5EB2C8668DBBF4AB
PIN VERIFIED: FALSE

Detail Tax Info:

Sales Tax \$0.00
\$0.00

Total Parts: \$400.18
Total Labor: \$1,530.00
Total Shop Supply Fees: \$122.40
Invoice Subtotal: \$2,052.58
Total Tax: \$0.00
Total Invoice: \$2,052.58

Payment Method

Credit Card

Terms

COD

Due Date

7/22/2024

Remit To

Sahling Kenworth - Kearney
28607 Network Place

Chicago, IL 60673-1286



Please tell us how we're doing!

Signature



**SAHLING
KENWORTH**

A CSM Company

Columbus | Kearney | York

Kearney

2206 East 25th St.
P.O. Box 2076
Kearney, NE 68848
(308) 234-2511

**** Reprint ****

Invoice: **041S234724.02**
Date / Hour: 7/22/2024 9:06:22AM
Repair Order: 234724
Customer: 204996
Branch: KRY
Total Invoice: \$ 2,052.58
Credit Card

Page 3 of 3

Bill To: Steve Bungler

Ship To: Steve Bungler

Customer P/O:

Add User: MHill

Open Date: 07/15/2024

Completion Date: 07/18/2024

Salesperson: House

CASH
REPRINT

DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

I HEREBY AUTHORIZE the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

NOTICE: You are entitled to inspect or receive any components, parts or accessories replaced or removed by the shop. There is a charge for Shop Supply Fees for technical service supplies and for the legal disposal of hazardous waste which is not itemized on your repair order. The charge will be 8% of the total labor to a maximum of \$175.

CUSTOMER SIGNATURE _____

PLEASE PRINT NAME _____ DATE _____