

RANCHLAND

BROKEN BOW, NEBRASKA

RANCHLAND FORD
1024 EAST SOUTH E STREET
BROKEN BOW, NE 68822
TEL: (308) 872-6488
WEBSITE: www.ranchland-ford.com



All Roads Lead to
Ranchland!

SO # 102934

Status

Printed 04/28/2025 11:21:26 AM

SERVICE ORDER CUSTOMER COPY



User J Mickle Page 1

Customer No MYERKE
Kenneth Myers
182 E SOUTH N ST
BROKEN BOW, NE 68822
Ford Pass:
Home (308) 870-1201 Bus 308872
Cell (308) 870-1201 Today
Email kenmyers2009@hotmail.com
Type
Term Cash

Advisor Judson
Shop S1
Priority
Promised 03/25/2025 5:00 PM
Opened 03/25/2025 11:15 AM
Cashiered
Tag#
Location
PO #

License	Odom In	Odom Out	In Service Date	Stock No
4-A4377	193368	193370		20106B
Year Make	Model	Model Number	Color	
2012 FORD	EXPEDITION		BLACK	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FMJK2A52CEF52087			09/24/2020	
Engine				

Request	Description	Job	CSR	Status		
REPAIR	C/S vehicle is misfiring, cel is on, need checked out	1	E104	Original		
Labor	Description			Amount		
REPAIR	C/S vehicle is misfiring, cel is on, need checked out			756.00		
Part	Description	Shp	Bin	Retail	Price	Amount
7L1Z 6584 A	GASKET - VALVE ROCKER ARM COVE	1	41 -F	43.80	27.80	27.80
XW4Z 6700 AA	SEAL ASY - CRANKSHAFT OIL - FR	1	40 -C	18.18	15.46	15.46
3L3Z 6020 EA	GASKET	1	60 -A-1	19.50	19.50	19.50
3L3Z 6020 FA	GASKET	1	60 -A-1	13.42	13.42	13.42
3L3Z 6020 DA	GASKET	1	60 -A-1	14.08	10.08	10.08
7L1Z 6584 B	GASKET - VALVE ROCKER ARM COVE	1	41 -F	33.40	21.83	21.83
NPN	Tune	1		350.00	350.00	350.00
Rate	135.00					
Technician	E106 -					
Cause	check for signs of misfire...check fault codes.. P0015-P0017-(camshaft timing faults) P0300-P0316 (random misfire) P0301-P0302-P0304 (miss #1-#2-#4) drove vehicle monitored misfire data..no miss on test drive.checked condition of coil..been replaced.monitored VCT data...timing data is at max. end of scale... (cam phaser issue) Est. for repairs made.					
Correction	R&R timing chains, tensioners, guides , arms, lower gear, install block off's in phasers, replaced front crank seal, replaced front cover seals, replaced valve cover gaskets..reused coolant, , DID NOT change oil, as not required for this repair....install custom tune.					
NOTE: 1/2 off per Jud, from previous repair						
				Parts Total		458.09
				Labor Total		756.00
				Request Sub-total		1,214.09

Labor	756.00
Parts	458.09
Supplies	49.00
Sub-Total	1,263.09
Sales Tax	35.50
Total Invoice	1,298.59

THE NOMINAL CHARGE FOR SHOP SUPPLIES IS APPLIED TO EACH SERVICE INVOICE TO COVER 1) SHOP SUPPLIES AND 2) HANDLING AND DISPOSAL OF HAZARDOUS WASTE MATERIAL

DISCLAIMER OF WARRANTIES

Any warranties on the product said hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes not authorizes any person to assume for it any liability in connection with the sale of said products. ALL PARTS ARE NEW, ORIGINAL EQUIPMENT UNLESS OTHERWISE SPECIFIED.

TERMS

No returns on electrical or special order items. Restocking charge applied on all merchandise returned for credit or refund. No returns after 30 days or without this invoice.

CUSTOMER SIGNATURE: _____

DATE: _____