



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 1 of 10
--	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000018872 Retail

COMPLAINT:

01 Combine Annual Maintenance Program (Annual Service)

CORRECTION:

Replace all filters.
 Drain;
 Engine oil.
 Service Reverser gearcase.
 Refilled to specifications.
 Added coolant
 Insure that all fluids are at specified levels.
 Remove and clean cab pre-filter.
 Grease all lubrication points on combine.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH128449	HYD FILTER	2.00	83.79	83.79	\$167.58	N
AN207368	HYDRO PUMP FILTER	1.00	110.88	110.88	\$110.88	N
AT129775	FILTER	1.00	119.63	119.63	\$119.63	N
AXE42065	Air Filter	1.00	84.14	84.14	\$84.14	N
AXE42066	Air Filter Debris	1.00	138.29	138.29	\$138.29	N
DZ112918	Fuel Filter	1.00	134.25	134.25	\$134.25	N
HXE11090	AIR FILTER	1.00	262.78	262.78	\$262.78	N
HXE11091	Air Filter	1.00	185.41	185.41	\$185.41	N
L214634	RECIRC FILTER	1.00	27.47	27.47	\$27.47	N
R502778	FUEL STRAINER	1.00	29.38	29.38	\$29.38	N
RE284091	CAB FILTER	1.00	73.43	73.43	\$73.43	N
RE509672	OIL FILTER	1.00	27.81	27.81	\$27.81	N
RE539465	Fuel Filter	1.00	106.81	106.81	\$106.81	N
TY25744	SYNTHETIC GREASE	2.00	18.28	18.28	\$36.56	N
TY26101	BRAKE & PARTS CLEANER	1.00	8.15	8.15	\$8.15	Y

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 2 of 10
--	---	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000018872 Retail

TY26372	80W140 SYNTHETIC QT	2.00	29.78	29.78	\$59.56	N
TY26408	SYNTHETIC HD460 OIL	5.00	39.14	39.14	\$195.70	N
TY26576	2.5 GAL PRE-MIX COOLANT	1.00	46.10	46.10	\$46.10	N
TY26632	ELECTRONIC CONTACT CLEANER	1.00	10.36	10.36	\$10.36	Y
TY26682	Plus-50 II Oil 15W40 CJ4/SN	8.00	22.71	22.71	\$181.68	N
TY6354	HY-GARD GALLON	1.00	27.44	27.44	\$27.44	N

Labor: \$815.10 Parts: \$2,033.41 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$2,848.51

EXPERT-1000000015285 Retail

COMPLAINT:

02 Feederhouse Conveyor Drive Chain, Remove and Replace

CORRECTION:

Remove cap screws, side shields, and deflectors.

Remove and replace drive chain.

Adjust chain and assemble in reverse order.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE80368	FEEDER DR CHAIN 60H	1.00	160.99	160.99	\$160.99	N

Labor: \$120.41 Parts: \$160.99 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$281.40

EXPERT-1000000022616 Retail

COMPLAINT:

03 Feederhouse Conveyor Chain Link, Remove

CORRECTION:

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 3 of 10
--	---	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000022616 Retail

Release chain tension.
Remove master chain link.
Remove half link.
Reinstall master chain link.
Adjust chain tension to specifications.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AH220541	CONN LINK CA557	4.00	12.82	12.82	\$51.28	N
Labor: \$314.93		Parts: \$51.28	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$366.21	

EXPERT-1000000031029 Retail

COMPLAINT:
04 Feederhouse Drive Chain Guides, Remove and Replace

CORRECTION:
Opened up top cover on the feeder house
Replace upper bar wear strips.
Reinstall chain and set to correct tension.
Reinstall shield.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
H171960	WEAR STRIP	4.00	22.63	22.63	\$90.52	N
Labor: \$240.83		Parts: \$90.52	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$331.35	

EXPERT-1000000042889 Retail

COMPLAINT:
05 Clean Grain Auger Bearing, Remove and Replace

CORRECTION:

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 4 of 10
--	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000042889 Retail

Remove locking tone wheel in opposite direction of shaft rotation. Removed bearing from bearing keeper.
 Remove bearing cover and bearing block.
 Remove and replace clean auger bearing.
 Assemble in reverse order.
 Changed out both auger bearings on the clean grain

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH133191	LOCK COLLAR 35	1.00	16.93	16.93	\$16.93	N
H152940	FLANGETTE GASKET	1.00	2.82	2.82	\$2.82	N
JD39102	BALL BEARING 25M	1.00	22.18	22.18	\$22.18	N
JD39104	BALL BEARING 35M	1.00	43.04	43.04	\$43.04	N
Labor: \$185.25		Parts: \$84.97	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$270.22	

EXPERT-1000000015325 Retail

COMPLAINT:

06 Lower Tailings Auger Bearings, Remove and Replace

CORRECTION:

Remove bearing cover.
 Relieve tension on chain.
 Remove tension bracket.
 Remove locking collar.
 Remove and replace tailings auger bearing.
 Assemble in reverse order.
 changed out both bearings the tailings

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
JD10384	BEARING 30M	1.00	49.58	49.58	\$49.58	N
JD39102	BALL BEARING 25M	1.00	22.18	22.18	\$22.18	N
Labor: \$463.13		Parts: \$71.76	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$534.89	

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 5 of 10
--	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000037845 Retail

COMPLAINT:

07 Upper Feederhouse Drive Belt, (Front End Drive) (W/ 5 Speed), Remove and Replace Remove lower drive belt.
 Remove upper drive belt.
 Replace upper drive belt.
 Reinstall lower drive belt.
 Adjust tension on both.
 Check operation.

CORRECTION:

Pulled the panels off to get the lower end of the belt. Remove lower drive belt. Removed the bracket to the feeder house drive pulley. Used the come along and pulled up the tensor to the upper belt. Took off the bracket to the reel pump. Remove upper drive belt. Felt and heard a bad bearing on the feeder house drive pulley. Took the snap ring off the end of the shaft and pulled the pulley off and took it to the work bench. the bearing on the inner side was bad. Ordered bearings. Removed the snap ring off the bearings and hammered them out. Cleaned up the pulley. Cleaned up the shaft. Got the new bearing and pressed them in place and installed the snap ring to hold them in place. Installed the pulley back on and installed the out snap ring to hold it in place. Replace upper drive belt. Put the brackets back on. Reinstall lower drive belt. Adjust tension on both. put the panels back on the back side. TM
 Check operation.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H229018	V-BELT	1.00	384.18	384.18	\$384.18	N
JD10018	BALL BEARING 6310ZZ	2.00	36.40	36.40	\$72.80	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
PT3750	FREIGHT JD - PARTS GOTH	1.00	42.00	42.00	\$42.00	N
Labor: \$355.68		Parts: \$456.98	OL&M: \$0.00	Misc: \$42.00	Sub-Total: \$854.66	

EXPERT-1000000019143 Retail

COMPLAINT:

08 Chopper Stationary Knife Blades / Replace ROTATE KNIFE BLADES ON STATIONARY KNIFE BANK

CORRECTION:

replaced all stationary knife blades.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H206215	SHAFT	1.00	85.23	85.23	\$85.23	N

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 6 of 10
--	---	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000019143 Retail

H215004	STATIONARY KNIFE	39.00	8.87	8.87	\$345.93	N
---------	------------------	-------	------	------	----------	---

Labor: \$277.88	Parts: \$431.16	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$709.04
------------------------	------------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000015267 Retail

COMPLAINT:

09 Unloading Auger Drive Chain, Remove and Replace

CORRECTION:

Remove chain tension from chain.

Remove connector link from chain.

Remove chain from sprockets.

Install new chain and tighten chain to specification.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE53952	UNLOADING CHAIN	1.00	258.78	258.78	\$258.78	N
Labor: \$240.83	Parts: \$258.78	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$499.61		

EXPERT-1000000024934 Retail

COMPLAINT:

10 Unloading Auger Drive Chain Tensioner Bushing, Replace

CORRECTION:

Loosen chain tension

Remove bushing

Install bushing and tension chain to spec

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE28341	Sprocket	1.00	88.49	88.49	\$88.49	N

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 7 of 10
--	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000024934 Retail

HXE25995	Spacer	1.00	7.03	7.03	\$7.03	N
----------	--------	------	------	------	--------	---

Labor: \$92.63	Parts: \$95.52	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$188.15
-----------------------	-----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000042666 Retail

COMPLAINT:

11 Rotary Screen Drive Belt, Pulley and Idlers, Remove and Replace

CORRECTION:

Remove belt from screen.
 Remove all pulleys one per time and replace all.
 Install new belt on screen and pulleys.

When running machine, was having issue with the moisture sensor auger. Found it did not want to work. Ended up putting a new motor on it and bolting everything back up. Cleared all codes and did a calibration on the TCR. Hooked up machine to the corn head and ran.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH140497	IDLER PULLEY	1.00	33.77	33.77	\$33.77	N
AXE13658	AUGER MOTOR SENSOR	1.00	318.90	318.90	\$318.90	N
H221273	ROTARY SCREEN BELT	1.00	46.54	46.54	\$46.54	N
Labor: \$602.06		Parts: \$399.21	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$1,001.27	

EXPERT-1000000015260 Retail

COMPLAINT:

12 Clean Grain Elevator Drive Belt, Remove and Replace

CORRECTION:

Loosen tensioner nut and relieve tension on belt.
 Raise right-hand door.
 Remove clean grain elevator belt cover cap screws and cover.
 Remove and replace clean grain elevator drive belt.
 Assemble in reverse order.

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 8 of 10
--	---	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000015260 Retail

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H223230	CL GR ELV BELT	1.00	270.92	270.92	\$270.92	N
Labor: \$463.13		Parts: \$270.92	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$734.05	

EXPERT-1000000048622 Retail

COMPLAINT:

13 Cleaning Shoe Return Pans, Remove and Replace

CORRECTION:

Remove and replace shake pan out of rear of machine.
Assemble in reverse order.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE83661	Return Pan	2.00	128.13	128.13	\$256.26	N
Labor: \$231.56		Parts: \$256.26	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$487.82	

EXPERT-1000000031286 Retail

COMPLAINT:

14 Software / Controllers, Update

CORRECTION:

Update all control units to the latest software version.

Labor: \$0.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

EXPERT-1000000020595 Retail

COMPLAINT:

15 Adjust All Chains and Belts / S-Series, X-Series MISSING 3 LATCH PINS

CORRECTION:

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 9 of 10
--	---	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000020595 Retail

Adjust all chains and belts, does not include chain repairs

Labor: \$463.13	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$463.13
------------------------	----------------------	-------------------------	---------------------	----------------------------

EXPERT-1000000045809 Retail

COMPLAINT:

16 Rotary Screen Outer Drive Belt Idler Pulley, Remove and Replace

CORRECTION:

Remove and replace pulley.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH140497	IDLER PULLEY	1.00	33.77	33.77	\$33.77	N
AH169549	IDLER PULLEY	1.00	42.10	42.10	\$42.10	N
HXE68016	V-BELT	1.00	21.28	21.28	\$21.28	N
M72598	Lynch Pin 5/32	4.00	2.21	2.21	\$8.84	N
TY22028	HY-GARD BULK	2.00	19.28	19.28	\$38.56	N
Labor: \$92.63	Parts: \$144.55	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$237.18		

EXPERT-1000000020905 Retail

COMPLAINT:

17 Powercast Spreader Shrouds, Remove and Replace REPLACE SPREADER GUIDES

CORRECTION:

Remove and replace shrouds. used new hardware due to the head of the bolts being gone.
Assemble in reverse order.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H225020	SHROUD	1.00	99.84	99.84	\$99.84	N
H225021	SHROUD	1.00	100.77	100.77	\$100.77	N

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No: 71224

Deliver To:

SERVICE INVOICE

COYOTE CANYON FARMS, INC. DAN KOTSCHWAR DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 Bus Phone: (308)569-2510 Prv Phone:	Invoice Number: 11620869 Invoice Date: 11/28/2023 Location: 06 Work Order Number: 487109 Payment Type: Finance Page: 10 of 10
--	---	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE S770	1241	1H0S770SCJ0800435	DK800435	

EXPERT-1000000020905 Retail

H225022	SHROUD	1.00	99.84	99.84	\$99.84	N
H225023	SHROUD	1.00	95.55	95.55	\$95.55	N
Labor: \$138.94		Parts: \$396.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$534.94	

Finance Information

Customer PO No:

Tax Exempt No: ON FILE NE

Advisor: KASH HOUSER

Type: Multi-use Acct US

Auth. No: 300922

Merchant No: 48000202

Card No: xxxxxxxxxxxx5967

Bill Code: 705 - JD COMBINE PARTS/SERVICE

Credit Plan: 11172 - 180 DAYS NO PAYMENTS/NO INTEREST

Labor: \$5,098.12

Parts: \$5,202.31

OL&M: \$0.00

Misc: \$42.00

Sales Tax: \$1.30

Grand Total: \$10,343.73

*** DOCUMENT COPY ***

LANDMARK
IMPLEMENT

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:Date: