

COLLINS AUTOMOTIVE LLC.
204 SOUTH MERIDIAN
Cozad, NE. 69130
Phone: 308-784-4442 Fax: 308-784-4421
www.collinsautomotive LLC.com

INVOICE

23775

Org. Est. # 025342
ASE MASTER TECHNICIAN
Visit Us Online

Invoice from History

Printed Date: 08/18/2025

Work Completed: 10/14/2024

MID NEBRASKA DOCKS & LIFTS - LANE ZIMBELMAN

2215 CENTRAL AVE.
Kearney, NE 68847
Cellular 308-325-2759

1989 Ford - Pickup F250 - 5.8L, V8 (351CI) VIN(H)

Lic # :

Odometer In : 129244

Odometer Out : 129244

VIN # : 1FTHX26H2 KKB49945

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext
CLEANER CLNR		1.00	8.84	8.84	CENTER LINK - Remove & Replace - 4WD - [Includes: Adjust toe-in.] - [DOES NOT include alignment (unless noted otherwise).]	154.00
Ball Joint - Front Upper 10339		2.00	58.61	117.22	DRAG LINK - Remove & Replace	182.00
Ball Joint - Front Lower 10253		2.00	45.43	90.86	TIE ROD &/OR END - Remove & Replace - Both - [Includes: Adjust toe-in only. NOTE: Deduct .4 if alignment is also performed.	182.00
Tie Rod End - Outer ES2728L		1.00	51.22	51.22	NOTE: Manufacturer recommends removal of Rack and Pinion Steering Gear when replacing Inner Tie Rod End(s) on some models. If remov	
Tie Rod End - Outer ES2727R		1.00	54.93	54.93	BALL JOINT - Remove & Replace - F150,F250,4WD Stamped Axle,Left,Upper & Lower - [DOES NOT include alignment.]	448.00
Steering Drag Link DS1069		1.00	139.67	139.67	BALL JOINT - Remove & Replace - F150,F250,4WD Stamped Axle,Right Side,Upper & Lower - [DOES NOT include alignment.]	476.00
Tie Rod End - Inner DS1072		1.00	76.32	76.32	CRANKSHAFT MAIN OIL SEAL - Remove & Replace - 4WD,V8,Gas Rear,One Piece Design (Circular Type),351 "W" (5.8L) Eng - [NOTE 1: Upper Rope Type Seal includes pack and add only. Split lip type Seals include replacing top and bottom halves. If it is necessary	798.00
SYNTHETIC BLEND MOTOR OIL 5-30		6.00	5.66	33.96	Hazardous Materials	9.00
Rear Main Seal Kit BS40645		1.00	50.25	50.25		
NAPA PROFORMER Oil Filter 21515MP		1.00	7.43	7.43		
Shop Supplies				28.38		

Org. Estimate 2,053.75 Revisions 913.13 Current Estimate 2,966.88

Revision # 1, Previous Estimate Amount: 2053.75, Additional Cost: 913.13, Revised Estimate: 2966.88, Parts: \$91.69 Labor: \$798.00 Sublet: \$0.00 Taxes & Fees: \$23.44 Authorized by - ZIMBELMAN, LANE, Date - 10/7/2024, Time - 3:54 PM, Initiated By - Shop, Written By - ZIEBELL, SARAH, Phone Number - Cellular: 308-325-2759

[Payments -]

Labor:	2,240.00
Parts:	659.13
HazMat:	9.00
SubTotal:	2,908.13
Tax:	46.14
Total:	2,954.27
Bal Due:	\$2,954.27

Vehicle Received: 10/14/2024

Customer Number : 3718

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. VEHICLES LEFT OVER 10 DAYS AFTER COMPLETION ARE SUBJECT TO A \$10.00/DAY STORAGE FEE.

Signature _____ Date _____

Visit us on the web: www.collinsautomotive LLC.com

Email Address: collinsautomotivebilling@cozadtel.net

Service Advisor : ZIEBELL, SARAH, Tech : VASQUEZ, GERARDO 1; COLLINS, ANDREW