

Landmark Implement Inc.

P.O. Box 11 73049 L Road Holdrege, NE 68949 Phone: 308-995-6511 Fax: 308-995-5475 www.landmarkimp.com

Holdrege@landmarkimp.com



Invoice To Account No: 715 SERVICE INVOICE Deliver To: JEROME FRITZ JEROME FRITZ Invoice Number: 10808395 473 S RD 473 S RD Invoice Date: 12/27/2019 HILDRETH NE 68947 HILDRETH NE 68947 Location: 01 Work Order Number: 327292 Payment Type: Finance Bus Phone: 308-938-5296 Bus Phone: (308)938-5296 Prv Phone: (308)991-5549 Prv Phone: (308)991-5549 Page: 1 of 2

Make/Model:	Meter:	Serial Number:	Eq ID;	Fleet No:
JOHN DEERE 250	2197	KV0250A150950	JF150950	

/DIA Retail
CORRECTION:

BOOM WON'T RAISE AND SERVICE

REPLACED ENGINE OIL AND FILTER. BLEW OUT FILTERS.

REMOVED FAN SHROUD TO GET TO HOSE GOING TO OIL COOLER. REPLACED LEAKING HOSE. REINSTALLED FAN SHROUD. FILLED COOLANT.

REMOVED FRONT SHIELDS.
FOUND SEVERAL WIRES THAT WERE CHEWED UP.
REPAIRED ALL WIRING.
INSERTED HARNESS INTO SLEEVE TO HELP KEEP MICE OUT.
REINSTALLED SHIELDS.

CHECKED BUCKET TILT AND FOUND RIGHT HAND CYLINDER WAS BAD.
TRIED TO DISASSEMBLE CYLINDER TO BE REBUILT. -CYLINDER COULD NOT BE DISASSEMBLED.
ORDERED NEW COMPLETE CYLINDER.
INSTALLED NEW CYLINDER.
BLED SYSTEM.
TOPPED OFF ALL FLUIDS.
GREASED ALL ZERKS.
TESTED OPERATION.

Part Number AH212126	<u>Description</u> HYDRAULIC CYLINDER	Quantity 1.00	<u>List Price</u> 1,072,70	<u>Net Price</u> 1,072,70	Extended Price \$1,072,70	Taxed Ind
R70438	HOSE	2.00	12.93	12.93	\$25,86	N
T19044	OIL FILTER	1.00	6.25	6.25	\$6.25	N.
TY22028	HY-GARD TM	3.00	13.88	13.88	\$41.64	N
TY26190	CONDUIT, 3/4" SLIT LOOM	4.00	1.09	1.09	\$4.36	N
TY26577	COOL-GARD TM	5.00	12.00	12.00	\$60.00	N
TY26682	Plus-50 II Oil 15W40 CJ4/SN	3.00	15.00	15.00	\$45.00	N
Miscellaneous PT3750	Description FREIGHT JD - PARTS HOLD	Quantity 1.00	<u>List Price</u> 120.00	<u>Net Price</u> 120.00	Extended Price \$120.00	Taxed Ind N