

#284339

2021 Sportsman 570

Red

TMC POWERSPORTS
704 WEST HWY 20
VALENTINE, NE 69201
Phone: (402) 376-1661

Repair Order

Internal Invoice

Doc Number: 31181

Service Writer: Brandi Jarrett

Date Printed: 04/17/2025

Date Promised: 07/31/2024

Cashier: Brandi Jarrett

Cashier Date: 08/07/2024

JD 475

Customer Information

Unit

2021 Polaris A21SEE57A7 SPORTSMAN 570
EPS - INDY RED

Color: Indy Red

Keyboard:

VIN/Serial No: 4XASEE573MA284339

Stock #: 284339

Odom/Hrs: 5,032

SERVICE & CHECKLIST

Description:

Resolution: Locate keys, push unit in, jump start, charge test battery, would partially charge and kick charger off, replace battery, check for draw, test run, check over fluids.

Parts

Part #	Qty	Description	Price	Discount	Total
4017419	1.00	BATTERY-U1	\$129.99	\$0.00	\$129.99
Parts Subtotal					\$129.99

Labor

Description	Technician	Hours	Total
	Jake Thornton	1.75	\$192.50
Labor Subtotal			\$192.50

Job Subtotal \$322.49

Approve: ☒ Decline: ☐

All Jobs Subtotal: \$322.49

Tax: \$0.00

Total: \$0.00

Less Deposits: \$0.00

Total Due: \$0.00

Customer Repaired
450480

TMC POWERSPORTS
704 WEST HWY 20
VALENTINE, NE 69201
Phone: (402) 376-1661

Repair Order

Internal Invoice

Doc Number: 30015
Service Writer: Brandi Jarrett
Date Printed: 04/17/2025
Date Promised: 07/31/2023
Cashier: Brandi Jarrett
Cashier Date: 07/31/2023

Customer Information

Fold Here

Unit

2021 Polaris A21SEE57A7 SPORTSMAN 570
EPS - INDY RED

Color: Indy Red

Keyboard:

VIN/Serial No: 4XASEE573MA284339

Stock #: 284339

Odom/Hrs: 0

Service & checklist

Description:

Resolution: Complete service and check over, remove front diff. Complete tear down clean, replace ring and pinion gears had excessive play on pinion bearing and was leaking oil

Parts

Part #	Qty	Description	Price	Discount	Total
3235638	1.00	HOUSING AND PINION CLUTCH	\$1,059.99	\$0.00	\$1,059.99
7661913	1.00	PIN, SPRING(10)	\$2.99	\$0.00	\$2.99
AGLB	1.00	AGL GEARCASE OL	\$14.99	\$0.00	\$14.99
7082101	1.00	FILTER-AIR INTA	\$34.99	\$0.00	\$34.99
3236669	1.00	KIT-REPAIR, SEAL	\$84.99	\$0.00	\$84.99
PS4B	2.00	PS-4 BULK OIL	\$10.99	\$0.00	\$21.98
2520799	1.00	FILTER-OIL, 10 M	\$14.99	\$0.00	\$14.99
2877922	0.50	DEMAND DRIVE PL	\$19.99	\$0.00	\$10.00

Parts Subtotal \$1,244.92

Labor

Description	Technician	Hours	Total
	Jake Thornton	4.5	\$495.00

Labor Subtotal \$495.00

Job Subtotal \$1,739.92

Approve: ☒ Decline: ☐

All Jobs Subtotal: \$1,739.92

Tax: \$0.00

Total: \$0.00

Less Deposits: \$0.00

Total Due: \$0.00

TMC POWERSPORTS
704 WEST HWY 20
VALENTINE, NE 69201
Phone: (402) 376-1661

Repair Order

Internal Invoice

Doc Number: 31181
Service Writer: Brandi Jarrett
Date Printed: 04/17/2025
Date Promised: 07/31/2024
Cashier: Brandi Jarrett
Cashier Date: 08/07/2024

Customer Information

Fold Here

Unit 2021 Polaris A21SEE57A7 SPORTSMAN 570 **Color:**Indy Red **Keyboard:**
EPS - INDY RED
VIN/Serial No:4XASEE573MA284339 **Stock #:**284339 **Odom/Hrs:**5,032

SERVICE & CHECKLIST

Description:

Resolution: Locate keys, push unit in , jump start, charge test battery,would partially charge and kick charger off, replace battery, check for draw, test run , check over fluids,

Parts

Part #	Qty	Description	Price	Discount	Total
4017419	1.00	BATTERY-U1	\$129.99	\$0.00	\$129.99
Parts Subtotal					\$129.99

Labor

Description	Technician	Hours	Total
	Jake Thornton	1.75	\$192.50
Labor Subtotal			\$192.50

Job Subtotal \$322.49

Approve: ☒ **Decline:** ☐

All Jobs Subtotal: \$322.49
Tax: \$0.00
Total: \$0.00
Less Deposits: \$0.00
Total Due: \$0.00

TMC POWERSPORTS
704 WEST HWY 20
VALENTINE, NE 69201
Phone: (402) 376-1661

Repair Order

Internal Invoice

Doc Number: 30015
Service Writer: Brandi Jarrett
Date Printed: 04/17/2025
Date Promised: 07/31/2023
Cashier: Brandi Jarrett
Cashier Date: 07/31/2023

Customer Information

Fold Here

Unit

2021 Polaris A21SEE57A7 SPORTSMAN 570
EPS - INDY RED

Color:Indy Red

Keyboard:

VIN/Serial No:4XASEE573MA284339

Stock #:284339

Odom/Hrs:0

Service & checklist

Description:

Resolution: Complete service and check over, remove front diff. Complete tear down clean, replace ring and pinion gears had excessive play on pinion bearing and was leaking oil

Parts

Part #	Qty	Description	Price	Discount	Total
3235638	1.00	HOUSING AND PINION CLUTCH	\$1,059.99	\$0.00	\$1,059.99
7661913	1.00	PIN,SPRING(10)	\$2.99	\$0.00	\$2.99
AGLB	1.00	AGL GEARCASE OL	\$14.99	\$0.00	\$14.99
7082101	1.00	FILTER-AIR INTA	\$34.99	\$0.00	\$34.99
3236669	1.00	KIT-REPAIR,SEAL	\$84.99	\$0.00	\$84.99
PS4B	2.00	PS-4 BULK OIL	\$10.99	\$0.00	\$21.98
2520799	1.00	FILTER-OIL,10 M	\$14.99	\$0.00	\$14.99
2877922	0.50	DEMAND DRIVE PL	\$19.99	\$0.00	\$10.00
Parts Subtotal					\$1,244.92

Labor

Description	Technician	Hours	Total
	Jake Thornton	4.5	\$495.00

Labor Subtotal \$495.00

Job Subtotal \$1,739.92

Approve: ☒ Decline: ☐

All Jobs Subtotal: \$1,739.92

Tax: \$0.00

Total: \$0.00

Less Deposits: \$0.00

Total Due: \$0.00