Serial Number: JJC0256318

Build Date: 17/Jul/2003

X Tec

Technical Type

510401000

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1469341 CL

Closed Date: 12/1/2022

Ship To: 34699

TITAN MACHINERY

Sold To:

Invoice #: Sold by:

1469341 CL

CHRIS KLUTHE

Cust PO: Cust Fleet#:

Job Desc:

**UPTIME INSPECTION** 

Make:

Model:

2366

Serial #: Tag:

JJC256318 6835628

CASE IH

Hours:

3931,0

**Service Order Summary** 

WO#

2593974 SV UPTIME INSPECTION (BM)

\$499.00

	TOTAL INVOICE	499.00
	Payment Information	
	CREDIT CARD	\$499.00
	Trans ID: 01Z6KJIFE500P7F9KESBSPS69A91KG0S	
×	Client ID: 3218739003 Store ID: 1420115001	
Customer Signature	Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264	
Phone: 308-728-5220 Cell Phone:	By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement applicable to this Account.	

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to sald machinery from fire, theft, or other causes beyond your control. A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

WO#: 2593974 SV UPTIME INSPECTION (BM)

#### Comments:

Started by removing shields to inspect Removed head and start inspect combine

Inspected combine

Finished inspection look up parts

Finished looking up parts and took to parts for pricing and availability Went over combine with customer

## Labor:

Description Amount \$499.00
Uptime Inspection \$499.00
Total Labor \$499.00

Parts:

Qty Vendor Part Number Description Bin Price Ext. Price

**Total Parts** 

Tax . Total WO \$499.00 Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1469341 CL

Closed Date: 12/1/2022

Ship To:

34699

**TITAN MACHINERY** 

Invoice #:

Sold To:

1469341 CL

Make:

CASE IH

Sold by:

**BENJAMIN MORSE** 

Model:

2366

Cust PO:

TO WITH MICHOL

Serial #:

JJC256318 6835628

Cust Fleet#: Job Desc:

**UPTIME INSPECTION** 

Tag: Hours:

3931.0

Service Order Summary

#### **WO#**

2597785 SV	TAILINGS (RD)	\$0.00
2597786 SV	CLEAN GRAIN (RD)	\$1,398.88
2597787 SV	SPREADER (RD)	\$394.67
2597789 SV	ROTOR (RD)	\$356.63
2597790 SV	FEEDER (RD)	\$1,914.06
2597791 SV	SERVICE (RD)	\$1,356.47
	, , ,	

## **TOTAL INVOICE**

\$5,420.71

#### **Payment Information**

\$5420.71

CNH PROMO 0301 \$1500 minimum with no payment,

no interest for 90 days 7528

Trans ID: 01Z6KJIFFL00P7F9KF8D8V1NSGG380A9

Client ID: 3218739003 Store ID: 1420115001

Customer Signature

Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement

applicable to this Account.

Phone: 308-728-5220

Cell Phone:

Regular purchase APR applies after the end of the promotional period. See Account Agreement for details.

hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control.

A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

WO#: 2597785 SV TAILINGS (RD)

Comments:

Labor:

Description

**Total Labor** 

Parts:

**Qty Vendor Part Number** 

Description

Bin

Price

Ext. Price

**Amount** 

**Total Parts** 

Tax

\$0.00

**Total WO** 

\$0.00

WO#: 2597786 SV CLEAN GRAIN (RD)

#### Comments:

Removed outside sprocket bearings, shaft and inside sprocket from clean grain elevator head. installed new bearings.

Installed shaft sprocket and bearings in upper clean grain then installed elevator chain, and installed elevator drive chains

#### Labor:

<b>Description</b> Labor		Amount \$755.20
Shop Supplies		\$56.64
	Total Labor	\$811.84

<u>Parts</u>						
Qty	Vendor	Part Number	Description	Bin	Price	Ext. Price
2.00	CAS	47508396	COLLAR BEARING LOCK	EW-3	\$11.25	\$22.50
1.00	CAS	1317429C1	SHAFT	14-B	\$56.00	\$56,00
6.00	CAS	87613234	WASHER	C2-8	\$2.45	\$14.70
2.00	CAS	88907	WOODRUFF KEY	C2-1	\$5.85	\$11.70
1.00	CAS	1317192C1	SPROCKET	14-B	\$119.00	\$119.00
2.00	CAS	1317193C2	SPACER		\$36.75	\$73.50
2.00	CAS	47577196	BEARING, BAL	EW-3	\$32.75	\$65.50
4.00	CAS	581469R1	FLANGE	15-A	\$6.40	\$25.60
155.0 0	CAS	1791DIN	50 CHAIN PER INCH	17-A	\$0.72	\$111.60
1.00	CAS	87034815	LINK CONN.	17-A	\$1.75	\$1,75
1.00	CAS	241-15113	LINK	17-A	\$8.25	\$8.25
102.0 0	CAS	1791DIN	50 CHAIN PER INCH	17-A	\$0.72	\$73.44
2.00	CAS	87034815	LINK CONN.	17-A	\$1.75	\$3.50
				Total Parts		\$587.04
				Tax		\$0.00
				Total WO		\$1,398.88

WO#: 2597787 SV SPREADER (RD)

## Comments:

Removed right hand vertical shaft, gear and bearings and reinstalled new bearings. Reinstalled shaft, gear and roll pin

<b>Description</b> Labor		Amount \$269.93
Shop Supplies		\$20.24
	Total Labor	\$290.17

Parts:

	4					
<b>Qty</b> 4.00 2.00	Vendor CAS CAS	Part Number 86603075 47508387	<b>Description</b> FLANGETTE-AC HEX BEARING	Bin LT1C EW-3	Price \$5.25 \$41.75	Ext. Price \$21.00 \$83.50
2,00	UAG	47000007	HEA DEANING	EVV-0	Ф41.70	φου.ου
				Total Parts		\$104.50
				Tax		\$0.00
				Total WO		\$394,67

WO#: 2597789 SV ROTOR (RD)

#### Comments:

Installed limit switch ran combine and adjusted rotor speed

#### Labor:

Description		Amount
Labor		\$295.00
Shop Supplies		\$22.13
	Total Labor	\$317.13

Parts:

Qty 1.00	Vendor Part CAS 12829	<b>Description</b> SWITCH	<b>Bin</b> 11-B	<b>Price</b> \$39.50	<b>Ext. Price</b> \$39.50
			Total Parts		\$39.50
			Tax		\$0.00
			Total WO		\$356.63

WO#: 2597790 SV FEEDER (RD)

#### Comments:

Removed belt shield,

Removed feeder jackshaft belt and removed bent jackshaft tensioner rod, spring and bushing,

Removed teflon bushing from pivot housing cleaned up and installed new bushings

Installed block in feeder for stop for drum

Installed tensioner rod on feeder jackshaft reinstalled belt shields

Ran combine and adjusted tension rod with window

#### Labor:

<b>Description</b> Labor		Amount \$1,264.08
Shop Supplies		\$75.84
	Total Labor	\$1,339.92

Parts:

. w	<del></del>			_		
Qtv	Vendor Part Num	ber Description	Bin	,	Price	Ext. Price
1.00	CAS 194216C3	ROD			\$79.50	\$79.50
2.00	CAS 1302308C1		C4-1		\$16.50	\$33.00
1.00	CAS 185414C2	SUPPORT			\$280.00	\$280.00

1.00 1.00 1.00 1.00	CAS CAS IMP IMP	PO23 182921A1 ZB1/4 ZB3/16	SPRING TUBE 1/4 COTTER KEY 3/16 COTTER KEY	32-A 32-A	\$49.25 \$132.00 \$0.29 \$0.10	\$49,25 \$132.00 \$0,29 \$0,10
				Total Par	ts	\$574.14
ATTACK ACCOUNTS OF THE PARTY OF THE PARTY.				T Total W	ax /O	\$0.00 \$1,914.06

WO#: 2597791 SV SERVICE (RD)

## Comments:

Installed new fuel and water filters, Adjusted cylinder on auger swing to keep auger in saddle, Fixed connection on front left hazard light, Installed new bulb in back right work light,

Pulled back tin work on right rear hazard light are and rebolted to hold in place. Removed concave support and cut out worn metal and cut metal to replace worn area. Dissasembled guides gathring chains and sprockets, clean up and reassemble with new parts

Greased combine Drove combine to storage out of town

Lapo	<u>r:</u>					
	<b>Descript</b> i Labor	ion				Amount \$1,281.78
				Total Labo	or .	\$1,281.78
<u>Parts</u>	u.					
Qty	Vendor Part N	lumber	Description	Bin	Price	Ext. Price
1.00	CAS 845570	99	PKG-FILTER.	F-4-B	\$17.48	\$17.48
1.00	CAS FS1212	2	SEPARATOR	F-6-B	\$23.83	\$23.83
1.00	CAS 846050	17	COOLANT FILTER/CONDITIONER	F-4-C	\$20.58	\$20.58
1.00	CAS 110225	8	BULB	C3-4	\$7.85	\$7.85
1.00	CAS 733443	349	GREASE	F-11	\$4.95	\$4.95
				Total Part	s	\$74.69
				Та	x	\$0.00
				Total W	0	\$1,356.47

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1353462 CL

Closed Date: 1/5/2022

Ship To:

34699

TITAN MACHINERY

Sold To:

Invoice #: Sold by:

1353462 CL

CHRIS KLUTHE

**Cust PO:** Cust Fleet#:

Job Desc:

UPTIME INSPECTION

Make:

Model:

Serial #:

Tag: Hours: 2366 JJC256318

CASE IH

6835628 3762.0

#### Service Order Summary

WA II		*
WO #		
2351612 SV	UPTIME INSPECTION	\$502.95
2367546 SV	FEEDER HOUSE	\$4,242.77
2367547 SV	AUGER BED	\$1,879.19
2367550 SV	CLEAN GRAIN	\$741.85
2367551 SV	ROTOR	\$2,139.18
2367555 SV	CHOPPER	\$511.58
2367556 SV	SPREADER	\$172.45
2367557 SV	STEERING	\$579.00
2367559 SV	ROTARY SCREEN	\$295.22
2367561 SV	TOP SIEVE	\$2,132.99

#### TOTAL INVOICE

\$13,197.15

#### **Payment Information**

\$13197.15

CNH PROMO 0301 \$1500 minimum with no payment,

no interest for 90 days 7528

Trans ID: 01Z6JOC9G000P7AV1LICIN1LC71GJOF0

Client ID: 3218739003 Store ID: 1420115001

Customer Signature

Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement

applicable to this Account.

Phone: 308-728-5220

Cell Phone:

Regular purchase APR applies after the end of the promotional period. See Account Agreement for details.

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control. A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

## WO#: 2351612 SV UPTIME INSPECTION

#### Comments:

- -Blew combine off. (rd)
- -Inspected cornhead. (rd)
- -Look at head. (jl)
- -Removed cornhead, started inspection. (rd)
- -Inspect. (rd)
- -Help with inspection. (il)
- -Inspect, did inspection on Ipad, started looking up parts. (rd)
- -Look up parts on dealer portal. (rd)
- -Parts and labor estimate. (rd)
- -Called Larry, went over parts and labor. (rd)

#### Labor:

<b>Description</b> Uptime Inspection		Total Labor		Amount \$499.00 \$499.00
Parts: Qty Vendor Part Number 1.00 CAS 73344349	<b>Description</b> GREASE	<b>Bin</b> F-11	<b>Price</b> \$3.95	Ext. Price \$3.95
		Total Parts		\$3.95
		Tax Total WO		\$502.95

## WO#: 2367546 SV FEEDER HOUSE

#### Comments:

- -Turned combine around.
- -Removed header drive belt and shield.
- -Removed hyd lines and capped.
- -Removed front feeder shield.

(rd)

- -Removed feeder house with forklift.
- -Removed back hex drive shaft, sprockets and bearings.
- -Installed new bearings in housing.
- -Removed bottom seal plate that had worn and missing bolts.
- -Removed front drum.
- -Checked bearings and shaft.
- -Found bottom feeder plate wearing thru on top, which is the reason for bolts wearing off. (rd)
- -Torchrd bolts out of floor plate.

- -Loosened face plate, slid forward.
- -Removed bottom plate.

(rd)

- -Went to parts, picked up bottom plate, set in feederhouse. (rd)
- -Bolted bottom plate in.
- -Repositioned face plate and tightened in place.
- -Installed door seal to back of feeder house.
- -Put back shaft, sprockets and bearings in place. (rd)
- -Installed drum in feederhose then installed new feeder chain.
- -Adjusted feeder chain and belt.
- -With forklift, installed feeder house back onto combine.
- -Hooked up cylinder, shields and hyd lines to reverser. (rd)

## Labor:

	La	<b>escription</b> bor					<b>Amount</b> \$2,094.40
	Sh	op Supplies					\$157.08
					Total Labor		\$2,251.48
<u>Parts</u>	<u>:</u>						
Qty	Vendor	Part Number	Description	Bin		Price	Ext. Price
6.00	CAS	86511973	SCREW	C2-5		\$0.45	\$2.70
6.00	CAS	196922C1	NUT	C2-6		\$1.65	\$9.90
1.00	CAS	136438A1	CONVEY 60			\$725.00	\$725.00
2.00	CAS	47577178	BALL BRG	EW-3	9	\$73.25	\$146.50
2.00	CAS	1970248C2	SPROCKET	14-A		\$118.00	\$236.00
4.00	CAS	197643C1	SCREW	C2-4		\$4.30	\$17.20
1.00	CAS	1994217C2	SUPPORT			\$735.00	\$735.00
4.00	CAS	186852C1	NUT	C4-9		\$3.85	\$15.40
8.00	TTM	TTM477-73816	3/8 - 16 X 1IN SERRATED SLOTTE	C4-4		\$1.09	\$8.72
4.00	CAS	84193279	CARRIAGE,1/2-13X1.25	C2-4		\$2.40	\$9.60
10.00	CAS	86624125	SCREW	C4-4		\$1.45	\$14.50
18.00	IMP	44110	FLANGE NUT 3/8-16 SERR	C4-4		\$0.13	\$2.34
1.00	CAS	326-656	CSHH G8 PHC .375-16 X 3.50	7-B		\$2.70	\$2.70
1.00	CAS	314148R1	SPACER	C4-2		\$3.25	\$3.25
1.00	CAS	195202C1	SEAL	13-B		\$22.00	\$22.00
1.00	IMP	57110	LOCKNUT 3/8-16	C1-13		\$0.16	\$0.16
4.00	CAS	87327171	BOLT SERRATED 3/8 16 GR 8 ZND	C2-4		\$1.00	\$4.00
1.00	CAS	87299546	PTO PIN 5/16 IN	F-13		\$0.82	\$0.82
1.00	CAS	86990536	LENS, RESERVOIR	C5-5		\$29.00	\$29.00
1.00		FREIGHT	FRT ON LENS			\$6.50	\$6.50
					Total Parts		\$1,991.29
					Tax		\$0.00
***************************************					Total WO		\$4,242.77

WO#: 2367547 SV AUGER BED

#### Comments:

- -Removed 2 front blocks.
- -Removed roll pins behind drive gear and pulled augers out.
- -Removed cleanout plate under augers.

(rd)

-Installed 1 new auger and bearing.

Description

- -Found all roll pins and bearings wore.
- -Replaced bearings by loosening front block & sliding auger down to make room to get gear & bearing out.

-Installed new bearing and roll pin on old auger so gear would mesh.

(rd)

- -Installed right auger, bevel gear, and wooden block.
- -Set backlash on gears.

(rd)

#### Labor:

	abor hop Supplies		Total Labor		\$1,192.38 \$17.77 \$1,210.15
Parts Qty 2.00 2.00 4.00 6.00 12.00 1.00 1.00 4.00 4.00	 Part Number 193414C2 571424R1 47508387 44110 ZB7 1308541C1 1308541C1 87040910 MBN-28	Description BOARD FLANGE HEX BEARING FLANGE NUT 3/8-16 SERR GRD 5 CRG BOLT PER OZ AUGER AUGER PIN SLOTTED 1-3/4 N.R.WASHER	Bin 13-B 15-A EW-3 C4-4 7-A WHT WHT C1-9	Price \$29.75 \$4.10 \$37.50 \$0.13 \$0.45 \$214.00 \$214.00 \$3.10 \$1.19	Ext. Price \$59.50 \$8.20 \$150.00 \$0.78 \$5.40 \$214.00 \$214.00 \$12.40 \$4.76
			Total Parts		\$669.04
			Tax <sup>1</sup>		\$0.00

**Total WO** 

Amount

\$1,879.19

WO#: 2367550 SV CLEAN GRAIN

#### Comments:

- -Installed new idler sprockets on clean grain drive & return grain drive. (rd)
- -Removed half link & reconnected with new connector link & adjusted elevator chain.
- -Disconnected battery & cleaned up adjustment bracket on top off elevator & welded up. (rd)
- -Adjusted belt & drive chain tension on clean grain drive.
- -Adjusted return grain elevator chain & drive chain tension.

(ra)

- -Readjusted elevator drive belt & ran machine.
- -Adjusted gear on auger bed.

(rd)

#### Labor:

<b>Description</b> Labor		Amount \$642.60
	Total Labor	\$642.60

#### Parts:

<b>Qty</b> 3.00 1.00 1.00	Vendor CAS CAS CAS	Part Number 103244 241-15113 87302107	Description SPROCKET LINK IDLER SPROCKET 17T	<b>Bin</b> 10-B 17-A LT1E	\$	Price 522.00 \$8.25 525.00	<b>Ext. Price</b> \$66.00 \$8.25 \$25.00
				Total I	Parts		\$99.25
					Tax		\$0.00
****	······································	***************************************		Tota	I WO		\$741.85

WO#: 2367551 SV ROTOR

#### Comments:

- -Removed rotor adjustment by removing limit switch bracket, removing driveline & jam nut slid thrust bearings off. (rd)
- -Cleaned up adjustment side of pulley, worked to get to take grease. (rd)
- -Unbolted chopper gearbox, lifted up with comealong enough to get adjustable pulley hub off.
- -Cleaned up inside & put new oring in & reinstaled on shaft.
- -Reset gearbox in place and bolted.
- -Reinstalled jackshaft assembly with new thrust bearings. (rd)
- -Checked alignment on driver to driven pulley and tightened bolts.
- -Attached belt shield and reinstalled limit switches.

(rd)

- -Calibrated feeder house by driving on dock & going thru calibrations.
- -Started putting on shields.

Description

(rd)

#### Labor:

	FS	ino:				\$1,886.15
				Total Labo	or	\$1,886.15
<u>Parts</u>	<u>:</u>					
Qty	Vendor	Part Number	Description	Bin	Price	Ext. Price
2.00	CAS	87375653	GEAR	LT1E	\$28.00	\$56.00
1.00	CAS	ZRG017BRC	BRAKE AND PARTS CLNR 17 OZ.		\$5.00	\$5.00
2.00	CAS	278927A1	BEARING	EW-2	\$92.00	\$184.00
2.00	CAS	217408	O-RING	C1-5	\$4.00	\$8.00
				Total Part	S	\$253.00
				Та	<b>X</b> .	\$0.00
				Total Wo	0	\$2,139.15

**Amount** 

WO#: 2367555 SV CHOPPER

#### Comments:

- -Removed broken blades & blade on opposite side.
- -Installed new blades and torqued.

(rd)

- -Removed stationary knife bracket & removed broken knives.
- -Had wrong knives, went to parts and ordered.

(rd)

-Installed stationary knives on bracket.

-Reinstalled bracket in combine.

(rd)

## Labor:

	<b>Description</b> Labor			Total Labor		Amount \$365.33 \$365.33
Parts Qty 1.00 2.00 1.00	Vendor Part Number CAS 87298694 CAS 442832A1 CAS 87298693	Description CHOPPER BLADE DOUBLE W/HWD SET OF BLADE CHOPPER BLADE DOUBLE W/HWD	<b>Bin</b> F-20 LT4 LT4	Total Parts	Price \$10.25 \$54.25 \$27.50	Ext. Price \$10.25 \$108.50 \$27.50 \$146.25
MAIN	0007550 014 00051 0 77			Tax Total WO	•	\$0.00 \$511.58

WO#: 2367556 SV SPREADER

#### Comments:

-Installed new pulley on horizontal shaft.

Description

Labor

-Reinstalled belt and set spring adjustment.

(rd)

## Labor:

				To	otal Labor		\$65.45
Parts Qty 1.00		Part Number 418093A1	<b>Description</b> PULLEY, STRAW SPRD DRIVE 8 IN	Bin		<b>Price</b> \$101.00	Ext. Price \$101.00
1.00 4.00 1.00	CAS CAS IMP	87613281 ZB8 57108	WASHER, 0.344X0.688X0.089 HTS GRD 8 HARDWARE PER OZ LOCKNUT 5/16-18	6-A C1-13		\$4.45 \$0.36 \$0.11	\$4.45 \$1.44 \$0.11
				To	otal Parts		\$107.00
					Tax		\$0.00
					Total WO		\$172.45

**Amount** 

\$65.45

WO#: 2367557 SV STEERING

#### Comments:

- -Removed tie-rod from steering arm.
- -Unbolted steering arm and bolted new arm on.
- -Reinstalled tie-rod.

(rd)

## Labor:

<b>Description</b> Labor		Total Labor		Amount \$119.00 \$119.00
Parts: Qty Vendor Part Number 1.00 CAS 412305A1	<b>Description</b> ARM, STEERING RH	Bin	<b>Price</b> \$460.00	Ext. Price \$460.00
		Total Parts		\$460.00
		Tax		\$0.00
		Total WO		\$579.00

## WO#: 2367559 SV ROTARY SCREEN

#### Comments:

- -Removed rubber gasket from around screen. (rd)
- -Took light out on cab to replace bulb.
- -Found bad connection in bulb.
- -Cleaned up and reinstalled.

(rd)

#### Labor:

	Description Labor				Amount \$104.72
			Total Labor		\$104.72
Parts Qty 1.00 1.00	Vendor Part Number  CAS 87429394  CAS 86976658	<b>Description</b> SEAL, ROTARY AIR SCREEN CLAMP, ROTARY AIR SCREEN	<b>Bin</b> LT1F	<b>Price</b> \$76.50 \$114.00	Ext. Price \$76.50 \$114.00
1100	3/10 33073333	SEAM (NOTALL ANGOREEN	Total Parts	ψ114.00	\$190.50
			Tax		\$0.00
1274			Total WO	·	\$295.22

# WO#: 2367561 SV TOP SIEVE

#### Comments:

- -Helped pull out top sieve, consider other repairs on sieve. (jl)
- -Removed top sieve.
- -Inspected rails in combine.

(rd)

- -Removed sensors & rubber flap from old sieve & installed on new sieve. (rd)
- -Took bottom sieve out because it wouldn't adjust.
- -Straightened adjusting arm.
- -Lubed sieve up and worked back and forth and freed up.
- -Reinstalled in combine.
- -Installed new top sieve in combine.
- -Attached rubber flap & sensors to back.
- -Reinstalled rubber flap on back of combine, and axle cover. (rd)

# <u>Labor:</u>

	<b>Description</b> Labor				Amount \$857.99
			Total Labor		\$857.99
<u>Parts</u> Qty	: Vendor Part Number	Description	Di-	D-t	pos pos. 1
1.00	CAS 1957315C8	SIEVE, CHAFFER, 1-5/8 CORN	Bin	<b>Price</b> \$1,275.00	Ext. Price \$1,275.00
			Total Parts		\$1,275.00
			Tax		\$0.00
			Total WO		\$2,132.99

Serial Number: YCS022139

Build Date: 04/May/2012

×	Technical Type	550100457 - 6R 30 3206 CORN HEAD
×	Variante	425191006 - 425191-Pinching knife rolls
×	Variante	725830106 - 725830-English for North America
×	Variante	425195006 - 425195-Base Unit- Pickup Head
X	Variante	711434006 - 711434-Tall crop/corn attachment pkg

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1360616 CL

Closed Date: 12/30/2021

Ship To:

34699

TITAN MACHINERY

Sold To:

1360616 CL

Invoice #: Sold by:

**BRAD MASIN** 

**Cust PO:** 

Cust Fleet#:

Job Desc: UPTIME INSPECTION Make:

CASE IH

Model: Serial #: 3206 YC5022139

Tag: Meter: 6836117

**Service Order Summary** 

**WO**#

2367572 SV 2367578 SV **UPTIME INSPECTION** 

REPAIRS AFTER INSPECTION

\$249.00

\$2,092.49

**TOTAL INVOICE** \$2,341.49 **Payment Information** \$2341.49 CNH PROMO 0301 \$1500 minimum with no payment, no interest for 90 days 7528 Trans ID: 01Z6JNSFS400P7ATCGCLJQ60R6CIQHNU Client ID: 3218739003 Store ID: 1420115001

Customer Signature

Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement

applicable to this Account.

Phone: 308-728-5220

Cell Phone:

Regular purchase APR applies after the end of the promotional period. See Account Agreement for details.

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price.

A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control.

-- CUSTOMER COPY --

#### WO#: 2367572 SV UPTIME INSPECTION

#### Comments:

Performed annual uptime inspection. Talk with customer over phone to describe repairs needed on corn head.

## Labor:

Description Uptime Inspection

Amount \$249.00

**Total Labor** 

\$249.00

## Parts:

Qty Vendor Part Number

Description

Price

Ext. Price

**Total Parts** 

Bin

Tax

**Total WO** 

\$249.00

#### WO#: 2367578 SV REPAIRS AFTER INSPECTION

#### Comments:

Hook cornhead to combine bring in removed and replaced all gathering chain idlers readjust chains, remove one set of knife roller because loose square couplers. Reinstalled knife roll with new square couplers, filled gearboxs with cornhead grease.

#### Labor:

<b>Description</b> Labor		Amount \$1,576.75
Shop Supplies		\$118.26
	Total Labor	\$1,695.01

# Parts:

Qty	 Vendor	Part Number	Description	Bin	Price	Ext. Price
12.00	CAS	B95573	KIT	LT4	\$27.25	\$327.00
4.00	IMP	57114	LOCKNUT 1/2-13	C1-13	\$0.24	\$0.96
2.00	CAS	176301C2	COUPLING/A	24-A	\$28.75	\$57.50
12.00	CAS	ZB8	GRD 8 HARDWARE PER OZ	6-A	\$0.36	\$4.32
2.00	CAS	73344909	CORNHEAD GREASE	F-11	\$3.85	\$7.70
				Total Parts		\$397.48
				Tax		\$0.00
						•
				Total WO		\$2,092.49

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1469345 CL

Closed Date: 12/1/2022

Ship To:

34699

TITAN MACHINERY

Invoice #:

Sold To:

1469345 CL

Make:

CASE IH

Sold by:

CHRIS KLUTHE

Model:

3206

**Cust PO:** 

Serial #:

YC5022139

Cust Fleet#: Job Desc:

UPTIME INSPECTION (BM)

Tag: Meter: **Service Order Summary**  6836117

WO#

2593981 SV

UPTIME INSPECTION

\$249.00

\$5,885.28

2599798 SV **ROW UNIT REPAIR** 

**TOTAL INVOICE** \$6,134.28 **Payment Information** \$6134.28 CNH PROMO 0301 \$1500 minimum with no payment, no interest for 90 days 7528 Trans ID: 01Z6KJIFH500P7F9KFKLE38KTU6E3RIO Client ID: 3218739003 Store ID: 1420115001 Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264 By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement Customer Signature applicable to this Account. Phone: 308-728-5220 Regular purchase APR applies after the end of the promotional period. See Account Agreement Cell Phone: for details.

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control. A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

WO#: 2593981 SV UPTIME INSPECTION

Comments:

Inspect cornhead

Labor:

**Description**Uptime Inspection

Amount

\$249.00

**Total Labor** 

\$249.00

Parts:

**Qty Vendor Part Number** 

Description

Bin

Price

Ext. Price

**Total Parts** 

Tax

**Total WO** 

**Total WO** 

\$249.00

\$5,885.28

WO#: 2599798 SV ROW UNIT REPAIR

#### Comments:

Dissasemble guides gathring chains and sprockets, clean up and reassemble with new parts. Installed seals in top of gear box on row 5 left side and row 6 left side Finished installing guide sprockets and chains on row units

Filled gearboxs with cornhead grease

Removed stripper plates from row 1 and 2 and cleaned debris out from underneath and finished installing row 6 with

#### Labor:

		escription					Amount \$2,196.28
		bor op Supplies					\$164.72
	31	ioh anhhiias			Takal Lahan		\$2,361.00
					Total Labor		φ2,501.00
Parts	•						
Qty		Part Number	Description	Bin		Price	Ext. Price
2.00	CAS	634036	OIL SEAL	C3-8		\$14.50	\$29.00
2.00	CAS	73344909	CORNHEAD GREASE	F-11		\$4.95	\$9.90
11.00	CAS	86611369	BRACKET			\$65.50	\$720.50
12.00	CAS	87029139	BRACKET,IDLE	LT1D		\$61.00	\$732.00
12.00	CAS	86978515	CHAIN, GATHERING, CHROME PIN	LT4		\$68.50	\$822.00
12.00	CAS	87593351	IDLER GUIDE SPACER			\$19.50	\$234.00
12.00	CAS	B95574A	KIT, 2200 DRIVE SPROCKET	LT4		\$71.99	\$863.88
1.00	CAS	84549635	SPROCKET, IDLER	24-A		\$28.25	\$28.25
2.00	CAS	280540	PLOW BOLT			\$4.70	\$9.40
2.00	!MP	57118	LOCKNUT 5/8-11	C1-13		\$0.68	\$1.36
1.00	CAS	73344349	GREASE	F-11		\$4.95	\$4.95
6.00	CAS	ZB10.9	10.9 METRIC HARDWARE	7-B		\$0.59	\$3.54
1.00	CAS	86611369	BRACKET			\$65.50	\$65.50
					<b>Total Parts</b>		\$3,524.28
					Tax		\$0.00

Serial Number: JJC0329050-

67

Build Date: 13/May/2002

X

Technical Type

551102004

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1229412 CL

Closed Date: 1/5/2021

CASE IH

1020

Ship To:

34699

**TITAN MACHINERY** 

Sold To

Invoice #:

1229412 CL

CHRIS KLUTHE

Sold by: CHI

Cust Fleet#: Job Desc:

**UPTIME INSPECTION** 

Make:

Model:

Serial #: Tag:

al #: JJC0329067 : 7002036

Meter:

**Service Order Summary** 

WO#

2096282 SV

**UPTIME INSPECTION** 

2114145 SV REPAIRS

\$253.56 \$3,411.54

	TOTAL INVOICE	\$3,665.10
	CREDIT CARD	\$3665,10
Customer Signature  Phone: 308-728-5220 Cell Phone:	Client ID: 3218739003 Store ID: 1420115001  Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-626.  By signing I certify that I am authorized to use this Account, to sign this receipt, and that the total amount of this invoice is repayable in accordance with the Account Agreed applicable to this Account.	it i agree

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control.

A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

WO#: 2096282 SV UPTIME INSPECTION

#### Comments:

Performed uptime inspection.

#### Labor:

Description Amount Uptime Inspection \$249.00

**Total Labor** 

\$249,00

#### Parts:

Qtv Vendor Part Number Description Bin Price Ext. Price 1.00 CAS 132096A1 GREASE 251H EP TUBE \$4.56 \$4.56 **Total Parts** \$4,56

> Tax **Total WO**

\$253.56

WO#: 2114145 SV REPAIRS

#### Comments:

Blocked up the reel, took off the hydraulic line that runs to the extending cylinger and the hydraulic line to the lift cylinder. Pulled off the drive chain replaced the idler pulley, pulled out the sickle and took bad knives off, got parts & hoses made. Replaced the drive chain on the right side, replaced the idler sprocket. Changed a lot of rivets on the plastic skids, changed the hydraulic lines. Grinded out the crack underneath on the bottom right side and welded up the crack. Put on the other idler pulley, rebuild the lift cylinder with a new seal kit. Mounted the cylinder. Finished up the head, put bolt in the pan that was missing, welded up the end where it was wore so the end guard would turn, put the sickle in. Hooked up, adjusted the sickle hold downs, they were a little loose, hooked up the belt, checked gear lube in the gear box, hooked up head and ran things, blew off the head. Rinsed off flex head, lubed up the sickle and chain and unhooked the head on the trailer.

#### Labor:

<b>Description</b> Labor		Amount \$2,827.55
Shop Supplies		\$174.85
	Total Labor	\$3,002.40

Parts:

Qty	Vendor	Part Number	Description	Bin	Price	Ext. Price
1.00	CAS	87047337	SEAL KİT		\$59.00	\$59.00
6.00	CAS	191256A1	CUT SECT	F-19	\$2.40	\$14.40
1.00	CAS	1307299C2	GUARD, KNIFE 3 CARBONITRIDED	F-24	\$19.00	\$19.00
1.00	CAS	1338269C1	GUARD STUB SINGLE	F-24	\$20.00	\$20.00
1.00	CAS	86627870	SPROCKET	LT1C	\$26.75	\$26.75
1.00	CAS	1338456C1	PULLEY	14-B	\$53.00	\$53.00
1.00	CAS	86996213	PULLEY, BELT CLEANING DRIVE	LT1C	\$43.00	\$43.00
1.00	CAS	241-1316	LINK	17-A	\$2.45	\$2.45
2.00	CAS	241-1716	LINK	17-A	\$4.95	\$9.90
66.00	CAS	611362R91IN	60 CHAIN PER INCH	17-A	\$0.72	\$47.52
7.00	DAY	4MIT	1/4' HOSE	SHOP	\$3.15	\$22.05
4.00	DAY	4G-6FJX	FEMALE JIC	SHOP	\$9.90	\$39.60
20.00	CAS	87013355	PKG-RIVET	C3-2	\$0.95	\$19.00
1.00	CAS	86507777	KIT	F-22	\$23.00	\$23.00
1.00	CAS	86617760	SECT OS14 RHE	F-21	\$6.90	\$6.90
2.00	IMP	44110	FLANGE NUT 3/8-16 SERR	C4-4	\$0.10	\$0.20

6.00	CAS	ZB5	GRD 5 HARDWARE PER OZ	F-8	\$0.17	\$1,02
1.00	CAS	87034815	LINK CONN.	17-A	\$1.75	\$1.75
2.00	TTM	TTM477-82512	1/4 - 20 X 3/4IN SERRATED SLOT	C4-4	\$0.24	\$0.48
2.00	IMP	44106	FLANGE NUT 1/4-20 SERR	C4-4	\$0.06	\$0.12
				Total Parts		\$409,14
				Tax		\$0.00
				Total WO		\$3,411.54

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1098876 CL

Closed Date: 1/28/2020

Ship To:

34699

TITAN MACHINERY

Invoice #:

Sold To:

1098876 CL

Make:

CASE IH

Sold by:

CHRIS KLUTHE

Model:

1020 JJC0329067

Cust PO:

Serial #: Tag:

7002036

Cust Fleet#: Job Desc:

**UPTIME** 

Meter:

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

**Service Order Summary** 

WO #

1833725 SV

UPTIME INSPECTION

\$249.00

1862497 SV WORK AFTER INSPECTION \$921.43

	TOTAL INVOICE	\$1,170.43		
	Payment Information  CREDIT CARD	\$1170.43		
, , , , , , , , , , , , , , , , , , ,	Trans ID: 01Z6HU14N900P769OTH7GB41D551DSD0  Client ID: 3218739003 Store ID: 1420115001			
Customer Signature	Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264			
Phone: 308-728-5220 Cell Phone:	By signing I certify that I am authorized to use this Account, to sign this receipt, and that I a that the total amount of this invoice is repayable in accordance with the Account Agreemen applicable to this Account.			

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control.

A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

## WO#: 1833725 SV UPTIME INSPECTION

#### Comments:

Performed annual inspection.

## Labor:

Description Amount Uptime inspection \$249.00 \$249.00

**Total Labor** 

Parts:

**Qty Vendor Part Number** Description Bin **Price** Ext. Price

**Total Parts** 

**Total WO** 

\$921.43

Tax **Total WO** \$249.00

WO#: 1862497 SV WORK AFTER INSPECTION

#### Comments:

Replaced idler sprocket on right side, adjusted chain. Pulled out the sickle, replaced sickle knives & end knives. Replaced end guards & couple main guards that were bent. Put sickle knife unit back in. Greased the head, ran & put on trailer.

## Labor:

<b>Description</b> Labor		<b>Amount</b> \$657.90
Shop Supplies		\$49.34
	Total Labor	\$707.24

#### Parts:

Qty	Vendor	Part Number	Description	Bin	Price	Ext. Price
5.00	CAS	191256A1	CUT SECT	F-19	\$2.35	\$11.75
1.00	CAS	86617760	SECT OS14 RHE	F-21	\$6.85	\$6.85
2.00	CAS	1338269C1	GUARD STUB SINGLE	F-24	\$20.00	\$40.00
2.00	CAS	1307299C2	GUARD, KNIFE 3" CARBONITRIDED	F-24	<b>\$18.75</b>	\$37.50
16.00	CAS	ZB7	GRD 5 CRG BOLT PER OZ	7-A	\$0.45	\$7.20
6.00	IMP	44112	FLANGE NUT 7/16-14 SERR	C4-4	\$0.21	\$1.26
1.00	CAS	323713	FITTING, LUBE	C2-9	\$3.50	\$3.50
1.00	CAS	B85141	85W140 GEAR OIL 1QT		\$6.63	\$6.63
1.00	CAS	84355310	U-JOINT		\$73.00	\$73.00
1.00	CAS	86627870	SPROCKET	LT1C	\$26,50	\$26.50
				Total P	arts	\$214.19
					Tax	\$0.00

Serial Number: YLS091173

Build Date: 22/Jun/2020

**************************************	Technical Type	581284829 - FRONT FOLD 12-2PT PLANTER
×	Variante	P55A03EB - 449407-Meter, electric drive
×	Variante	P55A05EC - 449414-Hydraulic Direct Drive w/alt
×	Variante	P55A13EC - 789008-Row markers
×	Variante	P55A30EB-SHIPPING STANDS
×	Variante	P55A04EC - 449149-Bulk Fill - no scales
×	Variante	P55A06EF ~ 449139-HD carrier w/HF wheel
×	Variante	P55A29EC - 422539-AFS Pro 700 Display
***************************************	Variante	P55A08EB - 449142-Row unit links standard
×	Variante	P55A17EF - 449436-Float NT residue mgr w/In-Cab
×	Variante	P55A07EB - 449161-Standard row unit
×	Variante	P55A09EB - 449418-Standard seed tube and sensor
×	Variante	P55A02EB - 449117-AFS Control
<b>X</b>	Variante	P55A10EC - 449144-Standard RID gauge wheels
X	Variante	P55A21EB - 449282-AFS North American English
×	Variante	P55A01-BASE UNIT
	Annual Company of the	

×	Variante	P55A18EC - 760028-Deluxe Air Compressor	
×	Variante	P55A12ED - 449444-Hyd down pressure automatic	арабория мандаль в формация об обще в общено в общено общ
X	Variante	P55A27EB - 725783-Additional Work Lights	мы оборожения в под
×	Variante	P55A11EC - 449428-2 Stage Closing In-Cab Ctrl	
X	Variante	P55A22EB - 449439-Hydraulic Wing Downforce	остишителься вышен в советствення в советствення в советствення в советствення в советствення в советствення в

Phone: 308-728-3234 800-658-3272 Phone: Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1511233 CL

Closed Date: 4/17/2023

Ship To:

34699

**TITAN MACHINERY** 

Sold To:

1511233 CL

Sold by:

SCOTT PARKER

Cust PO:

Invoice #:

Cust Fleet#:

Job Desc:

**UPTIME SERVICE** 

Make:

Model:

Serial #: Tag:

YLS091173 2811413

2150

CASE IH

Acres:

**Service Order Summary** 

**WO#** 

2694970 SV 2695767 SV UPTIME SERVICE REPAIRS

2702027 SV

**UPTIME INSPECTION** 

\$142.93 \$3,418.12

\$249.00

**TOTAL INVOICE** 

\$3,810.05

**Payment Information** 

\$3810.05

no interest for 90 days 7528

Trans ID: 01Z6KURT3H00P7H9F3CO8332NIQQIPPY

Client ID: 3218739003 Store ID: 1420115001

Customer Signature

Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement

applicable to this Account.

Phone:

Cell Phone:

308-728-5220

Regular purchase APR applies after the end of the promotional period. See Account Agreement

for details.

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price. I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control. A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full. Sold To:

**SERVICE ORDER:** 

WO#: 2694970 SV UPTIME SERVICE

Comments:

Issue: Uptime Service.

Correction: Greased planter

Went over planter with larry and grabbed parts

closing ticket

Labor:

**Amount** Description \$123.75 Labor \$9.28 Shop Supplies \$133.03

**Total Labor** 

Parts:

Ext. Price Price Description Bin Qty Vendor Part Number \$4.95 \$9.90 GREASE F-11 2.00 CAS 73344349

\$9.90 **Total Parts** 

Tax **Total WO** 

\$142.93

WO#: 2695767 SV REPAIRS

Comments: Issue: Repairs.

Correction: Pulled off gauge wheels for # 3 row unit.

Took off scrapers, and opener disc.

Installed new opener disc. Shimming looked good.

Torqued nuts.

Reinstalled scrapers, gauge wheels.

Will need to zero once i get the tractor back and hooked on.

I went along and tightened up all the row cleaner mounting bolts.

Changed the air compressor oil.

Blew out the filters and put back together.

Put seed meters back on.

Hooked tractor up to the planter.

Checked for zeroing on the opener disc.

Ran planter.

Pulled outside and ran, checked on functioning. #1 seed meter is not reading so I am testing wires

Put planter back together and pulled outside. Talked with larry

Labor:

**Amount** Description \$3,097.05 Labor \$165.57 **Shop Supplies** 

**Total Labor** 

\$3,262.62

Parts:

Price Ext. Price Bin Description Vendor Part Number Qty

2.00 CAS 51691765 DISK LTE5 \$77.75 \$155.50 **Total Parts** \$155.50 \$0.00 Tax \$3,418.12 **Total WO** WO#: 2702027 SV UPTIME INSPECTION Comments: Labor: Description Uptime Inspection Amount \$249.00 \$249.00 **Total Labor** Parts: Description **Qty Vendor Part Number** Bin Price Ext. Price **Total Parts** Tax \$0.00 **Total WO** \$249.00

Phone: 308-728-3234 Phone: 800-658-3272 Fax: 719-400-1001



See us for all of your Parts and service solutions

SERVICE ORDER: 1376793 CL

Closed Date: 2/24/2022

Ship To:

34699

TITAN MACHINERY

Sold To:

Invoice #:

1376793 CL

Sold by: **Cust PO:**  **CHRIS KLUTHE** 

Cust Fleet#: Job Desc:

**UPTIME INSPECTION** 

Make:

Model:

Serial #: Taq:

YLS091173 2811413

CASE IH

2150

Acres:

Service Order Summary

WO# 2406732 SV UPTIME INSPECTION \$252.95

TOTAL	INVOICE

\$252.95

CREDIT CARD

\$252,95

Client ID: 3218739003 Store ID: 1420115001

Customer Signature

Remit to: CNH Industrial Retail Accounts, PO Box 71264, Philadelphia, PA 19176-6264

Phone: 308-728-5220 Cell Phone:

By signing I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Account Agreement

applicable to this Account.

I hereby authorize the repair work to be done as described above on the machine(s) named hereon. All repair parts are to be billed at your regular price, I agreed to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full any unpaid balance shall constitute a lien on this machinery.

I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft, or other causes beyond your control. A service charge will be assessed equal to the lesser of 1.5% per month or the maximum rate permitted by law on all delinquent accounts, until paid in full.

## WO#: 2406732 SV UPTIME INSPECTION

#### Comments:

Inspect planter for wear, test planter operations, check wiring and hydraulic hoses, check for wear points, lube planter.

# Labor:

<b>Description</b> Uptime inspection		<b>Amount</b> \$249.00
	Total Labor	\$249.00

Parts:

<b>Qty</b>	 Part Number	<b>Description</b>	<b>Bin</b>	<b>Price</b>	Ext. Price
1.00	73344349	GREASE	F-11	\$3.95	\$3.95
			Total Parts		\$3.95

Tax . Total WO \$252.95