

Payment terms are 30 days from invoice date unless otherwise agreed upon in writing. Remit to:
Cummins Sales and Service
PO Box 772639
Detroit, MI 48277-2639

KEARNEY NE BRANCH 515 CENTRAL AVE PO BOX 1326 KEARNEY, NE 68848-(308)234-1994

REPRINT


INVOICE NO

J7-18220

TO PAY ONLINE LOGON TO customerpayment.cummins.com

BILL TO

STEVE BUNGER



OWNER

STEVE BUNGER



PAGE 1 OF 2

*** CCARD ***

| DATE | CUSTOMER ORDER NO. | DATE IN SERVICE | ENGINE MODEL | PUMP NO. | EQUIPM | ENT MAKE |
|----------------------------------|---|---|----------------------------------|-----------|--|---------------------------------|
| 09-DEC-2019 | 78 | 24-FEB-2005 | ISX CM870 | | KE | WORTH |
| CUSTOMER NO. | SHIP VIA | FAIL DATE | ENGINE SERIAL NO. | CPL NO. | EQUIPM | ENT MODEL |
| 1214215 | | 05-DEC-2019 | 79083096 | | | T660 |
| REF. NO. | SALESPERSON | PARTS DISP. | MILEAGE/HOURS | PUMP CODE | UN | IT NO. |
| 40661 | NQ532 | | 563481 / 0 | | | 881 |
| QUANTITY BACK ORDERED ORDERED | QUANTITY PART SHIPPED NUMBER | DESCRIPTION | PRODUCT CODE | | UNIT PRICE | AMOUNT |
| OSN/MSN/VIN | 1XKAD49X45J088881 | | | | | |
| COMPLAINT CORRECTION | TRUCK IS NOT GETTING ABOVE 1700 RPMS IN SOME OF THE UPPER GEARS. CUSTOMER WOULD ALSO LIKE US TO CHECK OVER THE TRUCK. CHECK OVER ENGINE, FOUND THE COOLANT FILTER WAS LEAKING AND THE POWER STEERING FILTER WAS LEAKING. HOOKUP WITH INSITE TO CHECK ECM PARAMETERS. FOUND THE LOAD BSE WHEEL SPEED WAS SET AT 1600 RPM, AND THE VEHICLE SPEED SOURCE IS SET AT 1600 RPM. ADJUST THE LOAD BASE SPEED TO THE MAX SETTING OF 1800 RPM, AND DISABLED THE GEAR DOWN PROTECTION. SET THE MAX VEHICLE SPEED SOURCE 2000 RPM. CHECK FOR AIR IN FUEL AND INLET RESTICTION, NO AIR FOUND AND RESTRICTION IS ONLY AT 2 INCHES ON THE GUAGE (OK). DRAIN POWER STEERING RESERVOIR AND REMOVE THE TOP PART AND FILTER CLEAN THE SEAL SURFACE AND TOP PART AND CLAMP REINSTALL TOP WITH NEW SEAL AND FILTER. REPLACE THE OIL FILL SEALS AND COOLANT FILTER. REFILL COOLANT TOOK 4 GALLONS TO TOPP OFF. MOVE TRUCK OUT SIDE AND TOOK FOR ROAD TEST. THE ENGINE CAN NOW GET UP TO 1800 RPM. CHECKED FOR LEAKS, NONE FOUND AT THIS TIME. | | | | | |
| | | I TALKED TO STEVE AND STEVE ID REPAIRING THE WATER FILTI LEAK \$992 | | | | |
| | 2 3936876 | SEAL.RECTANGULAR RING | CECO | | The state of the s | |
| 2 | 2 0000070 | SEAL, HEOTANGOLATTING | OLOO | | 4.12 | 8.24 |
| 1 | 1 3903475 | SEAL, RECTANGULAR RING | CECO | | 4.12 4.60 | 8.24 4.60 |
| | | | | | | |
| 1 | 1 3903475 | SEAL, RECTANGULAR RING | CECO | | 4.60 | 4.60 |
| 1 4 | 1 3903475 4 CC2825 | SEAL, RECTANGULAR RING ES COMP EG | CECO FLG | | 4.60 15.30 | 4.60 61.20 |
| 1 4 1 | 1 3903475 4 CC2825 1 WF2127 | SEAL,RECTANGULAR RING ES COMP EG PAC, WF | CECO FLG FLG | | 4.60 15.30 45.59 | 4.60 61.20 45.59 |
| 1 4 1 | 1 3903475 4 CC2825 1 WF2127 2 75-200 | SEAL,RECTANGULAR RING ES COMP EG PAC, WF ATF | CECO FLG FLG C1-NSPART1 | | 4.60 15.30 45.59 10.36 | 4.60 61.20 45.59 20.72 |

Billing Inquiries? Call (877)480-6970

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

| AUTHORIZED | BY | (print | name) |
|-------------------|----|--------|-------|
| | | | |



KEARNEY NE BRANCH 515 CENTRAL AVE PO BOX 1326 KEARNEY, NE 68848-(308)234-1994

REPRINT

Payment terms are 30 days from invoice date unless otherwise agreed upon in writing. Remit to:
Cummins Sales and Service PO Box 772639 Detroit, MI 48277-2639

INVOICE NO

J7-18220

TO PAY ONLINE LOGON TO customerpayment.cummins.com

BILL TO

STEVE BUNGER

AUTHORIZED BY (print name)



OWNER

STEVE BUNGER



PAGE 2 OF 2

*** CCARD ***

| DATE | CUSTOM | ER ORDER NO. | DATE IN SERVICE | ENGINE MODEL | PUMP NO. | EQUIPM | IENT MAKE |
|----------------------------------|---------------------|----------------|-------------------|---------------------|-----------------|------------|-----------|
| 09-DEC-2019 | | | 24-FEB-2005 | ISX CM870 | | KE | NWORTH |
| CUSTOMER NO. SHIP VIA | | FAIL DATE | ENGINE SERIAL NO. | CPL NO. | EQUIPMENT MODEL | | |
| 1214215 | | | 05-DEC-2019 | 79083096 | | | T660 |
| REF. NO. | SALE | SPERSON | PARTS DISP. | MILEAGE/HOURS | PUMP CODE | UI | NIT NO. |
| 40661 | N | Q532 | | 563481 / 0 | | | 881 |
| QUANTITY BACK ORDERED ORDERED | QUANTITY SHIPPED | PART NUMBER | DESCRIPTION | PRODUCT CODE | | UNIT PRICE | AMOUNT |
| OSN/MSN/VIN | 1XKAD | 49X45J088881 | | | | | |
| TAX EXEMPT NUMBERS | | PAR | TS: | | | 298.57 | |
| | | | PAR | TS COVERAGE CREDIT: | | | 0.00 CF |
| | | | TOT | AL PARTS: | | 298.57 | |
| | | | SUR | CHARGE TOTAL: | | | 0.00 |
| | | | LAB | OR: | | | 565.80 |
| | | | LAB | OR COVERAGE CREDIT: | | | 0.00 CF |
| | | | TOT | AL LABOR: | | 565.80 | |
| | | | MISC | O.: | | | 123.55 |
| | | | MISC | C. COVERAGE CREDIT: | | | 0.00 CF |
| | | TOT | AL MISC.: | | 123.55 | | |
| | | | ELE | CTRONIC TOOLING FEE | | | 50.00 |
| | | | HAZ | WASTE DISPOSAL | | | 28.29 |
| | | | SHO | P SUPPLIES | | | 45.26 |
| | | | | | LOCAL | | 0.00 |

| Billing Inquiries? Call (877)480-6970 | The state of the s | The state of the s | |
|--|--|--|--------|
| THERE ARE ADDITIONAL CONTRACT TERMS ON TI DOCUMENT, INCLUDING LIMITATION ON WARRANT | TIES AND REMEDIES, WHICH ARE | SUB TOTAL: | 987.92 |
| EXPRESSLY INCORPORATED HEREIN AND WHICH BEEN READ AND FULLY UNDERSTOOD. | PURCHASER ACKNOWLEDGES HAVE | TOTAL TAX: | 0.00 |
| | | TOTAL AMOUNT: US \$ | 987.92 |
| AUTHORIZED BY (print name) | SIGNATURE | DATE | |