

**BISH'S RV - KEARNEY**

115 East 1st Street  
Kearney, NE 68847  
308.455.8200

# Repair Order Invoice

Doc Number: 66111  
Service Writer: Nate Stephens  
Date Printed: 06/02/2025  
Date Promised: 05/31/2025  
Date In: 05/15/2025  
Cashier: Zach Harris  
Cashier Date: 06/02/2025

Lonzo Branich  
4024 Pont Express Rd  
Kearney, NE 68847

**Customer Information**

Cell Phone: 308.627.9023

Fold Here

## Summary

Approve	Decline	Unit	Job	Job Total
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	Inspection	\$276.61
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	DEWINTERIZE - WITH OUT ICE MAKER, DISHWASHER OR WASHING MACHINE	\$99.50
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	1. light	\$139.30
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	2. Light (Bedroom)	\$218.90
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	3. Bathroom fan	\$15.99
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	4. Bathroom ceiling	\$29.85
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	5. Kill switch	\$179.10
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	6. Tail lights	\$257.40
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	7. Mattress	\$500.00
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	powercord	\$19.99
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	water leak	\$447.64
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	Propane	\$341.19
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	Rear door	\$268.65
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2013 SHADOW	Brake line	\$199.00
Job Subtotal:				\$2,993.12
Misc:				\$248.45
Job Parts Subtotal:				\$608.12
Job Labor Subtotal:				\$2,385.00
Tax:				\$59.97
Total:				\$3,301.54
Less Deposits:				\$0.00
Visa/Mastercard:				(\$3,301.54)
Total Due:				\$0.00

Thank You For Your Business!

Signature: \_\_\_\_\_

# Detail

Unit

2013 SHADOW

VIN/Serial No:1S9GS3523DW873434

Color:

Plate:

Keyboard:

Odom/Hrs In:0

Out:0

## Inspection

Description:One hour labor, check out everything to make sure all is operational.

Labor		Hours	Total
Description	Technician	1.39	\$276.61
APPLIANCE QUICK CHECK INSPECTION -	Keegan Cumpston		
		Labor Subtotal	\$276.61
		Job Subtotal	\$276.61
		Approve: <input checked="" type="checkbox"/>	Decline: <input type="checkbox"/>

## DEWINTERIZE - WITH OUT ICE MAKER, DISHWASHER OR WASHING MACHINE

Description:

Labor		Hours	Total
Description	Technician	0.5	\$99.50
DEWIN - FLUSH ALL LINES AND CHECK FOR LEAKS	Keegan Cumpston		
		Labor Subtotal	\$99.50
		Job Subtotal	\$99.50
		Approve: <input checked="" type="checkbox"/>	Decline: <input type="checkbox"/>

## 1. light

Description:Light over door when coming in needs mounted

Resolution:Correction  
KC - 5/21/2025, 11:18:09 AM - Used existing hardware and installed light back to the ceiling panel

Done

Labor		Hours	Total
Description	Technician	0.7	\$139.30
CEILING LIGHT INSTALL -	Keegan Cumpston		
		Labor Subtotal	\$139.30
		Job Subtotal	\$139.30
		Approve: <input checked="" type="checkbox"/>	Decline: <input type="checkbox"/>

## 2. Light (Bedroom)

Description:Light on right side of bedroom hanging. can it be remounted or does it need replaced?

Resolution:Correction  
KC - 5/21/2025, 11:21:12 AM - I can remount it, but there's bar wires showing so I have to disassemble the light splice the wire back together and then reinstall the thread into the light receptacle and find a couple of nuts to put on the bolt

Done

Labor		Hours	Total
Description	Technician	0.9	\$179.10
CEILING LIGHT DIAGNOSE -	Keegan Cumpston		
WIRE HARNESS SECURE EXTERIOR WIRING	Keegan Cumpston	0.2	\$39.80
		Labor Subtotal	\$218.90
		Job Subtotal	\$218.90
		Approve: <input checked="" type="checkbox"/>	Decline: <input type="checkbox"/>

## 3. Bathroom fan

Description:Fan in not properly mounted. Needs mounted

Resolution:Correction



Resolution: KC - 5/21/2025, 1:29:20 PM - Reattach the batten strips across secured to the ceiling

Done

Parts					
Part #	Qty	Description	Price	Discount	Total
5" SS TRIM SCREW	1.00	5" SS TRIM SCREW	\$15.99	\$0.00	\$15.99
Parts Subtotal					\$15.99
Job Subtotal					\$15.99
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

#### 4. Bathroom ceiling

Description: CS ceiling is sagging, needs secured.

Resolution: Reattach the batten strips across secured to the ceiling

Labor					
Description	Technician	Hours			Total
CEILING BATTEN R&R - 8 FT	Keegan Cumpston	0.15			\$29.85
Labor Subtotal					\$29.85
Job Subtotal					\$29.85
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

#### 5. Kill switch

Description: Kill switch on inside, when turned on, a fan comes on. Why is this fan running?

Resolution: Correction  
KC - 5/21/2025, 1:33:07 PM - The fan that comes on is your converter charging the batteries once you turn the disconnect on it's gonna try charging your batteries and the fan is to cool the converter from becoming overheated. No fault found

Done

Labor					
Description	Technician	Hours			Total
ELECTRICAL SYSTEM TEST/DIAGNOSE -	Keegan Cumpston	0.9			\$179.10
Labor Subtotal					\$179.10
Job Subtotal					\$179.10
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

#### 6. Tail lights

Description: CS rear tail lights not working

Resolution: Correction  
KC - 5/21/2025, 1:35:21 PM - I didn't find any fault with the tail lights however, there is five yellow marker lights that are not working

Parts					
Part #	Qty	Description	Price	Discount	Total
71-7138	2.00	MC32AS MARKER LIGHT AMBER, WHT BASE	\$4.99	\$0.00	\$9.98
AMBER LIGHTS	2.00	CLEAR/AMBER LIGHTS	\$24.21	\$0.00	\$48.42
Parts Subtotal					\$58.40
Labor					
Description	Technician	Hours			Total
MARKER LIGHT R&R (EACH) -	Keegan Cumpston	1			\$199.00
Labor Subtotal					\$199.00
Job Subtotal					\$257.40
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

#### 7. Mattress

Description: Customer wants a firm mattress. Need options of what is available. Wants a hard mattress. King size.

Resolution: Correction  
KC - 5/21/2025, 2:40:21 PM - King size firm mattress 500 installed

Parts			Price	Discount	Total
Part #	Qty	Description			
MATTRESS	1.00	60"X75"	\$354.18	\$0.00	\$354.18
Parts Subtotal					\$354.18
Labor			Hours		Total
Description		Technician			
		Keegan Cumpston	0.79		\$145.82
Labor Subtotal					\$145.82
Job Subtotal					\$500.00
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

### powercord

**Description:**customer picked up power adapter. Took with him.

Parts			Price	Discount	Total
Part #	Qty	Description			
19-1744	1.00	A10-3015HVP 30AM-15AF DOGBONE	\$19.99	\$0.00	\$19.99
Parts Subtotal					\$19.99
Job Subtotal					\$19.99
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

### water leak

**Description:**water leak

**Resolution:**Sediment straining dish on the water pump was replaced. It was cracked. Also had to replace the toilet valve. It was leaking and the P-trap in the shower was cracked and leaking as well.

Parts			Price	Discount	Total
Part #	Qty	Description			
10-0698	1.00	255-313 SHURFLO 1/2" MPS-1/2" SWIVEL STRAINER	\$21.99	\$0.00	\$21.99
69-4460	1.00	385311641 Dometic 301/310/300 Water Valve	\$72.99	\$0.00	\$72.99
Parts Subtotal					\$94.98
Labor			Hours		Total
Description		Technician			
WATER FILTER CANISTER INSTALL -		Keegan Cumpston	0.4		\$91.60
SHOWER DRAIN BASKET R&R -		Keegan Cumpston	0.45		\$103.05
TOILET WATER VALVE R&R -		Keegan Cumpston	0.69		\$158.01
Labor Subtotal					\$352.66
Job Subtotal					\$447.64
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

### Propane

**Description:**LP pigtails were leaking. Customer stated he wanted new ones.

**Resolution:**Installed two new pigtails and did a leak test

Parts			Price	Discount	Total
Part #	Qty	Description			
06-0383	2.00	24" RV TYPE 1 PIGTAIL-PKG	\$32.29	\$0.00	\$64.58
Parts Subtotal					\$64.58
Labor			Hours		Total
Description		Technician			
LP LEAK TEST INSPECTION -		Keegan Cumpston	0.59		\$117.41
LP HIGH PRESSURE HOSE/PIGTAIL R&R -		Keegan Cumpston	0.8		\$159.20
Labor Subtotal					\$276.61
Job Subtotal					\$341.19
Approve: <input checked="" type="checkbox"/>					Decline: <input type="checkbox"/>

**Rear door****Description:**Carriage bolts**Resolution:**Where to pull out of the door from the hinge  
Headed to drill out all the rivets drill a hole through the door install carried bolts**Labor**

Description	Technician	Hours	Total
DOOR HINGES R&R -	Keegan Cumpston	1.35	\$268.65
<b>Labor Subtotal</b>			<b>\$268.65</b>
<b>Job Subtotal</b>			<b>\$268.65</b>
<b>Approve:</b> <input checked="" type="checkbox"/>			<b>Decline:</b> <input type="checkbox"/>

**Brake line****Description:**Brake line**Resolution:**Jack's trailer up and remove tire remove the hub unwind all the tire tread that was wrapped around the backing plate flange and inspect the wiring and make sure it was not damaged**Labor**

Description	Technician	Hours	Total
DRIVE HUB R&R -	Keegan Cumpston	1	\$199.00
<b>Labor Subtotal</b>			<b>\$199.00</b>
<b>Job Subtotal</b>			<b>\$199.00</b>
<b>Approve:</b> <input checked="" type="checkbox"/>			<b>Decline:</b> <input type="checkbox"/>

<b>All Jobs Subtotal:</b>	<b>\$2,993.12</b>
<b>Shop Supplies:</b>	<b>\$248.45</b>
<b>Tax:</b>	<b>\$59.97</b>
<b>Total:</b>	<b>\$3,301.54</b>
<b>Less Deposits:</b>	<b>\$0.00</b>
<b>Visa/Mastercard:</b>	<b>(\$3,301.54)</b>
<b>Total Due:</b>	<b>\$0.00</b>