



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | |
|---------------------------------------|--|---|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 | Invoice Number: 10772668 Invoice Date: 10/18/2019 Location: 06 Work Order Number: 314011 Payment Type: Account Page: 1 of 11 |
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | |
| Make/Model: | Meter: | Serial Number: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 |
| | | Eq ID: DK800435 |
| | | Fleet No: |

/S670AINSP Internal

COMPLAINT:

01 WINTER SERVICE INSPECTION PROGRAM ON COMBINES

CORRECTION:

- ☒ CHECK OPERATION OF DISPLAYS AND MONITORING SYSTEMS.
- ☒ RECALL AND CHECK STORED CODES.
- ☒ CHECK THAT SOFTWARE IS CURRENT FOR ALL CONTROLLERS. OPEN JOB CODE /HSOFT TO UPDATE SOFTWARE IF NEEDED.
- ☒ INSPECT BELTS AND CHAINS.
- ☒ CHECK WEAR LEVELS ON AUGERS AND CONCAVES.
- ☒ CHECK OPERATION OF FEEDING, SEPARATOR AND UNLOADING SYSTEMS.
- ☒ INSPECT BEARINGS AND SPROCKETS.
- ☒ CHECK OPERATION OF ALL ELECTRICAL AND HYDRAULIC SYSTEMS.
- ☒ CHECK OPERATION OF ALL SAFETY FEATURES.
- ☒ PREPARE AN ESTIMATE FOR CUSTOMER REVIEW.

OL&M Charges:

| <u>Description</u> | | | | | <u>Value</u> |
|--------------------|---------------|---------------|--------------|------------|--------------|
| fuel | | | | | \$97.91 |
| Labor: \$700.00 | Parts: \$0.00 | OL&M: \$97.91 | Misc: \$0.00 | Sub-Total: | \$797.91 |

/HSOFT Internal

CORRECTION:

| | | | | | |
|-----------------|---------------|--------------|--------------|------------|----------|
| Labor: \$100.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: | \$100.00 |
|-----------------|---------------|--------------|--------------|------------|----------|

/S670G000002 Internal

COMPLAINT:

03 SHORTEN AUGER TO 22.5' FROM 28'

CORRECTION:

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | | |
|---------------------------------------|---------------------------------------|------------------------|-----------------|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) | Invoice Number: | 10772668 |
| | COYOTE CANYON FARMS, INC. | Invoice Date: | 10/18/2019 |
| | DAN KOTSCHWAR | Location: | 06 |
| | 40374 ROAD 745 | Work Order Number: | 314011 |
| | FARNAM NE 69029 | Payment Type: | Account |
| Bus Phone: | Bus Phone: | Page: | 2 of 11 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|----------------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 | DK800435 | |

/S670G000002 Internal

MACHINE HAD 28' AUGER SETUP ON IT.
 CUSTOMER WANTED 22.5'
 SWING AUGER OUT.
 USE SKYJACK TO REMOVE BOOT.
 REMOVE GRAIN SAVER.
 REMOVE LIGHT AND HARNESS FROM TUBE.
 REMOVE OUTER 2 AUGERS.
 REMOVED TUBE.
 INSTALL SHORT TUBE.
 INSTALL SHORT AUGERS.
 INSTALL GRAIN SAVER.
 INSTALL BOOT.
 INSTALL LIGHT AND HARNESS.
 RIVET EACH HARNESS HOLDER ON TUBE.
 RAN MACHINE AND MADE SURE THE UNLOADING SYSTEM WAS GOING TO WORK.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|----------------------|----------|------------|-----------|----------------|-----------|
| 03M7185 | BOLT CARR 25 | 21.00 | 1.35 | 0.35 | \$7.35 | N |
| 14M7296 | FLANGE NUT 10 | 4.00 | 1.08 | 1.08 | \$4.32 | N |
| 14M7298 | FLANGE NUT 8M | 6.00 | 0.78 | 0.78 | \$4.68 | N |
| 14M7299 | FLANGE NUT 12 | 15.00 | 1.46 | 1.46 | \$21.90 | N |
| 19M7814 | BOLT 50 | 15.00 | 2.33 | 2.33 | \$34.95 | N |
| 19M7835 | BOLT 35M | 4.00 | 0.37 | 0.37 | \$1.48 | N |
| 19M7866 | M8 X 20 FLANGE BOLT | 1.00 | 0.92 | 0.92 | \$0.92 | N |
| 24H1300 | Washer | 10.00 | 3.81 | 3.81 | \$38.10 | N |
| 24M7178 | WASHER | 11.00 | 1.02 | 1.02 | \$11.22 | N |
| 57M11936 | MOUNT | 13.00 | 0.67 | 0.67 | \$8.71 | N |
| AH203021 | UNLOADING AUGER | 1.00 | 1,408.94 | 1,268.05 | \$1,268.05 | N |
| AH209150 | Bearing With Housing | 1.00 | 161.54 | 161.54 | \$161.54 | N |
| AT44188 | Rivet | 16.00 | 0.67 | 0.67 | \$10.72 | N |
| AXE68706 | Housing | 1.00 | 3,045.75 | 3,045.75 | \$3,045.75 | N |

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | | |
|---------------------------------------|---------------------------------------|------------------------|-----------------|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) | Invoice Number: | 10772668 |
| | COYOTE CANYON FARMS, INC. | Invoice Date: | 10/18/2019 |
| | DAN KOTSCHWAR | Location: | 06 |
| | 40374 ROAD 745 | Work Order Number: | 314011 |
| | FARNAM NE 69029 | Payment Type: | Account |
| Bus Phone: | Bus Phone: | Page: | 3 of 11 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|----------------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 | DK800435 | |

/S670G000002 Internal

| | | | | | | |
|-----------|--------------|-------|--------|--------|----------|---|
| HXE125955 | Door | 1.00 | 133.75 | 133.75 | \$133.75 | N |
| HXE59141 | WEATHERSTRIP | 1.00 | 18.43 | 18.43 | \$18.43 | N |
| M84309 | PUSH-ON NUT | 25.00 | 1.05 | 1.05 | \$26.25 | N |
| R44302 | TIE BAND | 13.00 | 0.12 | 0.12 | \$1.56 | N |

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|-------------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| PT3750 | FREIGHT JD - PARTS GOTH | 1.00 | 50.00 | 50.00 | \$50.00 | N |

Labor: \$904.44 Parts: \$4,799.68 OL&M: \$0.00 Misc: \$50.00 Sub-Total: \$5,754.12

/S670G1139001 Internal

COMPLAINT:

04 WHEEL SPACING 30"

CORRECTION:

USED THIS SEGMENT TO SLIDE THE REAR AXLES IN TO 30" ROWS.
 JACKED UP COMBINE.
 REMOVED BOLTS ON THE AXLE.
 REMOVED BOLTS ON TIEROD.
 USED THE TIEROD TO PULL THE AXLES IN.
 TIGHTENED ALL BOLTS TO SPEC.

Labor: \$324.35 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$324.35

/HCSERVQ -F-0014323 Internal

COMPLAINT:

05 SERVICE COMBINE FLUIDS AND FILTERS

CORRECTION:

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | | |
|---------------------------------------|---------------------------------------|------------------------|-----------------|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) | Invoice Number: | 10772668 |
| | COYOTE CANYON FARMS, INC. | Invoice Date: | 10/18/2019 |
| | DAN KOTSCHWAR | Location: | 06 |
| | 40374 ROAD 745 | Work Order Number: | 314011 |
| | FARNAM NE 69029 | Payment Type: | Account |
| Bus Phone: | Bus Phone: | Page: | 4 of 11 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|----------------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 | DK800435 | |

/HCSERVQ -F-0014323 Internal

COMPLETE ANNUAL MAINTENANCE PROGRAM

INCLUDES FOLLOWING SERVICE;

Replace all filters.

Drain;

Engine oil.

Reverser gearcase.

Primary countershaft gearcase.

Refill to specifications.

John Deere recommended tire pressures.

Insure that.

All fluid levels are at specified levels.

Safety systems are functional.

Remove and clean cab air pre-cleaner.

Grease all lube points on the combine.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| AH128449 | HYD FILTER | 2.00 | 53.60 | 53.60 | \$107.20 | N |
| AN207368 | HYDRO PUMP FILTER | 1.00 | 80.36 | 80.36 | \$80.36 | N |
| AT129775 | FILTER | 1.00 | 82.13 | 82.13 | \$82.13 | N |
| AXE42065 | Air Filter | 1.00 | 51.85 | 51.85 | \$51.85 | N |
| AXE42066 | Air Filter Debris | 1.00 | 95.55 | 95.55 | \$95.55 | N |
| HXE11090 | AIR FILTER | 1.00 | 169.75 | 169.75 | \$169.75 | N |
| HXE11091 | Air Filter | 1.00 | 134.24 | 134.24 | \$134.24 | N |
| L214634 | RECIRC FILTER | 1.00 | 19.67 | 19.67 | \$19.67 | N |
| RE284091 | CAB FILTER | 1.00 | 56.93 | 56.93 | \$56.93 | N |
| RE509672 | OIL FILTER | 1.00 | 19.48 | 19.48 | \$19.48 | N |
| RE533910 | FUEL FILTER | 1.00 | 113.88 | 113.88 | \$113.88 | N |
| RE539279 | OIL FILTER | 1.00 | 19.49 | 19.49 | \$19.49 | N |
| RE539465 | Fuel Filter | 1.00 | 94.43 | 94.43 | \$94.43 | N |
| SWDEF330X | BULK DEF GALLON | 13.00 | 1.67 | 1.67 | \$21.71 | N |

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | | |
|---------------------------------------|---------------------------------------|------------------------|-----------------|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) | Invoice Number: | 10772668 |
| | COYOTE CANYON FARMS, INC. | Invoice Date: | 10/18/2019 |
| | DAN KOTSCHWAR | Location: | 06 |
| | 40374 ROAD 745 | Work Order Number: | 314011 |
| | FARNAM NE 69029 | Payment Type: | Account |
| Bus Phone: | Bus Phone: | Page: | 5 of 11 |
| Prv Phone: | Prv Phone: | | |

| | | | | |
|----------------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 | DK800435 | |

/HCSERVQ -F-0014323 Internal

| | | | | | | |
|---------|----------------------------|------|-------|-------|----------|---|
| TY26101 | BRAKE & PARTS CLEANER | 1.00 | 4.92 | 4.43 | \$4.43 | N |
| TY26408 | SYNTHETIC HD460 OIL | 4.00 | 22.45 | 20.20 | \$80.80 | N |
| TY26673 | Plus-50 II Oil 15W40 GAL | 1.00 | 20.26 | 20.26 | \$20.26 | N |
| TY26675 | Plus-50 II Oil 15W40 2-1/2 | 3.00 | 49.98 | 49.98 | \$149.94 | N |

| <u>Miscellaneous</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|----------------------|---------------------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| PT3751 | FREIGHT SHORTLINES - PARTS GOTH | 1.00 | 100.00 | 100.00 | \$100.00 | N |

Labor: \$548.90 Parts: \$1,322.10 OL&M: \$0.00 Misc: \$100.00 Sub-Total: \$1,971.00

/S670G1138845 Internal

COMPLAINT:

06 FEEDER HOUSE REAR SEAL PLATE, R&R

CORRECTION:

UNLATCH REAR SUPPORT

REMOVE PLATE.

POUND THE HINGE SHAFT OUT AND REPLACE THE HINGE.

INSTALL PLATE BACK ON COMBINE AND ADJUST LATCH SO THAT IT WOULD CLOSE.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
| AXE60025 | Hinge | 1.00 | 257.64 | 257.64 | \$257.64 | N |

Labor: \$311.88 Parts: \$257.64 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$569.52

EXPERT-1000000023452 Internal

COMPLAINT:

07 REAR AXLE right rear needs paint buffed off and repainted

CORRECTION:

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | | | | |
|--|--|--|--|------------------------|--|
| Internal Used Stock No. 176285 (Sold) | | Internal Used Stock No. 176285 (Sold) | | Invoice Number: | |
|--|--|--|--|------------------------|--|

EXPERT-1000000023452 Internal

JACK UP THE REAR OF THE COMBINE
 INSTALL JACK STANDS
 REMOVED RIM AND BUFF OFF OLD PAINT
 PRIME AND REPAINT

PULLED THE COMBINE OVER TO THE WASH BAY AND WASHED THE RIM OUT AND SCRUBBED IT.
 WAS ABLE TO GET THE RUST COLOR TO GO AWAY.

| | | | | |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|
| Labor: \$187.13 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$187.13 |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|

/S670G1138848 Internal

COMPLAINT:
 08 CONVEYOR DRIVE CHAIN, R&R

CORRECTION:
 REMOVED SHIELDS
 REMOVE AND REPLACE DRIVE CHAIN
 ADJUST CHAIN AND ASSEMBLE IN REVERSE ORDER

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|-------------|-----------------|----------|------------|-----------|----------------|-----------|
| AXE72710 | Feeder Dr Chain | 1.00 | 141.03 | 141.03 | \$141.03 | N |

| | | | | |
|------------------------|------------------------|-------------------------|---------------------|----------------------------|
| Labor: \$324.35 | Parts: \$141.03 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$465.38 |
|------------------------|------------------------|-------------------------|---------------------|----------------------------|

/S670G000001 Internal

COMPLAINT:
 09 PERFORM PARKED REGEN IN SHOP - ADDITIONAL TIME REQUIRED IF COMPLETED IN THE FIELD

CORRECTION:
 MACHINE KEPT SAYING IT NEEDED TO COOL DOWN FOR TEN MINUTES AFTER EVERY SHUT DOWN.
 CONNECTED SERVICE ADVISOR AND CHECK FOR HOW MANY INCOMPLETE REGENS WERE IN THE COMPUTER.
 FOUND THAT IT HAD FAILED TO REGEN 12 TIMES PROBABLY DUE TO THE CUSTOMER SHUTTING THE MACHINE DOWN.
 STARTED A PARKED REGEN AND LET THE COMBINE DO ITS THING.

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | |
|---------------------------------------|--|---|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 | Invoice Number: 10772668 Invoice Date: 10/18/2019 Location: 06 Work Order Number: 314011 Payment Type: Account Page: 7 of 11 |
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | |
| Make/Model: | Meter: | Serial Number: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 |
| | | Eq ID: DK800435 |
| | | Fleet No: |

/S670G000001 Internal

| | | | | |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|
| Labor: \$187.13 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$187.13 |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|

/S670G1138967 Internal

COMPLAINT:

10 HYDRAULIC AND ELECTRICAL COMPONENTS - BXE10211DUAL SPEED STRAW SPREADER

CORRECTION:

CUSTOMER WANTED LANKOTA SPREADER PLATES INSTALL ON THE TAIL BOARD.

RAISE CHOPPER

REMOVE SPREADERS.

INSTALL NEW SPREADERS.

LOWER CHOPPER AND RUN MACHINE.

MACHINE RAN FINE.

| Part Number | Description | Quantity | List Price | Net Price | Extended Price | Taxed Ind |
|------------------------|---------------------------------|-------------------------|---------------------|------------------------------|----------------|-----------|
| LANTBHX12K | COMPLETE ASSY TAILBOARD SPINNER | 1.00 | 2,114.29 | 2,114.29 | \$2,114.29 | N |
| Labor: \$374.25 | Parts: \$2,114.29 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$2,488.54 | | |

/S670G1138856 Internal

COMPLAINT:

11 A/C COMPRESSOR, RECEIVER-DRYER, R&R- WATER COMING IN THE CAB FROM ROOF- REMOVE ROOF AND CHECK DRAIN HOSE

CORRECTION:

WHILE RUNNING THE MACHINE IT WAS NOTICED THAT WATER WAS COMING FROM THE HEAD LINER RUNNING DOWN THE WINDSHIELD.

FIGURED THE DRAIN HOSE FROM THE ROOF HAD CAME UNHOOKED.

REMOVED ROOF AND CHECKED ALL OF THE DRAIN HOSES.

REMOVED PLASTIC CORNER COVER INSIDE THE CAB AND FOUND THE DRAIN HOSE THAT RUNS BEHIND THE CORNER

POST HAD BECAME DISCONNECTED.

RECONNECTED IT AND RAN A/C. NO MORE WATER IN THE CAB.

INSTALLED ROOF BACK ON COMBINE.

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
 Gothenburg, NE 69138
 Phone: 308-537-2532
 Fax: 308-537-4282
 www.landmarkimp.com
 Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | | | | |
|--|--|--|-------------------|------------------------------|-----------|
| Internal Used Stock No. 176285 (Sold) | | Internal Used Stock No. 176285 (Sold) | | Invoice Number: 10772668 | |
| | | COYOTE CANYON FARMS, INC. | | Invoice Date: 10/18/2019 | |
| | | DAN KOTSCHWAR | | Location: 06 | |
| | | 40374 ROAD 745 | | Work Order Number: 314011 | |
| | | FARNAM NE 69029 | | Payment Type: Account | |
| Bus Phone: | | Bus Phone: | | Page: 8 of 11 | |
| Prv Phone: | | Prv Phone: | | | |
| Make/Model: | | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE JD S770 COMBINE | | 551 | 1H0S770SCJ0800435 | DK800435 | |

/S670G1138856 Internal

| | | | | |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|
| Labor: \$467.81 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$467.81 |
|------------------------|----------------------|-------------------------|---------------------|----------------------------|

/S670G000013 Internal

COMPLAINT:

12 REPLACE COUPLER ON MULTI-COUPLER - PRICING PER COUPLER

CORRECTION:

COUPLER ON SINGLE POINT BEGAN LEAKING WHEN HOOKED TO CUSTOMERS PLATFORM.
 REMOVE OLD COUPLER USING SPECIAL TOOL.
 INSTALLED THE NEW COUPLER.
 RAN MACHINE AND CHECKED FOR LEAKS.

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|------------------------|--------------------|------------------------|-------------------|----------------------------|-----------------------|---------------------|
| AXE49949 | VALVE | 1.00 | 181.30 | 181.30 | \$181.30 | N |
| H201368 | MULTICOUPLER COVER | 1.00 | 34.60 | 34.60 | \$34.60 | N |
| H202240 | SEAL | 2.00 | 1.55 | 1.55 | \$3.10 | N |
| Labor: \$124.75 | | Parts: \$219.00 | | OL&M: \$0.00 | | Misc: \$0.00 |
| | | | | Sub-Total: \$343.75 | | |

/S670G1138758 Internal

COMPLAINT:

13 GO AROUND MACHINE WITH THE CUSTOMER AND SHOW HIM HOW TO ADJUST THINGS AND RUN THINGS

CORRECTION:

CUSTOMER SHOWED UP WHILE WORKING ON HEAD.
 ASKED ME TO SHOW HIM THE CONTROLS IN THE CAB.
 RAN THE MACHINE WITH THE CUSTOMER TO HELP FAMILIARIZE HIM WITH THE CONTROLS.
 TALKED ABOUT SETUP AND HOW TO ADJUST THE PERFORMANCE OF THE MACHINE.
 ALSO USED THIS SEGMENT TO CALIBRATE THE PLATFORM ON THE COMBINE.

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | |
|---------------------------------------|--|---|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 | Invoice Number: 10772668 Invoice Date: 10/18/2019 Location: 06 Work Order Number: 314011 Payment Type: Account Page: 9 of 11 |
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | |
| Make/Model: | Meter: | Serial Number: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 |
| | | Eq ID: DK800435 |
| | | Fleet No: |

/S670G1138758 Internal

| | | | | |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$249.50 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$249.50 |
|-----------------|---------------|--------------|--------------|---------------------|

/S670G000030 Internal

COMPLAINT:

14 REPLACE LOWER CLEAN GRAIN ELEVATOR DOOR- CLOSE TRAPS ON BOTH SIDES SINCE ROBERT DIDNT AFTER WASHING

CORRECTION:

USED THIS SEGMENT TO CLOSE THE TRAPS ON THE VERTICAL AUGER HOUSING AND THE CROSS AUGER COVERS.

| | | | | |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$124.75 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$124.75 |
|-----------------|---------------|--------------|--------------|---------------------|

/S670G1138826 Internal

COMPLAINT:

15 DRIVE TO CUSTOMERS TO MAKE SURE IT HAS CORN CONCAVES IN IT. ALSO HAD TO RUN THE COMBINE WITH THE CUSTOMER

CORRECTION:

LOADED A&I CONCAVES INTO THE PICKUP.

DROVE TO CUSTOMER. 56 MILES RT

REMOVED COVER FOUND THAT THE COMBINE DID IN FACT HAVE ROUND BAR CONCAVES IN IT.

CUSTOMER THEN ASKED ME TO RIDE IN THE COMBINE WITH HIM TO SHOW HIM A FEW THINGS AND TRY TO GET HIS TANK SAMPLE LOOKING BETTER.

MADE A FEW ROUNDS WITH THE CUSTOMER AND WAS ABLE TO SHOW HIM A FEW THINGS AND WAS ABLE TO GET HIS TANK SAMPLE LOOKING BETTER.

CUSTOMER WAS HAPPY.

DROVE HOME

UNLOADED CONCAVES.

| | | | | |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$436.63 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$436.63 |
|-----------------|---------------|--------------|--------------|---------------------|

CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | |
|---------------------------------------|--|--|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 | Invoice Number: 10772668 Invoice Date: 10/18/2019 Location: 06 Work Order Number: 314011 Payment Type: Account Page: 10 of 11 |
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | |
| Make/Model: | Meter: | Serial Number: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 |
| | | Eq ID: DK800435 |
| | | Fleet No: |

/S670G000026 Internal

COMPLAINT:

16 INSTALL A&I CAMERA SYSTEM.

CORRECTION:

INSTALL CAMERA ON REAR OF MACHINE PER SHANE.

USED SKYJACK.

MOUNTED BRACKET.

UNHOOKED THE PLUG FROM THE WIRE AND PLUGGED IT INTO THE CAMERA.

CHECKED OPERATION OF CAMERA.

T673- RILEY KORT

| <u>Part Number</u> | <u>Description</u> | <u>Quantity</u> | <u>List Price</u> | <u>Net Price</u> | <u>Extended Price</u> | <u>Taxed Ind</u> |
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|
|--------------------|--------------------|-----------------|-------------------|------------------|-----------------------|------------------|



CONTINUED ON NEXT PAGE->



Landmark Implement Inc.

221 Lake Avenue
Gothenburg, NE 69138
Phone: 308-537-2532
Fax: 308-537-4282
www.landmarkimp.com
Gothenburg@landmarkimp.com



JOHN DEERE

Invoice To Account No:

Deliver To:

SERVICE INVOICE

| | | |
|---------------------------------------|--|--|
| Internal Used Stock No. 176285 (Sold) | Internal Used Stock No. 176285 (Sold) COYOTE CANYON FARMS, INC. DAN KOTSCHWAR 40374 ROAD 745 FARNAM NE 69029 | Invoice Number: 10772668 Invoice Date: 10/18/2019 Location: 06 Work Order Number: 314011 Payment Type: Account Page: 11 of 11 |
| Bus Phone: Prv Phone: | Bus Phone: Prv Phone: | |

| | | | | |
|----------------------------|--------|-------------------|----------|-----------|
| Make/Model: | Meter: | Serial Number: | Eq ID: | Fleet No: |
| JOHN DEERE JD S770 COMBINE | 551 | 1H0S770SCJ0800435 | DK800435 | |

| | | | | | | |
|-----------------------------------|------------------------|-------------------------|---------------------|-------------------|-----------------|---|
| /S670G000026 Internal A-MC110S | S Camera | 1.00 | 135.71 | 135.71 | \$135.71 | N |
| Labor: \$187.13 | Parts: \$135.71 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: | \$322.84 | |

INVOICE CONTAINS \$171.38 DISCOUNT

Customer PO No:
Tax Exempt No:
Advisor: AMBER METZLER

*** DOCUMENT COPY ***

Labor: \$5,553.00
Parts: \$8,989.45
OL&M: \$97.91
Misc: \$150.00
Sales Tax: \$0.00
Grand Total: \$14,790.36



TERMS AND CONDITIONS

Approved charges are due by the 10th of the month following purchase. I agree to pay a monthly periodic FINANCE CHARGE at the rate of 1.33% which is an ANNUAL PERCENTAGE CHARGE OF 16% on the unpaid balance. The purchaser agrees to pay reasonable attorney fees if collection efforts are required.

Received by:Date: