DATE	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
August 9 Tach-16 TTAF-3 Complice in accord C/W 11 C/W AI C/W AI Perform Installed Installed Change ELT litt All AD	60.8 744.9 ed with an ANN dance with Ces -10-09 Amende 080-08-14 Ame 076-07-12 Ame ded an ELT insp d new ELT mod d a CR-2 ,3 vol ELT 05-09-20 hium battery re	sna service i ed 06-17-201 ended 04-22- ended 08-30- pection in ac del E-04.Rep t battery mus 30 placement P	1 Seat Track I 1980 Foam I'i 1977 Ignition cordance with blace Duracell at be replaced of N-E-04.0	N8719B Cessna- 172 S/N-36419 ance with FAR part 43 appendix (D) under the scope and detail of items for this AIRFRAME and - (2).

930,904

PATE	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries mu	tion of Inspections, Tests ust be endorsed with Name, Ra see back pages for other specific	ating and Certificate Number of Technician or Repair
Augus Tach- TTAF Comp PROF Comp Clean Clean Did an Chang I certi	ELLER and in ression test are ed inspected ar ed, and checke n oil change pu	accordance as fallows ad gapped a d propeller t (7) quarts	#1-72/80, #3-72 Il spark plugs. blades in good of Phillips XC	ervice manual 2/80, #5-76/80 condition 20 W 50 in en	under section (2).), #2-74/80, #4-72/80, #6-74/80. Igine changed oil filter installed	McCauley DES.1A170 S/N-61595 TTP-3744.9 Repitch-493.9 r the scope and detail of items for this ENGINE and new Tempest oil filter P/N-48108-2 ANNUAL inspection and was determined to be in

lating the temperature.	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
DATE				Facility. (See back pages for other specific entries.)
Tach- TTAF Comp in acc C/W C/W C/W Instal Perfo ELT All A Refill Filled L cert	AD80-09 Amend AD80-08-14 And AD76-07-12 And led a new ELT I rmed an ELT in battery replacent D are current the led (L) and (R) I	ded 06-17-20 nended 04-2 nended 08-3 pattery P/N- spection in a nent due in / trough 2024- brakes with	e manual section of 1 Seat Track 2-1980 Foam Football of 2025 Mil-H-5606.	

TACH FLIGHT TIME IN Entries must be endorsed with				Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Resility. (See back pages for other specific entries.)	ed with Name, Rating and Certificate Number of Technician or Repair		
DATE				acility. (See back pages for other specific entries.)			
Tach-16 TTAF-3	3743.2 ed with an AN	NUAL insp	N8719B Cessna-172 S/N-36419 ection in accord	Continental-O-300-A McCauley DES.1A170 S/N-13235-D-7-A S/N-61595 TTE-3743.2 TTP-3743.2 TSMOH-141.47 Repitch-492.2 ordance with FAR part 43 appendix (D) under the scope and detail of items for this ENGINE a	ınd		
Cleaned Cleaned I certify airworth	that this ENC	s fallows # l gapped all s	-74/80, #3-78/3 spark plugs.	ervice manual under section (2) 8/80, #5-76/80, #2-78/80, 44-76/80, #6-76/80.			
Cleaned Cleaned I certify airworth	ession test are and inspected and it, and checked to that this ENC	s fallows # l gapped all s	-74/80, #3-78/3 spark plugs.	ervice manual under section (2) 8/80, #5-76/80, #2-78/80, #4-76/80 #6-76/80.			
Cleaned Cleaned I certify airworth	that this ENC	s fallows # l gapped all s	-74/80, #3-78/3 spark plugs.	ervice manual under section (2) 8/80, #5-76/80, #2-78/80, #4-76/80 #6-76/80.			
Cleaned Cleaned I certify airworth	that this ENC	s fallows # l gapped all s	-74/80, #3-78/3 spark plugs.	ervice manual under section (2) 8/80, #5-76/80, #2-78/80, #4-76/80 #6-76/80.			

YEAR	Tach 1657 4 Cessna- 172
DATE	TTAE 1-1-1-17 27 10 2 7 1 20 1 20 1 20 1 20 1 20 1
DATE	in accordance with Cessna service manual section (2).
-	C/W 11-10-09 Amended 06-17-2011 Seat Track Inspection.
-	C/W AD80-08-14 Amended 04-22-1980 Foam Filter Elements by installing a new air filter P/N-BA 6108-1. C/W AD76-07-12 Amended 08-30-1977 Ignition Switches and found no defects at this time.
	Installed a new ELT battery P/N-BP-1045
	Performed an ELT inspection in accordance with FAR part 91.207 appendix (D) sub paragraphs (1) through (4) with no defects noted. ELT battery replacement due in AUG of 2025
	All AD are current through 2023-07
	Installed a new battery RG-25
	Installed a new compass Airpath inner case compass C2350 L4V S/N PS-443
-	Installed altimeter (VFR) P/N-671BK Altimeter (VFR) (Outright) S/N-AF43-104083 W/O K166762 (2) MS33737-13C
	Made new hose for the transponder
	Installed (2) grommets on the post connections on the battery P/N-MS35489-20 Installed a new tab on top cowling
	Installed a new bulb for beacon on the belly P/N-FS-227 14V/28V
	Installed a new tail navigational light P/N-GE-305
	Reglued (R) step that came loose.
	Transponder, Encoder, Static System has been inspected.
	I certify that this AIRFRAME has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.
	Michael A Candy
	_ A&P2805335IA

diam'r.	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE		ting and Certificate Number of Technician or Repair
DATE				Facility. (See back pages for other specific	c entries.)
July 7,	2023		N8719B	Continental-O-300-A	McCauley DES.1A170
Tach-1657.4		Cessna-172	S/N-13235-D-7-A	S/N-61595	
TTAF-	27.2 / 7		S/N-36419	TTE-3719.67	TTP-3719.67
				TSMOH-139.72	Repitch-490.5
Cleane Cleane I certif	d inspected and d, and checked by that this EN the condition.	gapped all propeller b GINE and	spark plugs.		NNUAL inspection and was determined to be in
	603333IA				
	OUJJJJIA				
	003333IA				

YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Name, Ra Facility. (See back pages for other specific	ating and Certificate Number of Technician of Nepali
DATE	May 25, 201 Tach-1654.2	2		N8719B	Cessna- 172 S/N-36419
	C/W 11-10- C/W AD80 C/W AD76 Installed a r Performed ELT batter	dance with -09 Amende -08-14 Ame -07-12 Ame new ELT ba an ELT insp y replacement	Cessna service d 06-17-2011 S nded 04-22-19 nded 08-30-19 ttery P/N-BP-1 ection in accor nt due in AUG	Seat Track Inspection. 80 Foam Filter Elements by installing a new a 77 Ignition Switches and found no defects at to 045 dance with FAR part 91.207 appendix (D) sub of 2019.	D) under the scope and detail of items for this AIRFRAME air filter P/N-BA 6108-1. this time. b paragraphs (1) through (4) with no defects noted. inspection and was determined to be in airworthy condition.
	Michael A A&P2803	Candy 5335IA			

EAR:	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician Facility. (See back pages for other specific entries.)	or Repair
ATE			8830	racility. (See back pages for other specific entries.)	
	. 05 0017		MOTIOD	Continental-O-300-A McCauley DES.1A170	
	May 25, 2017		N8719B		
Tach-1654.2			Cessna-172 S/N-36419	TYPE AGIL AG	
1	TAF-3738.3		3/14-30419	TSMOH-136.52 Repitch-487.30	
		ANDILIAL	inspection in ac	cordance with FAR part 43 appendix (D) under the scope and detail of items for this El	NGINE and
_ ;	complied with a	d in pagerda	nespection in ac	a service manual under section (2).	
P	ROPELLER an	t are as fallo	we #1-78/80 #3.	3-79/80, #5-79/80, #2-78/80, #4-78/80, #6-78/80.	
	ompression tes	l are as lano	W2 #1-10/00 #2	1-17100, 113-17100, 112-10100, 111-10100, 110-10100	
C	Cleaned inspecte	d and gappe	d all spark plugs		
	Cleaned inspect	d and gappe	d all spark plugs and painted prop	s. Seller blades	ned to be in
C	Cleaned inspected Cleaned, inspect certify that this	ed and gappe ed, dressed a ENGINE a	d all spark plugs and painted prop		ned to be in
C	Cleaned inspect	ed and gappe ed, dressed a ENGINE a	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in
C I a	Cleaned inspected Cleaned, inspect certify that this irworthy condit	ed and gappe ed, dressed a ENGINE a ion.	d all spark plugs and painted prop	s. Seller blades	ned to be in

YEAR: RECOR	TODAY'S	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)		
Tach- TTAF Comp and i Amer Swite appe 2015 acco	ded 04-22-1980 hes and found no dix (D) sub para	Foam Filter El defects at this graphs (1) thro	n in accordance with FAR part 43 appendix (D) under the ce manual section (2). C/W 11-10-09 Amended 06-17-20 ements by installing a new air filter P/N-BA 6108-1.C/time. Installed a new ELT battery P/N-BP-1045 and Inspirate (4) with no defects noted. ELT battery replacement do not sump and tested for operation and found ok. I certion and was determined to be in airworthy condition.	Cessna- 172 S/N-36419 e scope and detail of items for this AIRFRAME 2011 Seat Track Inspection. C/W AD80-08-14 W AD76-07-12 Amended 08-30-1977 Ignition bected ELT in accordance with FAR part 91.207	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)			
DATE				Tacility. (See De	ack pages for other specific entires.)		
	April 4 20	115	N87	19R	Continental-O-300-A	McCauley DES.1A170	
25 20 00 2	April 4, 2015 Tach-1627.1		N8719B Cessna-172		S/N-13235-D-7-A	S/N-61595	
	TTAF-369		[전문] 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1 : 1	-36419	TTE-3669.37	TTP-3669.37	
distributed by	T 11Ar-309	1,2	5/11	30117	TSMOH-89.42	Repitch-440.12	
	with an A	A Carroy	pection and wa	s determined to be	in airworthy condition.	PROPELLER have been inspected in accordance	
			기가 하면 하는 것이 없는데 없는데 없다.				

ACT TO SERVICE A CONTRACTOR OF SERVICES SERVICES