

Sale Name: Aldinger Equipment & Shop Tools Auction

LOT 55 - International 605 Gas Power Unit



Description

Rockford clutch, Notes on tag: low compression, needs heads, cracked head rightside, the sight has a gas leak

Quantity: 1



<https://www.marshallbid.com/>